

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SH 7654A

DATE 3/1/2018 11:41

MAKE :

MODEL : HYUNDAI i40

| Qty | Parts Description/ Labour                                                                                                                                                                                                                                                                                                                                                                                                       | Type | Unit Price | Amount      |
|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------|-------------|
|     | Front Bumper Cover X                                                                                                                                                                                                                                                                                                                                                                                                            |      |            | \$ 562.30   |
|     | Front Bumper Bracket Top (LH) X                                                                                                                                                                                                                                                                                                                                                                                                 |      |            | \$ 22.40    |
|     | Front Bumper Retainer Mounting X                                                                                                                                                                                                                                                                                                                                                                                                |      |            | \$ 9.20     |
|     | Rear Pom (LH) x repair                                                                                                                                                                                                                                                                                                                                                                                                          |      |            |             |
|     | Sub Total                                                                                                                                                                                                                                                                                                                                                                                                                       |      |            | \$ 593.90   |
|     | Rear Pom Striker - 480 LESS 20%                                                                                                                                                                                                                                                                                                                                                                                                 |      |            | \$ 118.78   |
|     | Rear Fender (LH) x repair                                                                                                                                                                                                                                                                                                                                                                                                       |      |            |             |
|     | Discounted Total                                                                                                                                                                                                                                                                                                                                                                                                                |      |            | \$ 475.12   |
|     | Labour Charge                                                                                                                                                                                                                                                                                                                                                                                                                   |      |            | 100         |
|     | Panel Beating                                                                                                                                                                                                                                                                                                                                                                                                                   |      |            | \$ 350.00   |
|     | Spray Painting Charge                                                                                                                                                                                                                                                                                                                                                                                                           |      |            | \$ 400.00   |
|     | Tuff Kote                                                                                                                                                                                                                                                                                                                                                                                                                       |      |            | \$ 50.00    |
|     | TOTAL LABOUR                                                                                                                                                                                                                                                                                                                                                                                                                    |      |            | \$ 800.00   |
|     | ESTIMATE TOTAL                                                                                                                                                                                                                                                                                                                                                                                                                  |      |            | \$ 1,275.12 |
|     | (Kalam) (6/6/18)<br>4/1/18 1025hr<br>2 Pys.<br>C/S<br>After Repair pld                                                                                                                                                                                                                                                                                                                                                          |      |            |             |
|     | LKK Auto Consultants hence notify the Repairer of the following:<br>• To survey def. rearer spray painting<br>• To display damaged parts during resurvey<br>• Parts prices are subject to confirmation<br>• Third party surveys on a "Without Prejudice" basis<br>• No legal proceedings allowed<br>• Supplementary claims must be surveyed and is subject to final approval from insurance company<br>Acknowledged by Repairer |      |            |             |
|     | This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.                                                                                                                                                                                                                  |      |            |             |