

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**06 JAN 2018**

Estimate No. : b1 45412
Date Estimated : 06/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Kee Boo Chye (Ji Wucai)
5D Puay Hee Avenue

Singapore 347473

- ACCOUNT -

121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ8823J	C798951	30/04/2012	640iA/2	0

DESCRIPTION

To replace rear bumper and Remove and install bootlid and attachment include knocking cause by the accident

Painting rear bumper ,bootlid

To supply and rear emboss number plate.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

1275 2,550.00

1868 2,076.00

dd 83.00

150 177.00

? 80.00

Total Labour 1: **4,966.00**DESCRIPTION

RR BUMPER CARRIER
RR BUMPER ADAPTER
GUIDE CENTER REAR
GUIDE BOTTOM CENTER
MOUNT REAR LH
MOUNT REAR RH
RR BUMPER (PDC)
RR BUMPER TOW HOOK COVER (PRIMED)
BMW EMBLEM
MODEL LETTERING 640I

QTY	PRIC	VALUE
1	751.70	? 751.70
1	67.10	? 67.10
1	70.25	? 70.25
1	50.05	? 50.05
1	141.65	? 141.65
1	141.65	? 141.65
1	1,690.65	de 1,690.65
1	25.45	de 25.45
1	67.80	de 67.80
1	61.05	de 61.05

Total Parts : **3,067.35**

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45412
Date Estimated : 06/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ8823J	C798951	30/04/2012	640iA/2	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured Motorist / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 5/2/12 @ 1040 Excess S\$ _____

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY BY SURVEYOR (Yes / No) PML Yes / No

Surveyor's Signature Tan Jiah Tan Jiah

Recommend 4 days

Labour 1	:	4,966.00
Parts	:	3,067.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	562.33
Grand Total	:	8,595.68

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **