Vantage Automotive Limited

305 Alexandra Road S'pore 159942

200 . + 200 . +

400+

Date: 27.12.2017

440 0 x

RE: VEHICLE REPAIR QUOTATION

Insurance Company MSIG INSURA Vehicle Reg No **SJB7277T** Name of Insured SIME DARBY SERVICES

B 29040568 MCY

Policy Number Date of Accident Tyre of Claim

29.10.2017 OD CLAIM **AUDI A8**

Model

Chassis No WAUZZZ4H7FN007621

We are please to submit our estimate of repairs to the above mention vehicle.

	Parts	Labour
1 REAR LHS DOOR ASSY	\$ 2,230.00	
2 REAR LHS DOOR WEATHERSTRIP	\$ 105.00 ×	
3 REAR LHS DOOR LOWER SEAL	\$ 90.00 ×	
4 REAR LHS DOOR OUTER WEATHERSTRIP	\$ 195.00 ×	

Sub Total Parts = \$ 2,620.00 ADD 20% = \$ 524.00 Total Parts = \$ 3,144.00

1	REPLACE REAR LHS DOOR	\$ 500.00
2	RESPRAY REAR LHS DOOR	\$ 500.00 200
3	WIRING CONNECTION & CHECK	\$ 150.00
4	SUNDRIES	\$ 150.00
5	TRANSFER REAR LHS DOOR MECHANISM	\$ 350.00
6	TUFF KOTE @ \$60 PER PANEL	\$ 120.00 40
7	SEALANT FOR DOOR PANEL @ \$90 PER PANEL	\$ 180.00 ×
8	TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK	\$ 300.00 ×
	INCLUDING CLEAR FAULT CODE	. / \

Grand Total :	\$ 5,771.58
GST 7%	\$ 377.58
Sub Total :	\$ 5,394.00
Total (Labour)	\$ 2,250.00
INOLODINO GLEART AGET GODE	

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

KK Auto Consultants hence notify WONG GUO XIANG (64777409 / 83833190) epairer of the following:

· To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Reports

Reports