

Form

INS. CASE OWNER

Bemal.

CC 4/AIG1800

0413, Sub P.

LKK  
IDAC

Surveyor:

YWK / Kham.

DOI:

ASSIGNMENT

29/11/18

Date / Time:

8/1/18

Registered in Merimen:

8/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKH 2507E

Name of Insured:

WEEVA S/O GOPAL KRISHNAN

Insured Tel No.:

HP: 98770420

Excess Sec II :SS

D.O.A: 20/9/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

76768894866

Policy No.:

700479A1-07000

Make / Model:

WOLSWAGEN

Place of Accident:

SEAHADON AVE 2 UNISIDE  
EXITWAY - 20 LP CE 15

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hua  
Hong



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2870.05

Loss of Rental (LOR):

SS

days)

Loss of Use (LOU):

SS

3w.w (5w x 3 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only ☐ LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2w

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

2672.05

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2672.05

Name 1:

Hua Hung Private Limited

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18000413/yb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 08-01-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKH 8507E	Veh. Inspected	YP 6677C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	20/09/2017	Inspection Date	
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



# HUA HONG PRIVATE LIMITED

250 Sungei Kadut Street | Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## Estimate Repair List

12 January 2018

HHTPClaims18-03

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#09-16 AIG Building  
Singapore 079120

### ACCIDENT INVOLVING YP 6677 C & SKH 8507 E ON 20/09/2017 ALONG SERANGOON AVENUE 2 AT ABOUT 0745 HOURS

Insured : FLY BUILD PTE LTD  
Vehicle Registration No : YP 6677 C  
Vehicle Make : HINO  
Vehicle Model : XZU710R-HKFMS3  
Vehicle Chassis No : JHHUCS3H90K019587  
Policy No : VCA/P1969630  
Date of Accident : 20/9/2017

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper ✓ BT		\$ 600.00
2	2	Rear Bumper Bracket (LH/RH) ✓ BT	\$ 250.00	\$ 500.00
3	1	Rear Bumper Step ✓ BT		\$ 250.00
				<u>\$ 1,350.00</u>

To dismantle & change rear bumper, rear bumper step, knocking & pull straight rear chassis frame and all area affected by accident.

\$ 800.00  
500

To spray rear bumper, rear bumper LH/RH bracket, rear bumper step and rear chassis frame.

\$ 800.00 500

7% GST

\$ 2,950.00  
\$ 206.50

Total

\$ 3,156.50

3 days

#### LOK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.. 23/1/18.

- Part by part repair.

- Photo before Paint.

9003621

Sebastianyang@ltauto.com.

Authorised by Claims

Mrs Tan @ 9639 9195



## Hsiao Tong (LKKAUTO)

---

**From:** Ashley Tan <ashley@huahong.com.sg>  
**Sent:** Tuesday, 23 October 2018 10:38 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** Calvin Ang (LKKAUTO)  
**Subject:** RE: LOD documents for Vehicle No. YP6677C  
**Attachments:** RENTAL INVOICE.pdf; TAX INVOICE.pdf; TP Insurer Enquiry.pdf

Dear Hsiao Tong

Please refer to the revised LOD documents as attached.

Thanks & Regards

*Ashley Tan*



**HUA HONG PRIVATE LIMITED**  
25D SUNGEI KADUT STREET 1 SINGAPORE 729332  
T. 6661 9690 | M. 9816 4151 | F. 6661 9699  
Follow us @ huahong.com.sg  
   

---

**From:** Ashley Tan <ashley@huahong.com.sg>  
**Sent:** Friday, 19 October 2018 5:59 PM  
**To:** 'Calvin Ang (LKKAUTO)' <calvinang@lkkauto.com>  
**Subject:** Finalisation for Vehicle No. YP6677C

Hi Calvin

Please refer to photos attached for finalisation.

Thanks & Regards

*Ashley Tan*



**HUA HONG PRIVATE LIMITED**  
25D SUNGEI KADUT STREET 1 SINGAPORE 729332  
T. 6661 9690 | M. 9816 4151 | F. 6661 9699  
Follow us @ huahong.com.sg  
   

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Saturday, 27 October 2018 9:31 AM  
**To:** 'Ashley Tan'  
**Cc:** Calvin Ang (LKKAuto)  
**Subject:** RE: LOD documents for Vehicle No. YP6677C

Without Prejudice

Hi Ashley,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 2,370.05
2. Loss of Rental (3days x \$90.00)	\$ 270.00
3. LTA/GIA search fee	\$ 2.00
<b>Total</b>	<b><u>\$ 2,642.05</u></b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ashley Tan <[ashley@huahong.com.sg](mailto:ashley@huahong.com.sg)>  
**Sent:** Tuesday, 23 October 2018 10:38 AM  
**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** Calvin Ang (LKKAuto) <[kalvinang@lkkauto.com](mailto:kalvinang@lkkauto.com)>  
**Subject:** RE: LOD documents for Vehicle No. YP6677C

Dear Hsiao Tong

Please refer to the revised LOD documents as attached.

## Hsiao Tong (LKKAuto)

---

**From:** Ashley Tan <ashley@huahong.com.sg>  
**Sent:** Tuesday, 11 December 2018 12:46 PM  
**To:** Hsiao Tong (LKKAuto)  
**Subject:** RE: LOD documents for Vehicle No. YP6677C

Dear Hsiao Tong

As spoken yesterday, please advise the loss of rental.

Thanks & Regards

*Ashley Tan*



**HUA HONG PRIVATE LIMITED**  
25D SUNGEI KADUT STREET 1 SINGAPORE 729332  
T. 6661 9690 | M. 9816 4151 | F. 6661 9699  
Follow us @ huahong.com.sg



---

**From:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Sent:** Saturday, 27 October 2018 9:31 AM  
**To:** Ashley Tan <ashley@huahong.com.sg>  
**Cc:** Calvin Ang (LKKAuto) <kalvinang@lkkauto.com>  
**Subject:** RE: LOD documents for Vehicle No. YP6677C

Without Prejudice

Hi Ashley,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 2,370.05
2. Loss of Rental (3days x \$90.00)	\$ 270.00
3. LTA/GIA search fee	\$ 2.00
<b>Total</b>	<b>\$ 2,642.05</b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ashley Tan <[ashley@huahong.com.sg](mailto:ashley@huahong.com.sg)>  
**Sent:** Tuesday, 23 October 2018 10:38 AM  
**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** Calvin Ang (LKKAuto) <[kalvinang@lkkauto.com](mailto:kalvinang@lkkauto.com)>  
**Subject:** RE: LOD documents for Vehicle No. YP6677C

Dear Hsiao Tong

Please refer to the revised LOD documents as attached.

Thanks & Regards

*Ashley Tan*



**HUA HONG PRIVATE LIMITED**  
25D SUNGEI KADUT STREET 1 SINGAPORE 729332  
T. 6661 9690 | M. 9816 4151 | F. 6661 9699  
Follow us @ [huahong.com.sg](http://huahong.com.sg)



---

**From:** Ashley Tan <[ashley@huahong.com.sg](mailto:ashley@huahong.com.sg)>  
**Sent:** Friday, 19 October 2018 5:59 PM  
**To:** 'Calvin Ang (LKKAuto)' <[kalvinang@lkkauto.com](mailto:kalvinang@lkkauto.com)>  
**Subject:** Finalisation for Vehicle No. YP6677C

Hi Calvin

Please refer to photos attached for finalisation.

Thanks & Regards

*Ashley Tan*



**HUA HONG PRIVATE LIMITED**  
25D SUNGEI KADUT STREET 1 SINGAPORE 729332  
T. 6661 9690 | M. 9816 4151 | F. 6661 9699  
Follow us @ [huahong.com.sg](http://huahong.com.sg)



## Hsiao Tong (LKKAUTO)

---


**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Saturday, 15 December 2018 12:07 PM  
**To:** 'Ashley Tan'  
**Subject:** RE: LOD documents for Vehicle No. YP6677C  
**Attachments:** DV\_YP6677C.pdf

Without Prejudice

Hi Ashley,

We are prepared to revise our offer as follows: -

1. Cost of Repair(w/GST)	\$ 2,370.05
2. Loss of Rental (3days x \$100.00)	\$ 300.00
3. LTA/GIA search fee	\$ 2.00
<b>Total</b>	<b><u>\$ 2,672.05</u></b>



If our offer is acceptable by your client, please duly sign the DV enclosed and return together with the following document to us(LKK) for our necessary action: -

- Authorisation to Act signed by your client, Fly Build Pte Ltd

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ashley Tan <[ashley@huahong.com.sg](mailto:ashley@huahong.com.sg)>  
**Sent:** Tuesday, 11 December 2018 12:46 PM  
**To:** Hsiao Tong (LKKAUTO) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Subject:** RE: LOD documents for Vehicle No. YP6677C

Dear Hsiao Tong

As spoken yesterday, please advise the loss of rental.





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/AIG18000413/Smb3** ✓

20 MARCH 2018

**GEEVA S/O GOPAL KRISHNAN** ✓  
BLK 242 SERANGOON AVE 3 ✓  
#02-198 ✓  
SINGAPORE 550242 ✓

Dear Sir/Madam,

**ACCIDENT INVOLVING SKH 8507E AND YP 6677C ON 20/09/2017**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim  
Case Handler  
DID: 6749 4274  
FAX: 6741 4108  
Email: [bevanlim@lkkauto.com](mailto:bevanlim@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## AUTHORIZATION TO ACT


I, Fly Build Pte Ltd ("the third party claimant")  
of 11 Woodlands Close, #06-35 Woodlands @ 11 5737853 (address),  
owner of YP 6677 C (vehicle no.) hereby authorize  
Hun Hong Pte Ltd  
("the workshop") to act for me with respect to my claim for  
repair costs and/or rental and/or loss of use ("claim") for my  
vehicle no. YP 6677 C that was damaged pursuant to the  
accident which occurred on 20/9/2017 (date) along  
Serangoon Avenue 2 (location)  
involving vehicle no/s SKH 8507 E  
("the accident").

I further authorize the workshop to settle my above mentioned  
claim in a manner that they deem fit and the workshop is further  
authorized to receive payment further to settlement of my claim  
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach  
on my behalf is on a without prejudice and without admission of  
liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 21 day of Sept (month) 20 17 (year)

  
Signed by "the third party claimant"

  
Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, HUA HONG PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,370.05 (Repair Cost), S\$300.00 (Loss of Use/Rental), S\$2.00 (Disbursement) for vehicle no. YP 6677C that was damaged pursuant to the accident which occurred on 20/09/2017 (date) along SERANGOON AVE 2 (location) involving vehicle no/s SKH 8507E. This is pursuant to the inspection conducted on 23/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner FLY BUILD PTE LTD (the third party claimant") of vehicle no. YP 6677C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to YP 6677C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.


This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 06 (day) of Jan (month) 2018 (year)

Signed by appointed surveyor





Signed by "the workshop" (with chop)



# HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street | Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huhong.com.sg

## TAX INVOICE

19 October 2018

HHTPClaims18-03F

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#09-16 AIG Building  
Singapore 079120

Attn: Motor Claims Dept

### ACCIDENT INVOLVING YP 6677 C & SKH 8507 E ON 20/09/2017 ALONG SERANGOON AVENUE 2 AT ABOUT 0745 HOURS

Insured : FLY BUILD PTE LTD  
Vehicle Registration No : YP 6677 C  
Vehicle Make : HINO  
Vehicle Model : XZU710R-HKFMS3  
Vehicle Chassis No : JHHUCS3H90K019587  
Policy No : VCA/P1969630  
Date of Accident : 20/09/2017

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 600.00
2	2	Rear Bumper Bracket (LH/RH)	\$ 250.00	\$ 500.00
3	1	Rear Bumper Step		\$ 250.00
				<u>\$ 1,350.00</u>
				Less 10%
				<u>\$ (135.00)</u>
				<u>\$ 1,215.00</u>

To dismantle & change rear bumper, rear bumper step, knocking & pull straight rear chassis frame and all area affected by accident.

\$ 500.00

To spray rear bumper, rear bumper LH/RH bracket, rear bumper step and rear chassis frame.

\$ 500.00

\$ 2,215.00

7% GST

\$ 155.05

\$ 2,370.05



Authorised by Claims Dept  
Mrs Tan @ 9639 9195



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-17-174436

Date of Request: 21/11/2017

Your Ref No: Online Purchase

Hua Hong Pte Ltd  
25D Sungei Kadut Street 1  
Singapore 729332

Dear Sir/Madam,

Enquiry Date 21/11/2017  
Enquiry By TOH SIEW NG  
TP Vehicle No. SKH8507E  
Accident Date 20/09/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Sep 2017 <a href="#">Edit Reg</a>		08 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,215.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,215.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Geeva S/O Gopal Krishnan, ID: S9140618G								
Main Claimant:	FLY BUILD PTE LTD, Co. Reg. No.: 201634895K								
Vehicle Reg. No.:	YP6677C	Date of Loss:	20/09/2017 07:00 - :59 [3 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7676878958SG	Policy/Cover Note No.:	2100427991						
Vehicle Reg. No. (Insured):	SKH8507E	Policy No. (Claimant):	VCA/P1969630						
		Excess:							
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 17/01/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*YP6677C (7676878958SG)  
[SKH8507E]**

**TP**

**FLY BUILD PTE LTD**

**Sep 20 2017 7:00AM**

**[Geeva S/O Gopal Krishnan]**

**Hua Hong Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
**View**
[View in Browser](#)

### Letters/Correspondences

1 per page



No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	

### Assessment Reports

1 per page

















No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/01/18 14:54	Accident Statement From: OD - Reg. No: SKH8507E, Claimant: GEEVA S/O GOPAL KRISHNAN	 Load HTM	

### Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
15	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/05/18 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/11/18 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	01/11/18 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	01/11/18 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	01/11/18 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	01/11/18 10:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/18 16:16	EMAIL FROM AIG DD 05012018	 Load PDF	
2	08/01/18 16:16	NOTICE & GIA REPORT	 Load PDF	
3	25/01/18 18:05	TP ESTIMATE- MARKED	 Load PDF	
4	16/03/18 12:01	LETTER TO OI	 Load PDF	
5	15/01/19 12:00	WORKSHOP INVOICE	 Load PDF	
6	15/01/19 12:00	AUTHORISATION TO ACT FORM	 Load PDF	
7	15/01/19 12:00	Release Voucher	 Load PDF	
8	15/01/19 12:00	GIA SEARCH	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKH8507E (Insd veh)	Model:	HINO XZU710R-HKFMS3 4.0
	YP6677C (TP veh)		D (M)
Date of Accident:	20/09/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	3,156.50
Final Repair Cost	:	\$	2,370.05
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,672.05

3.00 days at \$100.00 per day  
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Hua Hong Pte Ltd	:	\$ 2,672.05
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

15 Jan  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18000413/SPB3Q2

Date: 15/01/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100427991  
**Claimant Vehicle No :** YP6677C **Insured Vehicle No :** SKH8507E  
 Date of Loss: 20/09/2017 Nature of Claim: TP Claim No: 7676878958SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP6677C**  
 Make & Model: HINO XZU710R-HKFMS3, 4.0 D (M) Engine No: N04CUS30662  
 Reg. Date: 20/06/2017 (Man. Year: 2016) Chassis No: JHHUCS3H90K019587  
 Colour: Silver Odometer: 22793 km  
 Engine Capacity: 4009 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 7.00R16 Rear Tyre Size: 7.00R16  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,350.00	1,215.00	135.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,000.00	600.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,950.00</b>	<b>2,215.00</b>	<b>735.00</b>	<b>24.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>206.50</b>	<b>155.05</b>	<b>51.45</b>	<b>24.92</b>
<b>Nett Amount (S\$)</b>	<b>3,156.50</b>	<b>2,370.05</b>	<b>786.45</b>	<b>24.92</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		<b>300.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>2,672.05</b>		

### INSPECTION

Date of Assignment: 08/01/2018  
 Date Inspected: 23/01/2018 Inspected At: Hua Hong Pte Ltd (Sungei Kadut)  
 25D Sungei Kadut Street 1  
 Singapore 729332  
 Estimated Period of Repair: 3.0 days

---

**Adjuster:** Sebastian Yeang Wai Keen**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	600.00 F	*600.00 FL
2	2		*REAR BUMPER BRACKET (LH/RH)	Bent	500.00 F	*500.00 FL
3	1		*REAR BUMPER STEP	Bent	250.00 F	*250.00 FL
					<b>Sub Total (\$\$)</b>	<b>1,350.00 1,350.00</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00 135.00</b>
					<b>Total Parts (\$\$)</b>	<b>1,350.00 1,215.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & CHANGE REAR BUMPER,REAR BUMPER STEP,KNOCKING & PULL STRAIGHT REAR CHASSIS FRAME AND ALL AREA AFFECTED BY ACCIDENT	New	800.00	500.00
2	TO SPRAY REAR BUMPER,REAR BUMPER LH/RH BRACKET,REAR BUMPER STEP AND REAR CHASSIS FRAME	New	800.00	500.00
Gross Labour Cost (S\$)			<b>1,600.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >