SUNDER : -	ASSIGNA			
From (Person); 600 ([0] of	Sno	Date	Time: 01012018 1207 pr
Estimated Cost:		Bill to:		
OD (TP/WS/TP RES/	DD RES / EVA / INV / MV	/ CS	In mucodi	8KF 5922U
at Workshop m/s	Lee Brother		Tel:	
of		bukH Are 6 *		BOVI
Policy No:		Claim No:	cmi	01800085/THE
Sum Insured:		Excess:		
Make of Veh: (Client's Record)			D.0	D.A. 03012018
CA / REV / REP. / RED. Date/Time: 0901)00	EV 24 HRS WP1 1.18 pm Person Contacte	d. Koven		cle (N) OUT
Date/Time Action/Inst	ruction (🗸) ESHNA	nte		
STO E	1F&J - X			
SKT F	1111 - X			

Reference No.: (S) SMo 18000 491 UVb
Policy Type: OD / TP / TP RES / TL / EVA

Admin (

): Case handler to make sure all Information created by the assignment team are ACCURATE.

Typist

<u>dmin</u> () Office	Assign Form	<u>Y-Date</u>	N-Date	<u>Y-Date</u>	N-Date
C	Reference No.	~			
С	Customer Code				
N	Assign From				
С	Assign Date	~		-	
С	Veh No (Inspected)	V			
С	Veh No (Insured)	~			
c	D.O.A	~			
C	Policy No				
c	Claim No	~			
С	Insurance Authorisation (CA /REV/REP)				
С	Report Type	~			
C	Weekend Charges				
N	Survey held at/Repairer	/			
С	Excess				
Survey 1) Assig	or (): Case handler to make sure to make su		ompleted	all required	informat
С	Vehicle No	~	-	-	-
С	Regn Month/Year	~			
N	Vehicle Type	V		-	
Ν	Make & Model			-	
C	Engine Capacity. (C.C)	~	+		-
N	Colour			-	
С	Odometer. (Sp.Reading)	~		-	
С	Chassis No	~		-	
N	General Condition	~	_	-	
N	Steering	~		-	
N	Brake	~	-	-	-
N	Modification (Modi)			-	
С	Tyre Size	~	-	-	-
N	Tyre Make	~	-	1	-
С	Tyre Balance	r	-	-	-
С	Date of Inspection	~		-	+
N	Survey held	~		-	+
N	Des.of Damages	~			
(2) Syst	em - (Views/Merimen)				
C	Damaged Vehicle Photographs Uploaded	~			
	rkshop Estimate/Assignment Form			1	
N	ALL Parts condition	~		1	
С	Market Value for OD cases			-	
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)			-	
С	Days of repair	~	-	+	14
С	Finalised Amount	V			
С	Re-inspection Cases to Finalize within 5 Days				
(4) Sys	tem - (Views/Merimen)				1
C	Resurvey photo Uploaded	V			

Date

Case Handler



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internati	onale Des Experts En Autor	mobile		
SO	MPO INSURANCE	SINGAPORE PL	Ref : CS/SMO18000	0491/Uvb		
#05	RAFFLES PLACE -01/06 GAPORE LAND TO	DWERSINGAPORE 048623	Date: 09-01-2018			
1.		Policy Particulars	:- THIRD PARTY CLA	ım		
	Insured Veh.	SKF 5922U	Veh. Inspected	SLC 5168J		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	CMTD1800085/THE	Excess (\$)	0.00		
8	Assign From	GRACE TEO	Assign Date	09/01/2018		
2.		Vehicle Part	iculars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.	10		
	Chassis No.		Colour			
	Odometer	_	Steering			
	Brakes		Modification			
	General					
3.		Condit	ions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre		W 3-3	mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		Descripti	on of Damages			
5.	English National	Genera	al Information			
	Accident Date	03/01/2018	Inspection Date	09/01/2018		
	Survey held at	LEE BROTHERS AUTOMOTIV				
	The state of the s	1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883				
5a.		A Concrete C	temarks			
		ON WAS CONDUCTED ON A"WI				

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 10 January, 2018 2:52 PM

To:

'Teo, Grace'

Cc:

'Choo, Thelma'; 'Henry, Irene James'; SUR

Subject:

RE: CMTD1800085/THE - ACCIDENT INVOLVING SKF5922U & SLC5168J ON

03.01.2018

Attachments:

SLC 5168J PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SLC 5168J

Date of survey: 9/1/2018 Number of days: 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 9 January, 2018 1:28 PM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Choo, Thelma' <thelma.choo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR

<sur@lkkauto.com>

Subject: RE: CMTD1800085/THE - ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Tuesday, 9 January, 2018 12:07 PM

To: admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Karen < karen@leebrothers.com.sg >; Choo, Thelma < thelma.choo@sompo.com.sg >; Henry, Irene James

<irene.henry@sompo.com.sg>

Subject: CMTD1800085/THE - ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

Our Reference: CMTD1800085/THE

Dear LKK AUTO/ Marcus,

Please make arrangement to conduct the survey for SLC5168J.

Please be informed that Thelma Choo the handler of this case.

Best Regards **Grace Teo**Claims Division

D: 6329 5170 | T: 6461 6555 | **F**: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Karen [mailto:karen@leebrothers.com.sg]
Sent: Tuesday, January 09, 2018 12:04 PM

To: Teo, Grace

Cc: Choo, Thelma; Henry, Irene James

Subject: RE: CMTD1800085/THE - ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

Importance: High

Dear Grace,

Please arrange LKK Auto Consultants, Mr Marcus Chua.

Thanks & Best Regards

Ms Karen Lee Brothers Automotive Pte Ltd 1 Kaki Bukit Ave 6 #02-47 Autobay Singapore 417883 Tel: 6509 5521

2

Fax: 6509 5523

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Tuesday, 9 January, 2018 12:01 PM

To: Karen

Cc: Choo, Thelma; Henry, Irene James

Subject: CMTD1800085/THE - ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

Our Reference : CMTD1800085/THE

Your Reference: SLC5168J

Without Prejudice

Date: 9TH January 2018

Attention:

M/S LEE BROTHERS AUTOMOTIVE PTE LTD

Dear Karen,

ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

We refer to your Notice of Accident dated 09/01/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
1,500,500		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 **Website:** www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Karen [mailto:karen@leebrothers.com.sg]
Sent: Tuesday, January 09, 2018 11:36 AM

To: Claims - Motor Survey

Subject: ACCIDENT INVOLVING SLC5168J AND SKF5922U ALONG PIE ON 03.01.2018

Importance: High

Dear Sirs,

We refer to the above matter.

Please arrange pre-repair inspection for our client vehicle no. SLC5168J and let us have your surveyor list.

Thanks & Best Regards

Ms Karen Lee Brothers Automotive Pte Ltd 1 Kaki Bukit Ave 6 #02-47 Autobay Singapore 417883

Tel: 6509 5521 Fax: 6509 5523



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

CMTD1800085/THE

Our ref:

CS/SMO18000491/Uvb

DATE: 10/1/2018

The Motor Claims Department M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SLC 5168J

We thank for your instruction on 9/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on at the premises of M/s LEE BROTHERS AUTOMOTIVE PTE LTD 9/1/2018 and have the following to report:-

Workshop Estimate Amount : S\$15,741.73

Revised Estimate Amount

:S\$7,020.72

"Check" Items Amount

:\$\$6,251.57

Market Value

:S\$


LTA Reimbursement Value

:S\$

Nett Value

:S\$

rear



nearside

front

Description of Damage:

The vehicle sustained damages at the

rear and front portion

Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA

Licensed Appraiser

Catherine Chong (LKK Auto)

From: Teo, Grace < grace.teo@sompo.com.sg>

Sent: Tuesday, 9 January, 2018 12:07 PM

To: admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Karen; Choo, Thelma; Henry, Irene James

Subject: CMTD1800085/THE - ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

Our Reference: CMTD1800085/THE

Dear LKK AUTO/ Marcus,

Please make arrangement to conduct the survey for SLC5168J.

Please be informed that Thelma Choo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Karen [mailto:karen@leebrothers.com.sg] Sent: Tuesday, January 09, 2018 12:04 PM

To: Teo, Grace

Cc: Choo, Thelma; Henry, Irene James

Subject: RE: CMTD1800085/THE - ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

Importance: High

Dear Grace,

Please arrange LKK Auto Consultants, Mr Marcus Chua.

Thanks & Best Regards

Ms Karen
Lee Brothers Automotive Pte Ltd
1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883

Tel: 6509 5521 Fax: 6509 5523

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Tuesday, 9 January, 2018 12:01 PM

To: Karen

Cc: Choo, Thelma; Henry, Irene James

Subject: CMTD1800085/THE - ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

Our Reference: CMTD1800085/THE

Your Reference: SLC5168J

Without Prejudice

Date: 9TH January 2018

Attention:

M/S LEE BROTHERS AUTOMOTIVE PTE LTD

Dear Karen,

ACCIDENT INVOLVING SKF5922U & SLC5168J ON 03.01.2018

We refer to your Notice of Accident dated 09/01/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	

3	Priority Services	Jimmy Lee	
(4		Lawrence Ng	
	V	Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards **Grace Teo**Claims Division **D**: 6329 5170 | T: 6461 6555 | **F**: 6221 3147





Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Karen [mailto:karen@leebrothers.com.sg]
Sent: Tuesday, January 09, 2018 11:36 AM

To: Claims - Motor Survey

Subject: ACCIDENT INVOLVING SLC5168J AND SKF5922U ALONG PIE ON 03.01.2018

Importance: High

Dear Sirs,

We refer to the above matter.

Please arrange pre-repair inspection for our client vehicle no. SLC5168J and let us have your surveyor list.


Thanks & Best Regards

Ms Karen Lee Brothers Automotive Pte Ltd 1 Kaki Bukit Ave 6 #02-47 Autobay Singapore 417883 Tel: 6509 5521 Fax: 6509 5523

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	9377Z	
Vehicle Details		
Vehicle No.:	SLC5168J	
Vehicle to be Exported:	Yes	
Intended De-registration Date:	10 Jan 2018	
Vehicle Make:	SUBARU	
Vehicle Model:	SUBARU XV 1.6I-S AWD CVT	
Primary Colour:	Orange	
Manufacturing Year:	2016	
Engine No.:	FB16Y249710	
Chassis No.:	JF1GP3KC5GG170352	
Maximum Power Output:	84.0 kW (112 bhp)	
Open Market Value:	\$15,849.00	
Original Registration Date:	16 May 2016	
First Registration Date:	16 May 2016	
Transfer Count:	0	
Actual ARF Paid:	\$15,849.00 7924	
Intended PARF Rebate D	Details	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	15 May 2026	
PARF Rebate Amount:	\$11,886.00	
Intended COE Rebate D		
COE Expiry Date:	15 May 2026	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$47,889.00	
COE Rebate Amount:	\$38,311.00	
Total Rebate Amount:	\$50,197.00	

The information contained herein is correct as at 10 Jan 2018



Compare

MSME18002952 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 04/01/2018 14:49 SUBMITTED BY: Chia Pel Ying

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 04/01/2018 15:09

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Mobile Number Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	04/01/2018 14:49
Date Of Accident	03/01/2017 18:20
Exact Location Of Accident	PIE (CHANGI) BEFORE PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLC5168J
Insured/Policyholder	
Name Of Registered Owner	TEONG EE HNG
NRIC No	S8139377Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98223172
Alternative Phone No	OFFICE-98223172
Vehicle Particulars	
Manufacturer	SUBARU
Model	SLC5168J
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA190296/1
Cover Note Number	
Driver	
Name of Driver	TAN YEW MING EDWIN
NRIC No	S8100466H
Date Of Birth	08/01/1981
Occupation	INDOOR
Date Of Driving Pass	08/11/2002
Driving Experience	14 YEARS AND 1 MONTH
Gender	MALE

(LOCAL) +65-81988181

NOEMAIL

Address

29 FERNVALE CLOSE #19-23

Postcode

797464

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG PIE ON EXTREME RIGHT LANE. FRONT CARS BRAKE AND I FOLLOWED TOO AND STOP IN TIME, OUT OF SUDDEN, HIT BY VEHICLE B AT THE REAR, CAUSED MY CAR MOVED FORWARD AND HIT ONTO VEHICLE C. IT'S A CHAIN COLLISON OF 3 VEHICLES.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKF5922U

Vehicle Make/Model/Colour

VEHICLE B

Details Of Properties Vehicle Category

PRIVATE CAR

Name of Driver

FOO SIN CHUAN

NRIC/Passport Number

S7826934J

Contact Number

98433301

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKK4575T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

. .

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

VEHICLE C

PRIVATE CAR

STEPHEN

S7608931J

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection. investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

Date & Time:

(If driver is not the policyholder)

Name:

NRIC/FIN No.:

Reporting Centre Personnel's Signature

Sketch Plan #2 Pg. 1

SKETCH PLAN

2

PIE Charles Constant Constant

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The dravelling along the on extremite right lane. Front cars brake and a Allaw the and clop in Ann. And oil sindden, hit by Von is get the secon, Counsed may our moved forward a historials Veh C. His a chair collision of 3 vehicles.		
Veh C.		was dravelling along 91E on extrense with land
Veh C. Veh C.	Frank	con brake and a fallow the and the
Veh C. Veh C.	Zn S	Sugar O d P o No. 12 by 1/01 15 1 1 1
Veh C.	1. (TOWN COST STRANGEN, KA PY AND IS ALL THE
7.30.000	VEC.A.	, consect my our travers dimnary of hit only
He a chair collision of 3 vehicles.	TO 250 OF 12 DO	
	Hit?	a chair collision of 3 rehides

DECLARATION

I/We declare the foregoing particulars are true in every gespect.

Policyholder's Signature

Date & Time:

Oriver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel: 6509 5521 / 65095524 Fax: 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

SKF5922U

ESTIMATE

DATE : 09.01.2018

VEHICLE NO : SLC5168J

MAKE/MODEL: SUBARU VX

ACC DATE : 03.01.2018

PAR	TICU	LAR	UNIT PRICE	AMOUNT
	QTY		SS	S\$
		LIST PRICE		
1	1	REAR WINDSCREEN MOULDING MU	25.60	25.60 -
2	1	REAR TAILGATE 50 LLY 30	856.00	856.00
3	1	REAR TAILGATE RUBBER 741	136.40	136.40
4	1	REAR TAILGATE LOCK Two Shiled	172.00	172.00 -
5	1	REAR TAILGATE LOCK CATCH 11	36.00	36.00
5	1	REAR TAILGATE INNER HANDLE 114	42.00	42.00
7	1	REAR TAILGATE INNER TRIM	256.00	256.00
3	1	REAR TAILGATE NUMBER PLATE GARNISH	238.00	238.00
)	1	REAR TAILGATE EMBLEM LOGO 🖪 1	84.80	84.80
10	1	REAR TAILGATE EMBLEM 'SUBARU' 1	74.80	74.80 -
11	1	REAR TAILGATE EMBLEM 'XV'	88.00	88.00 -
12	1	REAR TAILGATE EMBLEM 'AWD' NUL	58.80	58.80
13	1	REAR TAILGATE EMBLEM 'SYMMETRICAI'	62.80	62.80
14	2	REAR TAILLAMP RH/LH	426.48	852.96
15	1	REAR BUMPER De (720.00	720.00
16	1	REAR BUMPER TOW COVER TWI	16.00	16.00
17	1	REAR BUMPER TOP GARNISH 'SUBARU' ALL	340.00	340.00
18	2	REAR BUMPER REFLECTOR RH/LH 🗸 🦪	28.00	56.00
19	2	REAR BUMPER SIDE PROTECTOR RH/LH 11	38.00	76.00 [
20	2	REAR BUMPER SIDE RETAINER RH/LH Sut/nec	76.00	152.00 ~
21	1	REAR BUMPER REINFORCEMENT	227.20	227.20-
22	1	REAR BUMPER 3RD BRAKE LIGHT	201.00	201.00
23	1	CENTRE EXHAUST PIPE 1	844.00	844.00
24	1	REAR EXHAUST BOX DD/Sul	676.00	676.00
25	1	REAR EXHAUST BOX HEAT SHIELD &	90.00	90.00 -
26	3	REAR EXHAUST MOUNTING, 19	20.00	60.00
27	1	REAR END PANEL 100	432.00	432.00 -
28	1	REAR END PANEL GARNISH TWI	180.00	180.00
29	1	REAR SPARE TYRE PANEL FOAM 47	374.00	374.00 [
30	1	REAR SPARE TYRE PANEL CARDBOARD 11	277.20	277.20
31	2	REAR FENDER INNER TRIM RH/LH	358.00	716.00 7
32	2	REAR FENDER INNER SHIELD RH/LH 1	68.00	136.00 6
W(1770)		an environmental destruction of the production of the control of t	BALANCE B/F	8,557.56



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

a all and oliginal	Affiliated to Federation Internation	onale Des Experts En Automo	obile
SOMPO INSURANCE	SINGAPORE PL	Ref : CS/SMO180004	91/Uvbn2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TO	WERSINGAPORE 048623	Date: 17-01-2018 Code: SMO	
	Policy Particulars	:- THIRD PARTY CLAIM	И
Insured Veh.	SKF 5922U	Veh. Inspected	SLC 5168J
Policy No.	AND THE PROPERTY OF THE PROPER	Coverage (\$)	0.00
Claim No.	CMTD1800085/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	09/01/2018
2.	Vehicle Part	iculars & Condition	
Make & Model	SUBARU XV (A)	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1GP3KC5GG170352	Colour	ORANGE
Odometer	27722	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Condi	tions of Tyres	
	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
4.	The state of the s	tion of Damages	
THE VEHICLE SU	STAINED DAMAGES AT THE F	RONT AND REAR PORTIO	N.
5.		al Information	
Accident Date	03/01/2018	Inspection Date	09/01/2018
Survey held at	LEE BROTHERS AUTOMOTIV	/E PTE LTD	
	1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		
5a.		Remarks	
A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
5b.		e Days of Repair	
ESTIMATED NOF	RMAL PERIOD FOR REPAIR:	8 Working Day	/s



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 5168J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	25.60	25.60
	REAR TAILGATE	BADLY DENTED	856.00	856.00
- 2	REAR TAILGATE RUBBER	TWISTED	136.40	136.40
	REAR TAILGATE LOCK	TWISTED / SHORTED	172.00	172.00
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	36.00	
1	REAR TAILGATE INNER HANDLE	NOT NECESSARY	42.00	7.5
1	REAR TAILGATE INNER TRIM	CRACKED	256.00	256.00
1	REAR TAILGATE NUMBER PLATE GARNISH	NOT NECESSARY	238.00	
1	REAR TAILGATE EMBLEM LOGO	NOT NECESSARY	84.80	10
1	REAR TAILGATE EMBLEM "SUBARU"	NECESSARY	74.80	74.80
1	REAR TAILGATE EMBLEM "XV"	NECESSARY	88.00	88.00
1	REAR TAILGATE EMBLEM "AWD"	NECESSARY	58.80	58.80
1	REAR TAILGATE EMBLEM "SYMMETRICAL"	NECESSARY	62.80	62.80
	REAR TAILLAMP RH/LH @\$426.48	CRACKED	852.96	852.96
1	REAR BUMPER	DISTORTED	720.00	720.00
1	REAR BUMPER TOW COVER	TWISTED	16.00	16.00
1	REAR BUMPER TOP GARNISH "SUBARU"	NECESSARY	340.00	340.0
2	REAR BUMPER REFLECTOR RH/LH @\$28.00	NOT NECESSARY	56.00	
2	REAR BUMPER SIDE PROTECTOR RH/LH @\$38.00	NOT NECESSARY	76.00	
2	REAR BUMPER SIDE RETAINER RH/LH @\$76.00	BENT / NECESSARY	152.00	152.0
1	REAR BUMPER REINFORCEMENT	DENTED	227.20	227.2
1	REAR BUMPER 3RD BRAKE LIGHT	CRACKED	201.00	201.0
1	CENTRE EXHAUST PIPE	TO REPAIR SEE LABOUR	844.00)
1	REAR EXHAUST BOX	DENTED / BENT	676.00	676.0
1	REAR EXHAUST BOX HEAT SHIELD	BENT	90.00	90.0
3	REAR EXHAUST MOUNTING @\$20.00	NOT NECESSARY	60.00	
1	REAR END PANEL	BADLY DENTED	432.00	432.0
	REAR END PANEL GARNISH	TWISTED	180.00	180.0
	REAR SPARE TYRE PANEL FOAM	NOT NECESSARY	374.00	
	REAR SPARE TYRE PANEL CARDBOARD	NOT NECESSARY	277.20	
	REAR FENDER INNER TRIM RH/LH @\$358.00	NOT NECESSARY	716.00	
	REAR FENDER INNER SHIELD RH/LH @\$68.00	NOT NECESSARY	136.00	

Report Ref No. CS/SMO18000491/Uvbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT BUMPER	DENTED / DEFORMED	720.00	720.00
1	FRT BUMPER SPOILER	NOT FITTED	850.00	
	FRT BUMPER SIDE RETAINER RH/LH @\$32.00	NECESSARY	64.00	64.00
	FRT GRILLE ASSY	CRACKED	846.25	504.00
	FRT GRILLE LOGO	NOT NECESSARY	102.00	
	FRT HEADLAMP RH/LH @\$1023.80	CRACKED	2,047.60	2,047.60
	FRT HEADLAMP RETAINER RH/LH @\$62.00	NOT NECESSARY	124.00	8
	FRT REINFORCEMENT	DENTED	222.00	222.00
- 8	FRT SPONGE	TORN	81.25	81.25
	LESS 20% DISCOUNT	1007-000-21N	-2,722.93	-1,851.28
			10,891.73	7,405.13
	SPECIAL NETT ITEMS			
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	
1	SET REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	20.00	20.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET FRT AND REAR NUMBER PLATE WITH CASING (SN)	BENT	100.00	80.00
1	SET FRT BUMPER CLIP AND GRILLE CLIP (SN)	NECESSARY	65.00	65.00
1	SET FRT BUMPER SENSOR PARKING (SN)	NOT NECESSARY	280.00	
			870.00	450.00
	LABOUR		VARIO (MARIO DE	
	TO KNOCK OUT DENT, CUT/WELD REAR PANEL AND REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF CENTRE EXHAUST PIPE.		1,400.00	1,100.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		1,600.00	1,500.0
	TO CHECK FRONT AND REAR WIRING.		60.00	30.0
	TO REMOVE, REFIX REAR WINDSCREEN.		120.00	120.0
	TO TRANSFER REAR TAILGATE PARTS.		100.00	60.0
	TO REMOVE, REFIX CUSHION. }		180.00	60.0
	TO REMOVE, REPLACE INNER TRIM. }		60.00	o l
	TO REMOVE, REPLACE EXHAUST CENTRE PIPE AND REAR EXHAUST BOX.		180.00	60.0
	TO REMOVE, REPLACE REAR REVERSE SENSOR.		80.00	50.0
	TO REMOVE, REPLACE FRONT PARKING SENSOR.		80.00	40.0

LEE BROTHERS AUTOMOTIVE PTE. LTD.

QTY	SS	CC
14 A10	55	S\$
	BALANCE C/F	8,557.56
3 1 FRT BUMPER D.>/De	720.00	720.00 ~
4 1 FRT BUMPER SPOILER NA	850.00	850.00
2 FRT BUMPER SIDE RETAINER RH/LH ALL	32.00	64.00
1 FRT GRILLE ASSY CALL FOR YOU		846.25
	102.00	102.00
	1,023.80	2,047.60=
	62.00	124.00
2	222.00	222.00 =
	81.25	81.25
1 1 FRT SPONGE 7		13,614.66
	9 246 TI FSS 20%	2,722.93
	9 266-P1 7404-14ESS 20%	10,891.73
SPECIAL NETT ITEMS.		101000
1 (SET) REAR WINDSCREEN SEALANT AL	80.00	80.00
1 (SET) REAR WINDSCREEN SPONGE TAPE 🗸	u, 20.00	20.00
1 (SET) REAR BUMPER REVERSE SENSOR	her 280.00	280.00
1 (SET) REAR BUMPER CLIP	45.00	45.00
1 (SET) FRT AND REAR NUMBER PLATE WITH	CASING Buf 100.00	100.00
1 (SET) FRT BUMPER CLIP AND GRILLE CLIP	w 65.00	65.00
7 1 (SET) FRT BUMPER SENSOR PARKING	280.00	280.00
		870.00
LABOUR CHARGES :		
TO KNOCK OUT DENT, CUT/WELD REAR PA PARTS	NEL AND REPLACE ACCIDENT	//00 1,400.00
TO SPRAY PAINTING ON ACCIDENT PORTIO	N	/520 1,600.00
TO CHECK FRONT AND REAR WIRING		30 60.00
TO REMOVE, REFIX REAR WINDSCREEN		120 120.00
TO TRANSFER REAR TAILGATE PARTS		6 0 100.00
TO REMOVE, REPLACE INNER TRIM		V 60.00
7 TO REMOVE, REFIX CUSHION		180.00
TO REMOVE, REPLACE EXHAUST CENTRE P	PE AND REAR EXHAUST BOX	6 0 180.00
TO REMOVE, REPLACE REAR REVERSE SENS		80.00
10 TO REMOVE, REPLACE FRONT PARKING SEI		40 80.00
11 TO TUFF KOTE		60 120.00
	stance here electify	3,980.00
the Repairer		3080
To resulvey belong	re after spray painting	10935.12
	ged part(s) during resurvey subject to confirmation	(1) 34 11
Third party surve	y is on a "Without Prejudice" basis	1748
Supplementary if	AND LABOUR GRAND TOTAL : em(s) must be resurveyed and approval from Insurance Company	\$ 15,741.73
is subject to final	approval non insulation company	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF KOTE.		120.00	60.00
			3,980.00	3,080.00
	GRAND TOTAL		15,741.73	10,935.13

RECOMMENDED COST OF LUMP SUM REPAIRS	8,700.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMO18000491/Uvbn2

CHUA KANG SENG

Licensed Appraiser