

ASS. REC. BY:

REF: CS/FCI18000496/Kvd302

Special Instructions:

Sgt. Kenneth

ASSIGNMENT (Office)From (Person): Teo Swee Keong of FCIDate/Time: 08/01/2018 @ 5:31pm

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SHD 5625Z

Insured: _____

SH 9889B

at Workshop m/s _____

Trans-Cab

Tel: _____

6287 6666

of _____

No. 2 AMK Street 63

Policy No: _____

Claim No: _____

SH 9889B (POA: 5/1/2018)

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. _____

05/01/2018

CA / REV / REP. / REV 24 HRS

1wp1

H.O.D. Endorsement: _____

Date/Time: _____

8:23am @ 09/01/2018

Person Contacted: _____

CundyVehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

☒ ExcessSHD 5625Z - CC3 / AXA 14095417 / K29352-1N.O.A. 11/08/2017SH 9889B - CC3 / FCI 17021040 / K7100392N.O.A. 07/01/201712/1/18Email preli revised to FCI

FCI

09/01/2018

SHD 56252

10 15

Estimated Cost

CD ☒ NS ☐ TR ☐ RES ☐ COR ☐ RES ☐ TERA ☐ VMA ☐ VMA

Contract Reference No SHD 56252

Vehicle Make/Model Trans-Cab

Address No. 2 AMK Street 63

Insured

Policy No

Damage No

Sum Insured


Excess

Claims Record

Make of Van

Policy Condition

Remarks: The van has commenced its repair at the time of inspection.



Ball or Water Valve

CAC Accident Report Consistent? Yes or No

CAI App Seen Consistent? Yes or No

Est. Repairs 08 days Yes Yes or No

Lim Sum 1-B.1 Yes Yes or No

CA REV PER 24 HRS 'wp'

Date Person Contacted

Vehicle Make/Model Trans-Cab

Year 1995

Color White / Red

St. Bearing

Engine

CNO VFI ABC ISANC 282188

Gen. Comp. Good Ref. Poor Burnt

Steering Good Jammed Leaked Burnt

Brake Good Jammed Leaked Burnt

Misc. C SRM STD A P M

Tyre Size 215/60R16

BS DUN EXNOVA GY FS LIA MID CHTS. PR SUM

TOYO YOKO Giti

Front

R Ba

L Ba

COC

Survey Report

Des of Damages Fr. Rear CS NS JC Road No

The JC Chassis frame Body Structure affected due to ...

Date Time Action/Inspection

11/11 File pass to Cethum

12/885.12 (Red 36,053.62, 7370)

RECEIVED 2 JAN 2019

Day Time Repaid

☐ Prel Report
☐ Final Report

Prel Report

Final Report

Day Time Repaid

12/11 typist

Add Fee

☐ Prel Report
☐ Final Report

Prel Report

Final Report

Day Time Repaid

TP

12,885.12

Days of Repair 8

Resurvey No. of Trip

Time Rep

38x15=570

170+570

50

50

18



15/11/18

861

Survey Department Check List (Case Handler)

Reference No. : CS / FCI 18000496 / Kvd3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURA

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Veron 12/1/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000496/Kvd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-01-2018



Code : FCI2

1. Policy Particulars : THIRD PARTY CLAIM

Insured Veh.	SH 9889B	Veh. Inspected	SHD 5625Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	09/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/01/2018	Inspection Date	09/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 12 January, 2018 11:25 AM
To: 'Teo Swee Keong'
Cc: 'Serene Ler'; SUR
Subject: RE: NEW SURVEY ASSIGNMENT - TP VEH REF: SHD5625Z OUR REF: SH9889B DOA 5/1/2018
Attachments: SHD 5625Z PRELI ADVISED.pdf

Dear Swee Keong,

Enclosed preliminary revised of vehicle SHD 5625Z

Date of survey: 9/1/2018

Number of days: 8 days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Tuesday, 9 January, 2018 9:54 AM
To: 'Teo Swee Keong' <TeoSweeKeong@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serenerler@first-insurance.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT - TP VEH REF: SHD5625Z OUR REF: SH9889B DOA 5/1/2018

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Teo Swee Keong [mailto:TeoSweeKeong@first-insurance.com.sg]
Sent: Monday, 8 January 2018 5:31 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Serene Ler <Serenerler@first-insurance.com.sg>; Candy Kong (candy.kong@transcab.com.sg) <candy.kong@transcab.com.sg>
Subject: NEW SURVEY ASSIGNMENT - TP VEH REF: SHD5625Z OUR REF: SH9889B DOA

5/1/2018

Dear Sirs

New survey request for your handling.

Thanks and Regards,

SK Teo
Motor Claims Dept

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax
No. : 6507 3849 | Company Regn. No. 195000106C
email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing
of your personal data. Please refer to www.first-insurance.com.sg for
details of PDPA Personal Data Collection Statement.
Confidentiality Notice: This e-mail is confidential. It may also be legally
privileged. If you are not the addressee or to whom it is intended, you may
not copy, forward, disclose or use any part of it. If you have received this
message in error, please delete the message and all copies from your system
and notify the sender immediately by return e-mail.

-----Original Message-----

From: Caroline Cabrera
Sent: Monday, January 08, 2018 1:12 PM
To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Subject: FW: ARRANGE FOR SURVEY SHD5625Z

Dear SK,

For survey

Thanks & Regards
Caroline Cabrera
Motor Claims Department

First Capital Insurance Ltd

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C
D: 6507 3848 | F: 6507 3849
email: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing
of your personal data.
Please refer to www.first-insurance.com.sg for details of PDPA Personal Data
Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]

Sent: Monday, January 8, 2018 1:11 PM

To: Motor_Claims <Motor_Claims@first-insurance.com.sg>

Cc: Aini Binte Md Min <aini@first-insurance.com.sg>

Subject: ARRANGE FOR SURVEY SHD5625Z

Dear all ,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SH9889B - 05.01.2018 at 1000 Hrs - SHD5625Z

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED
Our ref: CS/FCI18000496/Kvd3

Date : 12/1/2018

The Motor Claims Department
M/s First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 5625Z


We thank for your instruction on 8/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 9/1/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$48,938.79
Revised Estimate Amount	: S\$12,885.12
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Sent: Monday, 8 January, 2018 5:31 PM
To: 'assignments@lkkauto.com'
Cc: Serene Ler; Candy Kong (candy.kong@transcab.com.sg)
Subject: NEW SURVEY ASSIGNMENT - TP VEH REF: SHD5625Z OUR REF: SH9889B DOA 5/1/2018
Attachments: img-108130900-0001.pdf; MOTOR SURVEY ASSIGNMENT.pdf

Dear Sirs

New survey request for your handling.

Thanks and Regards,

SK Teo
Motor Claims Dept

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C
email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: Caroline Cabrera
Sent: Monday, January 08, 2018 1:12 PM
To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Subject: FW: ARRANGE FOR SURVEY SHD5625Z

Dear SK,

For survey

Thanks & Regards
Caroline Cabrera
Motor Claims Department

First Capital Insurance Ltd

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C

MOTOR SURVEY ASSIGNMENT

Date 8/1/2018
Accident Date 5/1/18
Insured Vehicle SH9889B
Survey Location Trans-Cab Auto Services Pte Ltd
No. 2 Ang Mo Kio street 63
Singapore 569111
Contact No. 6257 1330
Our Ref No. SH9889B
Claim Type 3rd Party
Third Party Vehicle SHD5625Z
Contact Person Candy Kong
Fax No. 62571330

Survey Type Without Prejudice (Accident not reported / Est WR: \$48,938.79)

Appointed Surveyor LKH
Contact Person
Contact Number 6256 3561
Fax No. 6841 6315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & est

Cc : Workshop Trans - Cab Auto Services Pte Ltd
Officer In charge Serene Lee
Attention Candy Kong

IMPORTANT NOTE

Kindly submit the survey report by email only to surveyor@firstinsurance.com.sg within 14 days of survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

D: 6507 3848 | F: 6507 3849
email: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]
Sent: Monday, January 8, 2018 1:11 PM
To: Motor_Claims <Motor_Claims@first-insurance.com.sg>
Cc: Aini Binte Md Min <aini@first-insurance.com.sg>
Subject: ARRANGE FOR SURVEY SHD5625Z

Dear all ,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SH9889B - 05.01.2018 at 1000 Hrs - SHD5625Z

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD5625Z

Vehicle to be Exported: Yes

Intended De-registration Date: 05 Jan 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002699

Chassis No.: VF1ABL15AUC282188

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 16 Oct 2015

First Registration Date: 16 Oct 2015

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Oct 2023

PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date:	15 Oct 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,439.00
COE Rebate Amount:	\$32,811.00
Total Rebate Amount:	\$47,809.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/01/2018 13:53
Date Of Accident	05/01/2018 10:00
Exact Location Of Accident	COLLYER QUAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5625Z
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	NG NEE LEONG
NRIC No	S1217718F
Date Of Birth	07/10/1955
Occupation	OUTDOOR
Date Of Driving Pass	23/07/1979
Driving Experience	38 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81884798
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 838 WOODLANDS STREET 82 #04-269
Postcode	730838
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 05.01.2018 at about 1000hours, I was travelling straight on the third lane along Collyer Quay. Suddenly I felt an impact. Vehicle B (SH9889B) which was travelling on my left swerved into my lane and hit onto my taxi's left side portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH9889B
Vehicle Make/Model/Colour	COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Collyer Quay



A = 5705625 Z
B = 549889 B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach HIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

TRANS-CAB AUTO SERVICES PTE LTD

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5625Z - FCIL**AAD1801-075***Not Authored**Revised B4 point 8/12/2015-12*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD5625Z - CANDY

VF1ABL15AUC282188

RENAULT

LATITUDE

05.01.2018

FCIL**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>N</i>	1,259.42	} X
2	1	BUMPER ABSORBER FRT	\$	<i>SL</i>	394.68	
3	1	BUMPER BEAM FRT	\$	<i>N</i>	914.08	
4	1	BUMPER SPOILER FRT	\$	<i>SL</i>	181.75	
5	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i>	472.83	
6	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i>	266.80	
7	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i>	207.22	
8	1	BUMPER RETAINER FRT LH	\$	<i>SL</i>	151.41	
9	1	BUMPER BRACKET FRT LH	\$	<i>N</i>	181.75	
10	1	HEADLAMP LH	\$	<i>SL</i>	1,184.43	
11	1	HEADLAMP PANEL FRT LH	\$	<i>N</i>	152.15	} X
12	1	FENDER PANEL FRT LH	\$	<i>B</i>	783.83	
13	1	FENDER INSULATOR LH	\$	<i>SL</i>	130.84	
14	1	FENDER BRACKET FRT LH	\$	<i>SL</i>	34.14	
15	1	WHEELARCH FRT LH	\$	<i>SL</i>	278.84	
16	1	WHEEL HOUSING PANEL FRT LH	\$	<i>N</i>	4,682.09	
17	1	LOWER ARM FRT LH	\$	<i>SL</i>	685.76	
18	1	KUNCKLE ARM FRT LH	\$	<i>SL</i>	846.98	
19	1	ABSORBER FRT LH	\$	<i>SL</i>	360.54	
20	1	RADAITOR GRILLE	\$	<i>SL</i>	1,707.78	
21	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i>	173.36	} X
22	1	RADAITOR GRILLE FRAME	\$	<i>SL</i>	1,353.75	
23	1	FRAME FULL SUPPORT PANEL	\$	<i>N</i>	615.90	
24	1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i>	89.79	
25	1	BONNET	\$	<i>N</i>	1,941.63	
26	1	DOOR MIRROR LH	\$	<i>NAL</i>	1,483.40	
27	1	DOOR MIRROR GLASS LH	\$	<i>SL</i>	242.33	
28	1	DOOR MIRROR BACK COVER LH	\$	<i>SL</i>	218.46	
29	1	DOOR MIRROR LAMP LH	\$	<i>SL</i>	194.18	
30	1	DOOR PANEL FRT LH	\$	<i>B</i>	2,844.66	
31	1	DOOR HINGE UPPER LH	\$	<i>N</i>	274.50	} X
32	1	DOOR HINGE LOWER LH	\$	<i>N</i>	300.55	
33	1	DOOR CHECK FRT LH	\$	<i>SL</i>	194.77	
34	1	DOOR LOCK FRT LH	\$	<i>N</i>	908.75	

25713.35

TRANS-CAB AUTO SERVICES PTE LTD

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

AAD1801-075

SHD5625Z - FCIL

35	1	DOOR CATCH FRT LH	\$	S ₂	131.23	}	X
36	1	DOOR GRAB HANDLE FRT LH	\$	S ₂	210.96		
37	1	DOOR HANDLE OUTER FRT LH	\$	S ₂	477.76		
38	1	DOOR HANDLE CAP FRT LH	\$	S ₂	35.52		
39	1	DOOR HANDLE SEAL FRT LH	\$	S ₂	7.89		
40	1	DOOR HANDLE COVER FRT LH	\$	S ₂	13.22		
41	1	DOOR HANDLE MODULE FRT LH	\$	S ₂	133.60		
42	1	DOOR REGULATOR FRT LH	\$	N	505.19		
43	1	DOOR REGULATOR MOTOR FRT LH	\$	S ₂	796.46		
44	1	DOOR REGULATOR GUIDE FRT LH	\$	S ₂	120.97		
45	1	DOOR GLASS FRT LH	\$	S ₂	625.96	}	X
46	1	DOOR FINISHER FRT LH	\$	S ₂	515.06		
47	1	DOOR MOULDING FRT LH	\$	S ₂	176.82		
48	1	DOOR WHETHERSTRIP FRT LH	\$	S ₂	410.27		
49	1	DOOR SEAL LOWER FRT LH	\$	S ₂	91.17		
50	1	DOOR SEAL FRT LH	\$	S ₂	72.82		
51	1	DOOR WAIST SEAL OUTER FRT LH	\$	S ₂	291.27		
52	1	ROCKER PANEL OUTER LH	\$	N	987.49		
53	1	DOOR PANEL REAR LH	\$	B ₂	2,844.66		
54	1	DOOR GUIDE REAR LH	\$	S ₂	176.82	}	X
55	1	DOOR HINGE UPPER LH	\$	N	274.50		
56	1	DOOR HINGE LOWER LH	\$	N	300.55		
57	1	DOOR CHECK REAR LH	\$	S ₂	203.06		
58	1	DOOR GRAB HANDLE REAR LH	\$	S ₂	210.96		
59	1	DOOR HANDLE OUTER REAR LH	\$	S ₂	126.49		
60	1	DOOR HANDLE CAP REAR LH	\$	S ₂	35.52		
61	1	DOOR HANDLE SEAL REAR LH	\$	S ₂	7.89		
62	1	DOOR HANDLE COVER REAR LH	\$	S ₂	13.22		
63	1	DOOR HANDLE MODULE REAR LH	\$	S ₂	133.60		
64	1	DOOR FINISHER REAR LH	\$	S ₂	423.10	}	X
65	1	DOOR MOULDING REAR LH	\$	S ₂	176.82		
66	1	DOOR SEAL REAR LH	\$	S ₂	162.02		
67	1	DOOR WAIST SEAL OUTER REAR LH	\$	N	334.69		
68	1	DOOR REGULATOR REAR LH	\$	N	665.63		
69	1	DOOR REGULATOR MOTOR REAR LH	\$	N	893.75		
70	1	FENDER PANEL REAR LH	\$	B ₂	3,299.13		

TOTAL	\$	41,599.48
10%	\$	4,159.94
	\$	37,439.48

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	N ₂	66.00	X
---	------	-----------------------	----	----------------	-------	---

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-075**

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5625Z - FCIL

2	1SET	FRONT BUMPER CLIP	\$	nn 66.00 X
3	1SET	BUMPER SUPPORT FRT CLIP LH	\$	nn 9.80 X
4	1SET	BUMEPR RETAINER FRT CLIP LH	\$	nn 12.50 X
5	1	RIM LH FRT	\$	sn 385.00 X
6	1	TYRE LH FRT	\$	sn 330.00 X
7	1	DOOR STICKER "Trans-cab"	\$	na 80.00 60sn
8	1	DOOR STICKER "Classic"	\$	na 30.00 15sn
9	1	DOOR STICKER "6555-3333"	\$	na 80.00 60sn

TOTAL	\$	1,059.30
TOTAL PARTS	\$	38,498.79

To Check Electrical Lighting Concerned.	\$	170.00 30q
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00 1000q
Putty and spray painting of the affected portion.	\$	4,500.00 1320q
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 60q
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 120q
Towing fees	\$	nn 120.00 X
To rust-proofing of the affected areas.	\$	170.00 90q

To dismantle and refit front end suspension, undercarriage, parts, final checking and testing.

\$	nn 380.00 X
----	-------------

(PARTS BY PARTS) Repair Days

TOTAL	\$	10,440.00
Over All Total	\$	48,938.79

15 Days

Solely




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000496/Kvd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9889B	Veh. Inspected	SHD 5625Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	SH 9889B (DOA:5/1/2018)	Excess (\$)	0.00	
Assign From	TEO SWEE KEONG	Assign Date	09/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC282188	Colour	WHITE / RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	7 mm	
L/H Front Tyre	215/60 R16	GITI	7 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/01/2018	Inspection Date	09/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5625Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.22	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER BRACKET FRT LH	TO REPAIR SEE LABOUR	181.75	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER BRACKET FRT LH	SERVICEABLE	34.14	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	WHEEL HOUSING PANEL FRT LH	TO REPAIR SEE LABOUR	4,682.09	-
1	LOWER ARM FRT LH	SERVICEABLE	685.76	-
1	KNUCKLE ARM FRT LH	SERVICEABLE	846.98	-
1	ABSORBER FRT LH	SERVICEABLE	360.54	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	173.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	TO REPAIR SEE LABOUR	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-

Report Ref No. CS/FC118000496/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR MIRROR LH	DENTED / CUT	1,483.40	1,483.40
1	DOOR MIRROR GLASS LH	SERVICEABLE	242.33	-
1	DOOR MIRROR BACK COVER LH	SERVICEABLE	218.46	-
1	DOOR MIRROR LAMP LH	SERVICEABLE	194.18	-
1	DOOR PANEL FRT LH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT LH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT LH	SERVICEABLE	131.23	-
1	DOOR GRAB HANDLE FRT LH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER FRT LH	SERVICEABLE	477.76	-
1	DOOR HANDLE CAP FRT LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL FRT LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER FRT LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT LH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT LH	SERVICEABLE	120.97	-
1	DOOR GLASS FRT LH	SERVICEABLE	625.96	-
1	DOOR FINISHER FRT LH	SERVICEABLE	515.06	-
1	DOOR MOULDING FRT LH	SERVICEABLE	176.82	-
1	DOOR WEATHERSTRIP FRT LH	SERVICEABLE	410.27	-
1	DOOR SEAL LOWER FRT LH	SERVICEABLE	91.17	-
1	DOOR SEAL FRT LH	SERVICEABLE	72.82	-
1	DOOR WAIST SEAL OUTER FRT LH	SERVICEABLE	291.27	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	987.49	-
1	DOOR PANEL REAR LH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-

Report Ref No. CS/FC118000496/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH	SERVICEABLE	203.06	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR LH	TO REPAIR SEE LABOUR	334.69	-
1	DOOR REGULATOR REAR LH	TO REPAIR SEE LABOUR	665.63	-
1	DOOR REGULATOR MOTOR REAR LH	TO REPAIR SEE LABOUR	893.75	-
1	FENDER PANEL REAR LH	BENT	3,299.13	3,299.13
	LESS 10% DISCOUNT		-4,159.94	-1,125.56
			37,439.48	10,130.12
	SPECIAL NETT ITEMS			
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	66.00	-
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER SUPPORT FRT CLIP LH (SN)	NOT NECESSARY	9.80	-
1	SET BUMPER RETAINER FRT CLIP LH (SN)	NOT NECESSARY	12.50	-
1	RIM LH FRONT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER "CLASSIC" (SN)	NECESSARY	30.00	15.00
1	DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
			1,059.30	135.00

Report Ref No. CS/FCI18000496/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT, BUMPER BEAM FRT, BUMPER BRACKET FRT LH, HEADLAMP PANEL FRT LH, WHEEL HOUSING PANEL FRT LH, FRAME FULL SUPPORT PANEL, FRAME FULL SUPPORT BRACKET, BONNET, DOOR HINGE UPPER LH, DOOR HINGE LOWER LH, DOOR LOCK FRT LH, DOOR REGULATOR FRT LH, ROCKER PANEL OUTER LH, DOOR HINGE UPPER LH, DOOR HINGE LOWER LH,}		4,200.00	1,000.00
	DOOR WAIST SEAL OUTER REAR LH, DOOR REGULATOR REAR LH AND DOOR REGULATOR MOTOR REAR LH. }		-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	1,320.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
			-	-
			-	-
			10,440.00	2,620.00
	GRAND TOTAL		48,938.78	12,885.12

RECOMMENDED COST OF REPAIRS	12,885.12
------------------------------------	------------------

Report Ref No. CS/FCI18000496/Kvd3e2



Report Ref No. CS/FCI18000496/Kvd3e2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.