

## COMFORTDELGRO ENGINEERING PTE LTD

QBE - CP/P)

TS

REPAIR ESTIMATE\*

VEHICLE NO : SHD 3224K

DATE 8/1/2018

MAKE :

LKE - Brian

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>reg</i>			\$ 603.60	x
	Rear Bumper Clips <i>4cc</i>			\$ 22.00	✓
	Rear Bumper Sponge <i>2cc</i>			\$ 143.40	x
	SUB TOTAL			\$ 769.00	
	LESS 20% <i>25%</i>			\$ 153.80	
	DISCOUNTED TOTAL			\$ 615.20	
	Labour Charge				
	Panel Beating			\$ 350.00	2001-
	Spray Painting Charge			\$ 200.00	1801-
	TOTAL LABOUR			\$ 550.00	
	ESTIMATE TOTAL			\$ 1,165.20	
<p>08/01/2018 2:15pm          Hlt Antenna          ? IP          Photo given          1 sign 2 days          LKE Antenna          g</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					