

ASS. REC. BY:

REF:

A16 / Ref / 13000546 / Khs7

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

1.31

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR 2830X

Yr Regn:

08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c

1498

Colour:

n. Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

10855

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC166047000237

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

9

mm

L/Bal.

3

mm

L/Bal.

9

mm

D.O.A.

2/1/18

D.O.I.

12/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/11 File pass to Customer

P/P 4883.92

(P/P: 570.96 / 39%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC4/AIG18000546/Khs3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 09-01-2018	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGJ 9747J	Veh. Inspected	SLR 2830X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/01/2018	Inspection Date	12/01/2018	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGJ9747J (AIG)

Date : 05-01-2018

Accident Date : 02-01-2018

Our Ref : SLR2830X / CHAN

STEVEN TAN

C/O ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND. EST. SECTOR C

#01-76

SINGAPORE 575642

Not Author
1.13.1
Runway B4 paint
2 days

ESTIMATE COST OF REPAIR FOR HONDA CIVIC SLR2830X

1 PC FRONT BUMPER FASCIA

Nil/Nil \$579.90 ✓

1 PC FRONT O/S BUMPER SIDE RETAINER

SL \$13.60 X

1 PC FRONT O/S BUMPER FOGLAMP COVER

SL \$38.50 X

\$631.10 *632*

LESS 20% \$126.22

~~\$504.88~~ *505.60*

\$504.88 *505.60*

TO PUTTY AND SPRAY FRONT BUMPER AND FRONT O/S FENDER

\$500.00 *2201*

TO REMOVE FRONT DAMAGED PARTS, PANEL BEATING FRONT O/S FENDER
,ALIGN,ADJUST,RENEW REPLACE PARTS AND REFIX

\$450.00 *2001*
~~\$1,454.88~~

1455.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Singapore Dollars One Thousand Four Hundred Fifty Four And Cents Eighty Eight Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGJ9747J (AIG)

Accident Date : 02-01-2018

Date : 05-01-2018

Our Ref : SLR2830X / CHAN

STEVEN TAN

C/O ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND. EST. SECTOR C

#01-76

SINGAPORE 575642

Not wither
1.13.1 *12/1/18*
Runny B4 paint
2 day

ESTIMATE COST OF REPAIR FOR HONDA CIVIC SLR2830X

1 PC	FRONT BUMPER FASCIA	<i>not in</i>	\$579.90	✓
1 PC	FRONT O/S BUMPER SIDE RETAINER	<i>in</i>	\$13.60	X
1 PC	FRONT O/S BUMPER FOGLAMP COVER	<i>in</i>	\$38.50	X
			\$631.10	
		LESS 20%	\$126.22	
			\$504.88	
			\$579.90	
			115.98	
			463.92	
			\$504.88	
	TO PUTTY AND SPRAY FRONT BUMPER AND FRONT O/S FENDER		\$500.00	2201
	TO REMOVE FRONT DAMAGED PARTS, PANEL BEATING FRONT O/S FENDER ALIGN, ADJUST, RENEW REPLACE PARTS AND REFIX		\$450.00	2001
			\$1,454.88	

P 463.92
L 420.00
883.92 ✓ *ok*

KENNETH
PS GAFAM TCS.

Singapore Dollars One Thousand Four Hundred Fifty Four And Cents Eighty Eight Only

Catherine Chong (LKK Auto)

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Sent: Monday, 8 January, 2018 2:38 PM
To: assignments@lkkauto.com; admin-a@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Leong, Kah Yin; Kaur, Baljit; Hassim, Mohd Fitri; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran
Subject: aigencrypt - Pre repair inspection request - SLR2830X VS SGJ9747J (OI) DOA: 2/1/2018
Attachments: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGJ97... (50.3 KB); SGJ9747J.TIF

Hi,

Please refer to the enclosed request from **Alan's United Auto Pte Ltd**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Mr. Kenneth Kong as Single Joint Expert as requested.

Thank you.

Best Regards,

Mariesa Abu Kassim

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

08.01.2018 @ 4.05pm
Kenny veh nulin

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SLR2830X (2518972191SG)**
[SGJ9747J]

TP

MR STEVEN TAN
Jan 2 2018 5:00PM
[Lim Huet Yam]
Alans United Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 10/01/2018 09:56 AM.
To LKK_HQ
Subject No OI GIA Report

Dear LKK

Please be informed that we have not received any OI GIA Report till date.

Please find OI details as below:

Lim Huet Yam

Blk 238 Hougang Ave 1 #04-286
Singapore 530238

97916959

Regards,
Imran

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18000546/hs3

10th January 2018

Lim Huet Yam

Blk 238 Hougang Ave 1 #04-286

Singapore 530238

Dear Sirs,

**ACCIDENT INVOLVING SGJ 9747J AND SLR 2830X ON 02/01/2018 ALONG/ AT
BUANGKOK CRESCENT OPPOSITE BLOCK 981C OPEN CARPARK**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghila

Claims

Tel : 6841 2096

Fax: 6741 4108

Email : vicalpeh@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Vic (LKKAUTO)

From: alan khong chin wah <alanauto@gmail.com>
Sent: Monday, 26 February, 2018 10:30 AM
To: Vic (LKKAUTO)
Subject: Re: aigencrypt - Pre repair inspection request - SLR2830X VS SGJ9747J (OI) DOA: 2/1/2018 *** LKK REF - CC4/AIG18000546/hs3

Dear Vic

Offer Accepted , please proceed payment to us thank you .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686

On Mon, Feb 26, 2018 at 10:26 AM, Vic (LKKAUTO) <vicalpeh@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Kenny,

We refer to the above matter and we confirmed in receipt of your Letter of Demand dated 05/02/2018.
Please disregard our previous email due to typo error.

On a without prejudice basis and purely for an amicable settlement and without admission of liability to our Insured's part, we propose below amount to settle your client's claim:

Cost of Repair (w/gst)	\$ 945.79
Loss of Rental (\$100 x 2 days)	\$ 200.00
GIA Search Fee	\$ 2.00
TOTAL	\$ 1,147.79

Kindly confirm acceptance for payment processing.

The above amount is to be made payable to **ALAN'S UNITED AUTO PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Monday, 5 February, 2018 10:16 AM

To: kennychan@alanutd.com; alan khong chin wah

Cc: Admin A; Asher Sng (LKKAuto); assignments; Vic (LKKAuto); Shirley Hiew (LKK Auto)

Subject: RE: aigencrypt - Pre repair inspection request - SLR2830X VS SGJ9747J (OI) DOA: 2/1/2018

*** LKK REF - CC4/AIG18000546/hs3

Your Ref: SLR 2830X

“WITHOUT PREJUDICE”

Our Ref: CC4/AIG18000546/Khs3

Dear Kenny,

ACCIDENT INVOLVING VEHICLES SGJ 9747J AND SLR 2830X ON 02/01/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2018 Edit Reg		09 Jan 2018 00:00 Edit Adj Rpt	S\$883.92 Edit Estimates	S\$883.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lim Huet Yam, ID: S1571864A, Tel: +6592968068		
Main Claimant:	MR STEVEN TAN, ID: S1237238H		
Vehicle Reg. No.:	SLR2830X	Date of Loss:	02/01/2018 17:00 - :59
Claim Type:	TP / 2518972191SG	Policy/Cover Note No.:	0100668073 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SGJ9747J	Policy No. (Claimant):	17-MU008824-R00
		Excess:	
Repairer:	Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76, 575642 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/01/2018]		
Driver/Custodian (Insured):	LIM TSEEU THIAM (), NRIC: S1640374A		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (10/01/2018): No OI GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR2830X (2518972191SG)**
[SGJ9747J]
TP
MR STEVEN TAN
Jan 2 2018 5:00PM
[Lim Huet Yam]
Alans United Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail		Print			
1	05/02/18 11:51	Video - Accident													1		Load MP4			
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1		Edit			
Assessment Reports															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail		Print			
1	26/01/18 14:31	Accident Statement From:SC - Reg. No: SGJ9747J, Claimant: LIM HUET YAM													1		Load HTM			
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	05/02/18 10:21	Chassis Number													1		Load JPG			
2	05/02/18 10:21	Odometer Reading													1		Load JPG			
3	05/02/18 10:21	General View													1		Load JPG			
4	05/02/18 10:21	General View													1		Load JPG			
5	05/02/18 10:21	General View													1		Load JPG			
6	05/02/18 10:21	General View													1		Load JPG			
7	05/02/18 10:21	General View													1		Load JPG			
8	05/02/18 10:21	General View													1		Load JPG			
9	05/02/18 10:21	General View													1		Load JPG			
10	05/02/18 10:21	General View													1		Load JPG			
11	05/02/18 10:24	Reinspection Photo													1		Load JPG			
12	05/02/18 10:24	Reinspection Photo													1		Load JPG			
Documentation															1 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	09/01/18 16:29	EMAIL FROM WORKSHOP DD 08.01.2018.pdf													1		Load PDF			
2	09/01/18 16:29	ACKNOWLEDGEMENT EMAIL TO AIG DD 08.01.2018.pdf													1		Load PDF			
3	09/01/18 16:30	TP ESTIMATE													1		Load PDF			
4	09/01/18 16:30	TP GIA REPORT 1													1		Load PDF			
5	09/01/18 16:30	TP GIA REPORT 2													1		Load PDF			
6	10/01/18 11:52	SGJ 9747J - NON REPORTING LETTER													1		Load PDF			
7	16/01/18 11:26	TP ESTIMATE- MARKED													1		Load PDF			
8	01/02/18 08:51	LETTER TO OI													1		Load PDF			
9	05/02/18 10:37	EMAIL TO AIG													1		Load PDF			
10	05/03/18 15:34	AUTHORISATION TO ACT													1		Load PDF			
11	05/03/18 15:34	GIA SEARCH													1		Load PDF			

12	05/03/18 15:34	RELEASE VOUCHER		Load PDF	
13	05/03/18 15:34	RENTAL RECEIPT		Load PDF	
14	05/03/18 15:34	WORKSHOP INVOICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGJ9747J (Insd veh)	Model:	HONDA CIVIC 1.5 TURBO VTI-S
	SLR2830X (TP veh)		SR (A)
Date of Accident:	02/01/2018		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				1,557.49
Final Repair Cost	:	\$				945.79
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				2 days
LTA / GIA Search Fee	:	\$				2.00
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				1,147.79

Is Third Party Workshop GIA Registered?	[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)			
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown

1)	Alan's United Auto Pte. Ltd.	:	\$	1,147.79
2)		:	\$	
3)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

05 Mar
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18000546/KHS3S2

Date: 05/03/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100668073
Claimant Vehicle No :	SLR2830X	Insured Vehicle No :	SGJ9747J
Date of Loss:	02/01/2018	Nature of Claim:	TP
		Claim No:	2518972191SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2830X	Engine No:	L15B72453250
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Chassis No:	MRHFC1660HT000237
Reg. Date:	08/08/2017 (Man. Year: 2017)	Odometer:	10655 km
Colour:	Metallic Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	505.60	463.92	41.68	8.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	420.00	530.00	55.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,455.60	883.92	571.68	39.27
+ GST 7.00/7.00% (S\$)	101.89	61.87	40.02	39.28
Nett Amount (S\$)	1,557.49	945.79	611.70	39.27
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,147.79		

INSPECTION

Date of Assignment:	09/01/2018		Alans United Auto Pte Ltd (HQ)
Date Inspected:	12/01/2018	Inspected At:	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76
Estimated Period of Repair:	2.0 days		Singapore 575642

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Dented / Cut	579.90 FL	*579.90 FL
2	1		*FRONT O/S BUMPER SIDE RETAINER	Serviceable	13.60 FL	*- FL
3	1		*FRONT O/S BUMPER FOGLAMP COVER	Serviceable	38.50 FL	*- FL
F=Franchise part, L=ListItemDisc,						
Sub Total (S\$)					632.00	579.90
- List Item Discount on L Items 20.00/20.00% (S\$)					126.40	115.98
Total Parts (S\$)					505.60	463.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY FRONT BUMPER AND FRONT O/S FENDER.	New	500.00	220.00
2	TO REMOVE FRONT DAMAGED PARTS, PANEL BEATING FRONT O/S FENDER, ALIGN, ADJUST, RENEW REPLACE PARTS AND REFIX.	New	450.00	200.00
Gross Labour Cost (\$\$)			950.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >