

ASS. REC. BY: \_\_\_\_\_

REF: CS/GAI18000554/Mjrd3z

Special Instruction: \_\_\_\_\_

SALE/LOT: MA 6804 6059 ASSIGNMENT (Office)

From (Person): Kelvyna Ngian of GAI Date/Time: 2:40pm @ 09/01/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP  WS  TP RES /  OD RES /  EVA /  INV /  MV /  CS

To Inspect Vehicle No: SCZ7557S Insured: \_\_\_\_\_

at Workshop m/s: Tropical Success Tel: 6481 7773

of Blk 5032, AMK Ind. Prk 2 #01-303 8733 8187 William

Policy No: \_\_\_\_\_ Claim No: CLM6MVP00000517

Sum Insured: \_\_\_\_\_ Excess: TBA \$400

Make of Veh: \_\_\_\_\_ D.O.A. 08/01/2018

(Client's Record) 10/01/2018

CA /  REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 2:56pm @ 09/11/2018 Person Contacted: Calvin Vehicle  IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>Flood Case</u>
	<u>SCZ7557S-X</u>
<u>12/1/18</u>	<u>Revert to Kelvyna through email.</u>
	<u>Repairer asking for \$35K; Pending claim number &amp; excess</u>
<u>24/1/18</u>	<u>sent anthorse repair to repairer. kelvyna anthorse at 6/5 \$22k</u>
	<u>Kelvyna ask to inform repair that if any balance will be paid by insured.</u>



## Nivitha (LKK Auto)

---

**From:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Sent:** Tuesday, 9 January 2018 2:40 PM  
**To:** 'SUR'; Ashley Chong (LKK Auto)  
**Subject:** FW: OD claim SCZ7557S: -flood damage -ACCIDENT REPORT & estimate  
**Attachments:** IMG\_20180109\_0001.pdf; SCZ7557S.pdf

Hi team

Please conduct OD survey –one of the cars affected by the flash flood yesterday.

Thanks  
Kelvyna

---

**From:** Tropical Success [mailto:tsac303@singnet.com.sg]  
**Sent:** Tuesday, January 09, 2018 10:34 AM  
**To:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Subject:** OD claim SCZ7557S: ACCIDENT REPORT & estimate

Hi kelvyna

Spoke to you yesterday. Attached here estimate for my customer SCZ7557S OD claim for flood damage.

Regards  
Calvin  
Tropical Success Auto Care  
Blk 5032 Ang Mo Kio Ind Pk2  
#01-303 S(569535)  
Tel: 64817773

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18000554/M1rd3	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 09-01-2018	
		Code : GAI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SCZ 7557S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	KELVYNA NGIAN	Assign Date	09/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/01/2017	Inspection Date	
Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Your Ref: TBADate: 12 January 2018Our Ref: CS/GAI18000554/M1rd3The Motor Claims Department  
GREAT AMERICAN INSURANCE COMPANY


Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SCZ 7557S**We thank you for the instruction on 09/01/2018Please be informed that we had conducted the inspection of the abovementioned vehicle 11/01/2018 at the premises of m/s: TROPICAL SUCCESS AUTO CARE and have the following to report:-

Repairer's Estimate (Gross)	: S\$ <u>66,808.60</u>
Revised Estimate Amount	: S\$ <u>10,002.00</u>
"Check" Items (Estimated)	: S\$ <u>25,733.80</u>
Total Repair Cost (Estimated)	: S\$ <u>35,735.50</u>
Pre-Accident Value	: S\$ <u>150,000.00</u>
COE/PARF value	: S\$ <u>118,781.00</u>
Nett Value	: S\$ <u>31,219.00</u>


**Description of Damage:**

The vehicle recovered from flood. Many electrical &amp; mechanism parts found damaged and contaminated by flood water at the time of inspection.

**Comment:**We have not authorize repair.Repairer asking repair cost Lump Sum \$35,000.00. Hence, we are of the view that the vehicle is not economical to repair.

Days of repair: 14 days

Yours faithfully  
MA CHIN FOOK  
Automotive Assessor



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 12 January 2018

Our Ref: CS/GAI18000554/M1rd3

The Motor Claims Department  
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,


**PRELIMINARY ADVICE OF VEHICLE NO. SCZ 7557S**

We thank you for the instruction on 09/01/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/01/2018 at the premises of m/s: TROPICAL SUCCESS AUTO CARE and have the following to report:-

Repairer's Estimate (Gross)	: <u>S\$ 66,808.60</u>
Revised Estimate Amount	: <u>S\$ 10,002.00</u>
"Check" Items (Estimated)	: <u>S\$ 25,733.80</u>
Total Repair Cost (Estimated)	: <u>S\$ 35,735.50</u>
Pre-Accident Value	: <u>S\$ 150,000.00</u>
COE/PARF value	: <u>S\$ 118,781.00</u>
Nett Value	: <u>S\$ 31,219.00</u>

Description of Damage:  
The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.



Comment:  
We have not authorize repair.  
Repairer asking repair cost Lump Sum \$35,000.00.  
Days of repair: 14 days

*hence we are of  
the view that the  
vehicle is not normal to  
repair.*

Yours faithfully  
MA CHIN FOOK  
Automotive Assessor

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Friday, January 12, 2018 3:39 PM  
**To:** 'Ngian, Kelvyna'  
**Cc:** SUR  
**Subject:** RE: OD claim SCZ7557S: -flood damage -ACCIDENT REPORT & estimate  
**Attachments:** SCZ 7557S OD.pdf

Dear Kelvyna,

Enclosed herewith preliminary revised of SCZ 7557S.  
Repairer asking repair cost not more than Lump sum \$35,000.00.

We have not authorize repair and kindly advise on excess and the claim number.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, January 09, 2018 2:59 PM  
**To:** 'Ngian, Kelvyna' <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: OD claim SCZ7557S: -flood damage -ACCIDENT REPORT & estimate

Dear Sir/Mdm,

Thank you for the assignment.

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]  
**Sent:** Tuesday, 9 January 2018 2:40 PM  
**To:** 'SUR' <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Ashley Chong (LKK Auto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** FW: OD claim SCZ7557S: -flood damage -ACCIDENT REPORT & estimate

Hi team

Please conduct OD survey –one of the cars affected by the flash flood yesterday.

Thanks  
Kelvynā

---

**From:** Tropical Success [<mailto:tsac303@singnet.com.sg>]  
**Sent:** Tuesday, January 09, 2018 10:34 AM  
**To:** Ngian, Kelvyna <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>  
**Subject:** OD claim SCZ7557S: ACCIDENT REPORT & estimate

Hi kelvyna

Spoke to you yesterday. Attached here estimate for my customer SCZ7557S OD claim for flood damage.

Regards  
Calvin  
Tropical Success Auto Care  
Blk 5032 Ang Mo Kio Ind Pk2  
#01-303 S(569535)  
Tel: 64817773

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 22 January 2018

Our Ref: CS/GAI18000554/M1rd3

The Motor Claims Department  
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SCZ 7557S**


We thank you for the instruction on 09/01/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/01/2018 at the premises of m/s: TROPICAL SUCCESS AUTO CARE and have the following to report:-

Repairer's Estimate (Gross)	: <u>S\$ 66,808.60</u>
Revised Estimate Amount	: <u>S\$ 10,002.00</u>
"Check" Items (Estimated)	: <u>S\$ 25,733.80</u>
Total Repair Cost (Estimated)	: <u>S\$ 35,735.50</u>
Pre-Accident Value	: <u>S\$ 150,000.00</u>
COE/PARF value	: <u>S\$ 118,781.00</u>
Nett Value	: <u>S\$ 31,219.00</u>

**Description of Damage:**

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.



**Comment:**

We have not authorize repair.

Repairer asking repair cost Lump Sum not more than \$25,000.00..

Days of repair: 14 days

Yours faithfully  
MA CHIN FOOK  
Automotive Assessor

## Janice Lee (LKKAuto)

---

**From:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Sent:** Wednesday, January 24, 2018 2:06 PM  
**To:** Janice Lee (LKKAuto)  
**Cc:** SUR  
**Subject:** CLMOMVP000000517: OD claim SCZ7557S: -flood damage -ACCIDENT REPORT & estimate

Dear Janice

We will authorize repair cost at \$22,000.00, subject to deduction of excess of \$400. Please inform repairer accordingly that the balance (if any) will be paid directly by the insured.

Thanks  
Kelvyna

---

**From:** Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]  
**Sent:** Monday, January 22, 2018 10:21 AM  
**To:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: OD claim SCZ7557S: -flood damage -ACCIDENT REPORT & estimate

Dear Kelvyna,

Enclosed herewith preliminary revised of **SCZ 7557S**.  
Repairer asking repair cost not more than Lump sum \$25,000.00.

We have not authorize repair and kindly advise on excess and the claim number.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Friday, January 12, 2018 3:39 PM  
**To:** 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: OD claim SCZ7557S: -flood damage -ACCIDENT REPORT & estimate

**Janice Lee (LKKAuto)**

---

**To:** tsac303@singnet.com.sg  
**Cc:** SUR  
**Subject:** SCZ 7557S GAI OD DOA : 11/02/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SCZ 7557S** at L/S not more than **\$22,000.00 (Excess \$400/-)**. Please note that the insurance has only authorise repair cost L/S **\$22,000.00(BEFORE excess \$400/-)**.  
**\*(If any)balance repair cost will be paid directly by the insured.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

張建福 (機件) 拖車服務  
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 18165

Date: 8.01.18

寶號  
Messrs: Tropical Success

車號  
Vehicle No: SGZ 7557S 車型  
Model No:

由  
From: upp. changi rd 到  
To: Ang Mo Kio ind. p. 2

時間 (日/夜)  
Time (day/night):

其他  
Others: King Jolly.

CASH \$: 120 CHEQUE:

經手人  
Authorised by: [Signature] 收貨人  
Received by:

注意 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。  
NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

張建福 (機件) 拖車服務  
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 18301

Date: 8.1.18

寶號  
Messrs: Tropical

車號  
Vehicle No: PCZ 7557 S 車型  
Model No: BM 740

由  
From: 032Ame 到  
To: Auto Point choy Hae

時間 (日/夜)  
Time (day/night):

其他  
Others: ← 2 trip

CASH \$: \$ 100.00 CHEQUE:

經手人  
Authorised by: [Signature] 收貨人  
Received by:

注意 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。  
NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

# Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 4773E

## Vehicle Details

Vehicle No.: SCZ7557S  
Vehicle to be Exported: No  
Intended De-registration Date: 08 Jan 2018  
Vehicle Make: B.M.W.  
Vehicle Model: 730LI AT D/AB 4DR SR LED DSC NAV HUD  
Primary Colour: Blue  
Manufacturing Year: 2012  
Engine No.: 10128323N52B30AF  
Chassis No.: WBAYE22020DZ20926  
Maximum Power Output: 190.0 kW (254 bhp)  
Open Market Value: \$74,262.00  
Original Registration Date: 31 May 2013  
First Registration Date: 31 May 2013  
Transfer Count: 0  
Actual ARF Paid: \$105,672.00

## Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 30 May 2023  
PARF Rebate Amount: \$79,254.00

## Intended COE Rebate Details

COE Expiry Date: 30 May 2023  
COE Category: E - Open Category

COE Period(Years):	10
Q <sub>1</sub> Paid:	\$73,301.00
COE Rebate Amount:	\$39,527.00
<b>Total Rebate Amount:</b>	<b>\$118,781.00</b>

The information contained herein is correct as at 08 Jan 2018

OK

- Lowest Down (To share driving experience and safety)
- Kuppel Corp pays \$4570m to resolve boiler fraud

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**



Shine Connect

**Lake View Credit Pte Ltd**

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted 20 results/page

Save Search

To get alerted when new  
BMW 7 Series is added

Search Selection



**BMW 7 Series 730Li Sunroof** **\$161,800** **\$14,970 /yr** **25-Jun-2011** **2,996 cc** **61,251 km** **Luxury** **Available**

New Facelift LED Headlight Model! Promo 1.79% Interest Rate! Low Mileage! 1 MD Owner! Fully Agent (PML) Servicing Records Since Day 1. Free 1 Year Extended Premium Warranty + 1 Year Doorsteps Serv...

Hamilton Autohub Pte Ltd

Posted: 06-Jun-2018 Tags: 2011 BMW 730Li, BMW 730Li, BMW 730Li, Used BMW



**BMW 7 Series 730Li Sunroof** **\$140,800** **\$13,550 /yr** **26-Apr-2013** **2,996 cc** **72,000 km** **Luxury** **Available**

1 Owner, Low Mileage Done, Full Serviced Histories With PML, Up To 80% Loan Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.

Faster Auto Trading

Posted: 06-Jun-2018 Tags: 2011 BMW 730Li, BMW 730Li, BMW 730Li, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Eng Cap Mileage

For old advertisements, view Expired ads

30 results/page

sgCarMart is the number one car marketplace for private import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale from cars, mainly used cars, luxury cars, sports cars & SUVs, MPV, hatchback, or CUV, SUV & MPV cars. We can also help you find a car for sale, for mileage cars, car history, compare rates & car insurance. Find the used BMW 730Li, used BMW 730Li Singapore, used BMW 730Li, used BMW 730Li Singapore or even the used BMW 730Li Singapore. We have more car dealers comprising private imported, individual car dealers, and car hire dealers in our site. From new car price lists, new car searches and new car promotions, but our partner sites are also covered for Singapore jobs, real estate properties for sale, travel, car performance, cars, car reviews, forum reviews, commercial vehicle leasing & UOE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but we do not warrant or give any form of responsibility in accuracy, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Cars
- Used Cars
- Sell My Car
- Directory
- Products
- Articles
- Forum
- Tools & Tips

- About Us
- Contact Us
- Privacy Policy
- Terms of Service

- Terms of Service
- Privacy Policy
- Privacy Data Protection Statement

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renege policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/01/2018 15:33
Date Of Accident	08/01/2018 09:05
Exact Location Of Accident	BEDOK NORTH AVE 4 AND UPPER CHANGI RD JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCZ7557S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE BEE KIEN
NRIC No	S6814773E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98188727
Alternative Phone No	OTHERS-98188727

### Vehicle Particulars

Manufacturer	BMW
Model	730LI-3.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVP000000438-01-000
Cover Note Number	31/05/2017 - 30/05/2018

### Driver

Name of Driver	LEE BEE KIEN
NRIC No	S6814773E
Date Of Birth	19/04/1968
Occupation	INDOOR
Date Of Driving Pass	24/09/1986
Driving Experience	31 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98188727
Fax Number	
Contact Number	OTHERS-98188727
EMail Address	NOEMAIL

Address

22 TANAH MERAH KECIL LINK #03-46  
465427

Postcode

Was driver an employee of the Insured's Company? NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

### General information of the Accident

Type Of Accident

FLOOD

Weather Conditions

RAINING

Road Surface

FLOODED

### Other information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 1

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? NO

I have been approached by unknown persons) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

REFER TO STATEMENT

### Attachment(s)


Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08 January 2018 at 9:00am, I was driving north along Bedok North Ave 4 towards lpp Changi Rd. It was raining heavily and my car was stuck in traffic jam at junction of lpp Changi Rd. When I was turning into lpp Changi Rd, suddenly my car could not start and could not move. My car was flooded with water due to the heavy rain.

Vehicle No: S(7 7557S (6A)

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature

Date & Time

08/01/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name:

NRIC/IN No:

(ANK)

Claim Own Policy  Claim Third Party  Reporting Only  
 Claim TD/TIP at other workshop (Tropical Success)

Sketch Plan

SKETCH PLAN

VEHICLE NO: SGE 7337S  
INSURER: PICCA American  
DATE & TIME: 08/01/2018  
(A 2015)

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repealate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an **admission of policy liability** on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**K. Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 08/01/18

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Approving Centre Personnel's Signature  
Name: [Signature]  
NIC/PIN No: [Signature]



**GREATAMERICAN.**  
INSURANCE COMPANY

UEN: T15FC0029B    GBT REG. NO.: M90370081T  
3 TEMASEK AVENUE, #16-01 CENTENNIAL TOWER  
SINGAPORE 039190  
TEL: +65 8904 6000  
FAX: +65 6235 2616

## CERTIFICATE OF INSURANCE

Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) Motor Vehicles (Third Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third Party Risks) Rules, 1960 (Malaysia)

### Policy Details

Certificate Number	: MOMVP000006438-01-000	Cover	: Private Car (Comprehensive)
Policyholder Name	: Lee Bee Kien	Chassis Number	: WBAYE22020DZ20926
NCD Entitlement	: 50% No Claim Discount	Engine Number	: 10128323N52B30AF
Hire Purchase	: United Overseas Bank Limited	Registration Number	: SCZ7557S
Period of insurance	: From 31/05/2017 (00:00) To 30/05/2018 (23:59) (Both Dates Inclusive)		

### Persons or Classes of Persons entitled to Drive

- a) The Policyholder  
b) Any person who is driving on the Policyholder's order or with their permission  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor or so has been Vehicle permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

### Limitations as to Use

Use only for social, domestic and pleasure purposes and for Policyholder's business  
This Policy does not cover:

- a) Use for Hire and Reward  
b) Use for racing, pace making, reliability trial or speed testing  
c) Use for carriage of goods (other than samples) in connection with any trade of business  
d) Use for any purpose in connection with Motor Trade

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

Excess (Section 1)	: SGD 400.00	Workshop	: Any Workshop
Excess (Section 2)	: N/A	Off Peak Car	: No
Windscreen Excess	: SGD 100.00	NCD Protection	: Yes
ADDITIONAL EXCESS	: Please refer overleaf		


### Driver Details

Main Driver	: Lee Bee Kien
Named Driver 1	: Ong Sing Seng
Named Driver 2	: N/A
Named Driver 3	: N/A
Name of Intermediary	: Anna & Associates
Date of Issue	:

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Signed for and on behalf of

**Great American Insurance Company**



Authorized Signatory

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S6814773E



LEE BEE KIEN

李美娟

Name

CHINESE

Date of Birth

19-04-1968

Sex

F

Country of Birth

SINGAPORE



1605188



NRIC No. S6814773E

Blood Group

O+

Religion

10-01-1994

22 TANAH MERAH KECHIL LINK #03-46  
SINGAPORE 485427

NRIC No: S6814773E

Date: 28/07/2017

REPUBLIC OF SINGAPORE DRIVING LICENCE

NRIC No. S6814773E



LEE BEE KIEN

Birth Date: 19 Apr 1968

Issue Date: 03 May 2010



001852685A

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

ISSUE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of 24 Sep 1986  
at the driver; and other motor vehicles <= 2500kg



Licence No. S6814773E

NR 176A

# TROPICAL TECH AUTOMOBILE SERVICES

Blk 5032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Great American Insurance Company, Singapore Branch**  
 Attn : 3, Temasek Avenue, #16-01,  
 Centennial Tower,  
 Singapore 039190

Estimate bill : TT 02 / 18 / TP / 18

Registration No : SCZ7557S

Make / model : BMW 730Li (F02)

Office No :

Fax No :

Date 04 / 01 / 2018

Mileage :

**OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.**

1pc	Air con 134a condenser		\$	862.00
1pc	Air con 134a compressor		\$	1,465.00
1pc	Air con blower motor		\$	1,277.00
1pc	Air con blower motor resistance		\$	511.00
1pc	Air con 134a expansion valve		\$	190.00
1pc	Air con 134a cooling coil		\$	1,138.00
1pc	Engine oil filter with 'O' ring		\$	23.00
1pc	Engine air filter		\$	63.00
1pc	Alternator		\$	2,426.00
1pc	Engine air mass		\$	776.00
1pc	Engine electronic throttle body		\$	1,620.00
1pc	Engine control unit		\$	4,680.00
1pc	Engine oil cap		\$	50.00
1pc	Engine valve cover		\$	1,149.00
1pc	Engine timing top plate		\$	121.00
2pcs	Engine cam shaft balancing gear	(Each \$1725.00)	\$	3,450.00
2pcs	Engine cam shaft balancing gear plate	(Each \$90.00)	\$	180.00
2pcs	Engine cam shaft balancing gear plate bolt	(Each \$25.00)	\$	50.00
1set	Engine valve seal (Inlet)		\$	205.00
1set	Engine valve seal (Exhaust)		\$	205.00
1set	Engine grinding valve gasket kit		\$	1,035.00
1pc	Engine cylinder head gasket		\$	332.00
1pc	Engine timing chain		\$	380.00
1pc	Engine timing chain tensioner		\$	276.00
	Sub total :		\$	22,464.00
	Less 10% discount :		\$	2,246.40
	A total :		\$	20,217.60
Total amount for Page 1 :			\$	20,217.60

Tropical Tech Automobile Services

(Authorised Signature)

# TROPICAL TECH AUTOMOBILE SERVICES

Bk 5032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : Great American Insurance Company, Singapore Branch  
 Attn : 3, Temasek Avenue, #16-01,  
 Centennial Tower,  
 Singapore 039190

Estimate bill : TT 02 / 18 / TP / 18

Registration No : SCZ7557S

Make / model : BMW 730Li (F02)

Office No :

Fax No :

Date 04 / 01 / 2018

Mileage :

**OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.**

1pc	Engine oil filter housing cooler seal ring		\$	-	72.00
1pc	Engine oil filter housing pressure switch		\$	-	104.00
1pc	Engine timing bottom rail		\$	X	345.00
6pcs	Engine piston with ring kit	(Each \$805.00)	\$	-	4,830.00
7pair	Engine crankshaft main bearing	(Each \$205.00)	\$	-	1,435.00
6pcs	Engine crankshaft con rod	(Each \$422.00)	\$	-	2,532.00
6pair	Engine crankshaft con rod bearing	(Each \$191.00)	\$	-	1,146.00
1pc	Engine oil pump		\$	-	1,379.00
1pc	Engine oil pump timing chain		\$	-	207.00
1pc	Engine oil pump timing chain rail		\$	-	293.00
1pc	Engine oil pump timing chain plate		\$	-	25.00
1set	Engine bottom gasket kit		\$	-	431.00
1set	Engine oil sump bolt kit		\$	X	104.00
1pc	Engine oil sump sensor		\$	-	396.00
1pc	Engine oil sump drain plug		\$	X	21.00
1pc	Engine oil sump drain plug washer		\$	-	4.00
1pc	Engine starter motor		\$	X	759.00
1pc	Electric steering rack end pinion		\$	X	9,957.00
1pc	Automatic transmission gearbox assy		\$	X	15,540.00
	Sub total :		\$		39,580.00
	Less 10% discount :		\$		3,958.00
	B total :		\$		35,622.00
	Total amount for Page 2 :		\$		35,622.00

Tropical Tech Automobile Services

  
 (Authorised Signature)

# TROPICAL TECH AUTOMOBILE SERVICES

Blk 5032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Great American Insurance Company, Singapore Branch**  
 Attn : 3, Temasek Avenue, #16-01,  
 Centennial Tower,  
 Singapore 039190

Estimate bill : TT 02 / 18 / TP / 18

Registration No : SCZ7557S

Make / model : BMW 730Li (F02)

Office No :

Fax No :

Date 04 / 01 / 2018

Mileage :

**OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.**

**Special Net Items :**

7.5lts	Castrol Edge Synthetic Engine Oil (10W / 60)	S	30.00	\$ <del>WV</del> / 225.00	} R
1bte	BMW coolant			\$ <del>WV</del> / 39.00	
1pc	Banner AGM maintenance free 12V 90ah (900CCA) battery			\$ <del>X</del> 217.00	} H
	Programming, coding, transfer data to engine control unit			\$ <del>SA</del> 600.00	
1bte	Brake fluid			\$ <del>X</del> 26.00	} H
1bte	Air con 134a condenser oil treatment			\$ <del>WV</del> / 56.00	
1bte	Air con 134a compressor oil treatment			\$ <del>WV</del> / 56.00	} H
1bte	Filling air con 134a gas			\$ <del>WV</del> / 64.00	
	Conduct air con vacuum test			\$ <del>WV</del> / 26.00	} H
8lts	Automatic transmission oil	(Each \$23.00)		\$ <del>WV</del> / 184.00	
2lts	Rear axle oil	(Each \$23.00)		\$ <del>WV</del> / 46.00	} H
	C total :			\$ 2,149.00	
	Towing vehicle from Upper Changi Road to workshop.			\$ 120.00	
	Towing vehicle from workshop to Ang Mo Kio Auto Point (Cheng Hoe for Insurance e-filing)			\$ <del>check</del> 100.00	
	Remove and refit front bumper in order to facilitate repairs.			\$ <del>180</del> 200.00	
	Remove and renew air con 134a condenser, air con 134a compressor, air con blower motor, air con blower motor resistance, air con 134a expansion valve, air con 134a cooling coil.			\$ <del>500</del> 700.00	
	Remove and refit interior front dash-board in order to facilitate repairs.			\$ <del>280</del> 400.00	
	Lift up front LH passenger seat, front RH seat, rear passenger seat in order to facilitate repairs.			\$ <del>300</del> 800.00	
	Wash / clean / shampoo on interior car mat.			\$ <del>500</del> 800.00	
	Total amount for Page 3 :			\$ 5,269.00	

Tropical Tech Automobile Services

(Authorised Signature)

# TROPICAL TECH AUTOMOBILE SERVICES

Blk 5032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : Great American Insurance Company, Singapore Branch  
 Attn : 3, Temasek Avenue, #16-01,  
 Centennial Tower,  
 Singapore 039190

Estimate bill : TT 02 / 18 / TP / 18

Registration No : SCZ7557S

Make / model : BMW 730Li (F02)

Office No :  
 Fax No :

Date : 04 / 01 / 2018

Mileage :

**OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.**

Lift up engine assy in order to facilitate repairs.

S ~~800.00~~

Remove and renew engine oil, engine oil filter, engine air filter, battery, alternator, engine air mass, engine electronic throttle body, engine oil cap, engine valve cover, engine timing top plate, engine camshaft balancing gear, engine camshaft balancing gear plate, engine camshaft balancing gear plate bolt, engine valve seal (Inlet), engine valve seal (Exhaust), engine grinding valve gasket kit, engine cylinder head gasket, engine timing chain, engine timing chain tensioner, engine oil filter housing cooler seal ring, engine oil filter housing pressure switch, engine bottom rail, engine piston with ring, engine crankshaft main bearing, engine crankshaft con rod, engine crankshaft con rod bearing, engine oil pump, engine oil pump timing chain, engine oil timing chain plate, engine bottom gasket kit, engine oil sump bolt kit, engine oil sump sensor, pump timing chain rail, engine oil sump drain plug, engine oil sump drain plug washer, engine starter motor.

S 3,000.00

Remove and refit front under carriage in order to facilitate repairs.

S 600.00

Remove and renew electric steering rack and pinion.

S 400.00

Conduct wheel alignment test.

S 100.00

Remove and renew automatic transmission gear box, automatic transmission oil, rear axle oil.

S 800.00

Balance brought forward from Page 1

S 20,217.60

Balance brought forward from Page 2 :

S 35,622.00

Balance brought forward from Page 3 :

S 5,269.00

**Grand final amount :**

S 66,808.60

66,808.90

Tropical tech Automobile Services

Insured persons hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to Insurer's survey
- No illegal modification(s) is allowed
- Any supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

*Report*  
 To check mr of vehicle  
 EXCESS TRAT.  
 14w days.  
 11/1/2018  
 P/P Repairer  
 31/1/18

(Authorised Signature)



Javila

# TROPICAL TECH AUTOMOBILE SERVICES

Blk 3030 Ang Mo Kio Avenue 3 #01-201 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Great American Insurance Company**  
Attn : 3 Temasek Avenue  
#16-01 Centennial Tower  
Singapore 039190

Supplementary bill : TT 02 / 18 / OD / TP

Registration No : SCZ7557S

Office No : Motor Claims Department  
Fax No : 68046000  
62352616

Make / model : BMW 730Li (F02)

Mileage : \_\_\_\_\_ Date 04 / 01 / 2018

**OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.**

Supplementary spare parts items :

1pc	Radiator ✓		\$	1,484.00	NN
1pc	Engine brake vacuum pump ✗		\$	<del>702.00</del>	NN
1pc	Engine valve cover breather hose ✗		\$	<del>122.00</del>	NN
1pc	Engine inlet manifold ✗		\$	<del>1,080.00</del>	XX
1pc	Engine cylinder head ✓		\$	<del>5,935.00</del>	R ✗
12pcs	Engine inlet valve ✓	(Each \$71.00)	\$	852.00	
12pcs	Engine exhaust valve ✓	(Each \$87.00)	\$	1,044.00	NE
1pc	Engine oil filter housing cooler ✓		\$	486.00	
1pc	Engine block solenoid switch ✓		\$	380.00	
1pc	Engine oil sump sensor ✗		\$	387.00	NE
1set	Interior front carnet ✓		\$	1,200.00	
1set	Interior rear carnet ✓		\$	1,150.00	
	Sub total :		\$	14,822.00	
	Less 10% discount :		\$	1,482.20	
	A total :		\$	13,339.80	

11277.50

Special net items :

Skimming and balancing engine crankshaft ✓		\$	400	<del>500.00</del>	NE
B total :		\$		500.00	

**Grand final amount :**

\$ 13,839.80

Tropical Tech Automobile Services

  
  
 \_\_\_\_\_  
 (Authorised Signature)

# TROPICAL TECH AUTOMOBILE SERVICES

Blk 5032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : Great American Insurance Company, Singapore Branch  
 Attn : 3, Temasek Avenue, #16-01,  
 Centennial Tower,  
 Singapore 039190

Estimate bill : TT 02 / 18 / TP / 18

Registration No : SCZ7557S

Make / model : BMW 730Li (F02)

Office No :

Fax No :

Date : 04 / 01 / 2018

Mileage :

**OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.**

1pc	Air con 134a condenser		\$	X	867.00
1pc	Air con 134a compressor		\$	X	1,465.00
1pc	Air con blower motor		\$	X	1,277.00
1pc	Air con blower motor resistance		\$	X	511.00
1pc	Air con 134a expansion valve		\$	X	190.00
1pc	Air con 134a cooling coil		\$	X	1,138.00
1pc	Engine oil filter with 'O' ring		\$	—	23.00
1pc	Engine air filter		\$	—	63.00
1pc	Alternator		\$	X	2,476.00
1pc	Engine air mass		\$	—	776.00
1pc	Engine electronic throttle body ✓		\$	?	1,620.00
1pc	Engine control unit		\$	X	4,680.00
1pc	Engine oil cap		\$	X	50.00
1pc	Engine valve cover		\$	X	1,149.00
1pc	Engine timing top plate ✓		\$	X	171.00
2pcs	Engine cam shaft balancing gear	(Each \$1725.00)	\$	X	3,450.00
2pcs	Engine cam shaft balancing gear plate	(Each \$90.00)	\$	X	180.00
2pcs	Engine cam shaft balancing gear plate bolt	(Each \$25.00)	\$	X	50.00
1set	Engine valve seal (Inlet)		\$	—	205.00
1set	Engine valve seal (Exhaust)		\$	—	205.00
1set	Engine grinding valve gasket kit		\$	—	1,035.00
1pc	Engine cylinder head gasket		\$	—	332.00
1pc	Engine timing chain ✓		\$	X	380.00
1pc	Engine timing chain tensioner ✓		\$	X	276.00
	Sub total :		\$		22,464.00
	Less 10% discount :		\$		2,246.40
	A total :		\$		20,217.60
Total amount for Page 1 :			\$		20,217.60

Tropical Tech Automobile Services

(Authorised Signature)

# TROPICAL TECH AUTOMOBILE SERVICES

Blk 5032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Great American Insurance Company, Singapore Branch**  
 Attn : 3, Temasek Avenue, #16-01,  
 Centennial Tower,  
 Singapore 039190

Estimate bill : TT 02 / 18 / TP 18

Registration No : SCZ7557S

Make / model : BMW 730i (F02)

Office No :  
 Fax No :

Date : 04 / 01 / 2018

Mileage :

## OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.

1pc	Engine oil filter housing cooler seal ring		\$	77.00
1pc	Engine oil filter housing pressure switch		\$	104.00
1pc	Engine timing bottom rail		\$	345.00
6pcs	Engine piston with ring kit ✓	(Each \$805.00)	\$	4,830.00
7pair	Engine crankshaft main bearing ✓	(Each \$205.00)	\$	1,435.00
6pcs	Engine crankshaft con rod ✓	(Each \$422.00)	\$	2,532.00
6pair	Engine crankshaft con rod bearing ✓	(Each \$191.00)	\$	1,146.00
1pc	Engine oil pump ✓		\$	1,379.00
1pc	Engine oil pump timing chain ✓		\$	307.00
1pc	Engine oil pump timing chain rail ✓		\$	293.00
1pc	Engine oil pump timing chain plate ✓		\$	25.00
1set	Engine bottom gasket kit		\$	131.00
1set	Engine oil sump bolt kit		\$	104.00
1pc	Engine oil sump sensor		\$	396.00
1pc	Engine oil sump drain plug ✗		\$	21.00
1pc	Engine oil sump drain plug washer		\$	4.00
1pc	Engine starter motor ✗		\$	759.00
1pc	Electric steering rack end pinion ✗		\$	9,957.00
1pc	Automatic transmission gearbox assy ✗		\$	15,540.00
	Sub total :		\$	39,580.00
	Less 10% discount :		\$	3,958.00
	B total :		\$	35,622.00
	Total amount for Page 2 :		\$	35,622.00

Tropical Tech Automobile Services

  
 (Authorised Signature)

# TROPICAL TECH AUTOMOBILE SERVICES

Blk 5032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : Great American Insurance Company, Singapore Branch  
 Attn : 3, Temasek Avenue, #16-01,  
 Centennial Tower,  
 Singapore 039190

Estimate bill : TT 02 / 18 / TP / 18

Registration No : SCZ7557S

Make / model : BMW 730Li (F02)

Office No :  
 Fax No :

Date : 04 / 01 / 2018

Mileage :

**OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.**

**Special Net Items :**

7.5lts	Castrol Edge Synthetic Engine Oil (10W / 60)	\$	30.00	\$ <del>42</del> ✓	325.00
1bte	BMW coolant			\$ <del>42</del> ✓	39.00
1pc	Banner AGM maintenance free 12V 90ah (900CCA) battery			\$ <del>X</del> ✓	817.00
	Programming, coding, transfer data to engine control unit			\$ <del>550</del> ✓	600.00
1bte	Brake fluid			\$ <del>X</del> ✓	36.00
1bte	Air con 134a condenser oil treatment			\$ <del>52</del> ✓	56.00
1bte	Air con 134a compressor oil treatment			\$ <del>52</del> ✓	56.00
	Filling air con 134a gas			\$ <del>52</del> ✓	54.00
	Conduct air con vacuum test			\$ <del>52</del> ✓	26.00
8lts	Automatic transmission oil	(Each \$23.00)		\$ <del>52</del> ✓	181.00
2lts	Rear axle oil	(Each \$23.00)		\$ <del>52</del> ✓	46.00
	C total :			\$	2,149.00
	Towing vehicle from Upper Changi Road to workshop.			\$	120.00
	Towing vehicle from workshop to Ang Mo Kio Auto Point (Cheng Hoe for Insurance e-filing)			\$ sheet	100.00
	Remove and refit front bumper in order to facilitate repairs.			\$ 180	200.00
	Remove and renew air con 134a condenser, air con 134a compressor, air con blower motor, air con blower motor resistance, air con 134a expansion valve, air con 134a cooling coil.			\$ 520	200.00
	Remove and refit interior front dash-board in order to facilitate repairs.			\$ 280	100.00
	Lift up front LH passenger seat, front RH seat, rear passenger seat in order to facilitate repairs.			\$ 300	100.00
	Wash / clean / shampoo on interior car mat.			\$ 500	100.00
	Total amount for Page 3 :			\$	5,269.00

Tropical Tech Automobile Services

(Authorised Signature)

# TROPICAL TECH AUTOMOBILE SERVICES

Blk 3032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

TEL : 6481 7773 / 6481 1403 / FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : Great American Insurance Company, Singapore Branch  
 Attn : 3, Temasek Avenue, #16-01,  
 Centennial Tower,  
 Singapore 039190

Estimate bill : TT 02 / 18 / TP 18

Registration No : SCZ7557S

Make / model : BMW 730Li (F07)

Office No :  
 Fax No :

Date : 04 / 01 / 2018

Mileage :

**OWN DAMAGED CLAIMS FOR TRAFFIC VEHICLE BEARING REGISTRATION NO : SCZ7557S BEDOK NORTH AVENUE 4 AND UPPER CHANGI ROAD JUNCTION ON 08 JANUARY 2018 AT ABOUT 0906JRS.**

Lift up engine assy in order to facilitate repairs.

\$ ~~2800.00~~ 2800.00

Remove and renew engine oil, engine oil filter, engine air filter, battery, alternator, engine air mass, engine electronic throttle body, engine oil cap, engine valve cover, engine timing top plate, engine camshaft balancing gear, engine camshaft balancing gear plate, engine camshaft balancing gear plate bolt, engine valve seal (Inlet), engine valve seal (Exhaust), engine grinding valve gasket kit, engine cylinder head gasket, engine timing chain, engine timing chain tensioner, engine oil filter housing cooler seal ring, engine oil filter housing pressure switch, engine bottom rail, engine piston with ring, engine crankshaft main bearing, engine crankshaft con rod, engine crankshaft con rod bearing, engine oil pump, engine oil pump timing chain, engine oil timing chain plate, engine bottom gasket kit, engine oil sump bolt kit, engine oil sump sensor, pump timing chain rail, engine oil sump drain plug, engine oil sump drain plug washer, engine starter motor.

\$ 3,000.00

Remove and refit front under carriage in order to facilitate repairs.

\$ 600.00

Remove and renew electric steering rack end pinion.

\$ 400.00

Conduct wheel alignment test.

\$ 100.00

Remove and renew automatic transmission gearbox, automatic transmission oil, rear axle oil.

\$ 800.00

Balance brought forward from Page 1 :

\$ 20,217.60

Balance brought forward from Page 2 :

\$ 35,677.00

Balance brought forward from Page 3 :

\$ 5,269.00

**Grand final amount :**

**\$ 66,808.60**

Tropical tech Automobile Services

  
 (Authorised Signature)

*Revert  
 To check mr of vehicle  
 EXCESS TRAF.  
 14w days.  
 11/1/2018  
 P/P Repur*

## Janice Lee (LKKAuto)

---

**From:** William Tan <tanlihao74@gmail.com>  
**Sent:** Thursday, November 22, 2018 5:17 PM  
**To:** Janice Lee (LKKAuto); William Tan  
**Subject:** Re: SCZ 7557S

I agreed the amount.

On Thu, 22 Nov 2018 at 4:42 PM, Janice Lee (LKKAuto) <[JaniceLee@lkkauto.com](mailto:JaniceLee@lkkauto.com)> wrote:

Dear Sir,

Kindly confirm L/S \$22K @ 14 days.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

GREAT AMERICAN INSURANCE COMPANY      Ref : CS/GAI18000554/M1rd3e2

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Date : 28-11-2018



Code : GAI

### 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SCZ 7557S
Policy No.	MOMVP000000438-01-000	Coverage (\$)	0.00
Claim No.	CLMOMVP000000517	Excess (\$)	0.00
Assign From	KELVYNA NGIAN	Assign Date	09/01/2018

### 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 730LI	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBAYE22020DZ20926	Colour	BLUE
Odometer	93217	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R20	MICHELIN	8 mm
L/H Front Tyre	245/40 R20	MICHELIN	8 mm
R/H Rear Tyre	275/35 R20	MICHELIN	8 mm
L/H Rear Tyre	275/35 R20	MICHELIN	8 mm

### 4. Description of Damages

THE VEHICLE RECOVERED FROM FLOOD. MANY ELECTRICAL & MECHANISM PARTS FOUND DAMAGED AND CONTAMINATED BY FLOOD WATER AT THE TIME OF INSPECTION.

### 5. General Information

Accident Date	08/01/2017	Inspection Date	11/01/2018
Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.		

### 5a. Remarks

A)THE MARKET VALUE IS S\$150,000.00(EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>14 Working Days</b>
-------------------------------------	------------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCZ 7557S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	AIR CON 134A CONDENSER	NOT NECESSARY	862.00	-
1	AIR CON 134A COMPRESSOR	NOT NECESSARY	1,465.00	-
1	AIR CON BLOWER MOTOR	NOT NECESSARY	1,277.00	-
1	AIR CON BLOWER MOTOR RESISTANCE	NOT NECESSARY	511.00	-
1	AIR CON 134A EXPANSION VALVE	NOT NECESSARY	190.00	-
1	AIR CON 134A COOLING COIL	NOT NECESSARY	1,138.00	-
1	ENGINE OIL FILTER WITH 'O' RING	NECESSARY	23.00	23.00
1	ENGINE AIR FILTER	NECESSARY	63.00	63.00
1	ALTERNATOR	NOT NECESSARY	2,426.00	-
1	ENGINE AIR MASS	NECESSARY	776.00	776.00
1	ENGINE ELECTRONIC THROTTLE BODY	NECESSARY	1,620.00	1,620.00
1	ENGINE CONTROL UNIT	NOT NECESSARY	4,680.00	-
1	ENGINE OIL CAP	NOT NECESSARY	50.00	-
1	ENGINE VALVE COVER	NOT NECESSARY	1,149.00	-
1	ENGINE TIMING TOP PLATE	NOT NECESSARY	121.00	-
2	ENGINE CAM SHAFT BALANCING GEAR @\$1725.00	NOT NECESSARY	3,450.00	-
2	ENGINE CAM SHAFT BALANCING GEAR PLATE @\$90.00	NOT NECESSARY	180.00	-
2	ENGINE SHAFT BALANCING GEAR PLATE BOLT @\$25.00	NOT NECESSARY	50.00	-
1	SET ENGINE VALVE SEAL (INLET)	NECESSARY	205.00	205.00
1	SET ENGINE VALVE SEAL (EXHAUST)	NECESSARY	205.00	205.00
1	SET ENGINE GRINDING VALVE GASKET KIT	NECESSARY	1,035.00	1,035.00
1	ENGINE CYLINDER HEAD GASKET	NECESSARY	332.00	332.00
1	ENGINE TIMING CHAIN	NECESSARY	380.00	380.00
1	ENGINE TIMING CHAIN TENSIONER	NECESSARY	276.00	276.00
1	ENGINE OIL FILTER HOUSING COOLER SEAL RING	NECESSARY	72.00	72.00
1	ENGINE OIL FILTER HOUSING PRESSURE SWITCH	NECESSARY	104.00	104.00
1	ENGINE TIMING BOTTOM RAIL	NECESSARY	345.00	345.00
6	ENGINE PISTON WITH RING KIT @\$805.00	NECESSARY	4,830.00	4,830.00
7	PAIR ENGINE CRANKSHAFT MAIN BEARING @\$205.00	NECESSARY	1,435.00	1,435.00
6	ENGINE CRANKSHAFT CON ROD @\$422.00	NECESSARY	2,532.00	2,532.00

Report Ref No. CS/GAI18000554/M1rd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
6	PAIR ENGINE CRANKSHAFT CON ROD BEARING @\$191.00	NECESSARY	1,146.00	1,146.00
1	ENGINE OIL PUMP	NECESSARY	1,379.00	1,379.00
1	ENGINE OIL PUMP TIMING CHAIN	NECESSARY	207.00	207.00
1	ENGINE OIL PUMP TIMING CHAIN RAIL	NECESSARY	293.00	293.00
1	ENGINE OIL PUMP TIMING CHAIN PLATE	NECESSARY	25.00	25.00
1	ENGINE BOTTOM GASKET KIT	NECESSARY	431.00	431.00
1	SET ENGINE OIL SUMP BOLT KIT	NOT NECESSARY	104.00	-
1	ENGINE OIL SUMP SENSOR	NECESSARY	396.00	396.00
1	ENGINE OIL SUMP DRAIN PLUG	NOT NECESSARY	21.00	-
1	ENGINE OIL SUMP DRAIN PLUG WASHER	NECESSARY	4.00	4.00
1	ENGINE STARTER MOTOR	NOT NECESSARY	759.00	-
1	ELECTRIC STEERING RACK END PINION	NOT NECESSARY	9,957.00	-
1	AUTOMATIC TRANSMISSION GEARBOX ASSY	NOT NECESSARY	15,540.00	-
1	RADIATOR (ADDITIONAL)	NOT NECESSARY	1,484.00	-
1	ENGINE BRAKE VACUUM PUMP (ADDITIONAL)	NOT NECESSARY	702.00	-
1	ENGINE VALVE COVER BREATHER HOSE (ADDITIONAL)	NOT NECESSARY	122.00	-
1	ENGINE INLET MANIFOLD (ADDITIONAL)	NOT NECESSARY	1,080.00	-
1	ENGINE CYLINDER HEAD (ADDITIONAL)	TO REPAIR SEE LABOUR	5,935.00	-
12	ENGINE INLET VALVE @\$71.00 (ADDITIONAL)	NECESSARY	852.00	852.00
12	ENGINE EXHAUST VALVE @\$87.00 (ADDITIONAL)	NECESSARY	1,044.00	1,044.00
1	ENGINE OIL FILTER HOUSING COOLER (ADDITIONAL)	NECESSARY	486.00	486.00
1	ENGINE BLOCK SOLENOID SWITCH (ADDITIONAL)	NECESSARY	380.00	380.00
1	ENGINE OIL SUMP SENSOR (ADDITIONAL)	NECESSARY	387.00	387.00
1	SET INTERIOR FRONT CARMET (ADDITIONAL)	NECESSARY	1,200.00	1,200.00
1	SET INTERIOR REAR CARMET (ADDITIONAL)	NECESSARY	1,150.00	1,150.00
	LESS 10% DISCOUNT		-7,686.60	-2,361.30
			69,179.40	21,251.70
	<b>SPECIAL NETT ITEMS</b>			
1	7.5 LTS CASTROL EDGE SYNTHETIC ENGINE OIL (10W / 60) @\$30.00 (SN)	NECESSARY	225.00	225.00
1	BTE BMW COOLANT (SN)	NECESSARY	39.00	39.00

Report Ref No. CS/GAI18000554/M1rd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BANNER AGGM MAINTENANCE FREE 12V 90AH (900CCA) BATTERY (SN)	NOT NECESSARY	817.00	-
1	PROGRAMMING, CODING, TRANSFER DATA TO ENGINE CONTROL UNIT (SN)	NECESSARY	600.00	300.00
1	BTE BRAKE FLUID (SN)	NOT NECESSARY	36.00	-
1	BTE AIR CON 134A CONDENSER OIL TREATMENT (SN) }	NECESSARY	56.00	120.00
1	BTE AIR CON 134A COMPRESSOR OIL TREATMENT (SN) }		56.00	-
1	FILLING AIR CON 134A GAS (SN) }		64.00	-
1	CONDUCT AIR CON VACUUM TEST (SN) }		26.00	-
8	LTS AUTOMATIC TRANSMISSION OIL @\$23.00 (SN)	NECESSARY	184.00	184.00
2	LTS REAR AXLE OIL @\$23.00 (SN)	NECESSARY	46.00	46.00
			2,149.00	914.00
	<b>LABOUR</b>			
	SKIMMING AND BALANCING ENGINE CRANKSHAFT. (ADDITIONAL)		500.00	400.00
	TOWING VEHICLE FROM UPPER CHANGI ROAD TO WORKSHOP.		120.00	120.00
	TOWING VEHICLE FROM WORKSHOP TO ANG MO KIO AUTO POINT (CHENG HOE FOR INSURANCE E-FILING)	NOT NECESSARY	100.00	-
	REMOVE AND REFIT FRONT BUMPER IN ORDER TO FACILITATE REPAIRS.		200.00	180.00
	REMOVE AND RENEW AIR CON 134A CONDENSER, AIR CON 134A COMPRESSOR, AIR CON BLOWER MOTOR, AIR CON BLOWER MOTOR RESISTANCE, AIR CON 134A EXPANSION VALVE, AIR CON 134A COOLING COIL.		700.00	500.00
	REMOVE AND REFIT INTERIOR FRONT DASH-BOARD IN ORDER TO FACILITATE REPAIRS.		400.00	280.00
	LIFT UP FRONT LH PASSENGER SEAT, FRONT RH SEAT, REAR PASSENGER SEAT IN ORDER TO FACILITATE REPAIRS.		800.00	300.00
	WASH / CLEAN / SHAMPOO ON INTERIOR CAR MAT.		800.00	500.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND RENEW ENGINE OIL, ENGINE OIL FILTER, ENGINE AIR FILTER, BATTERY, ALTERNATOR, ENGINE AIR MASS, ENGINE ELECTRONIC THROTTLE BODY, ENGINE OIL CAP, ENGINE VALVE COVER, ENGINE TIMING TOP PLATE, ENGINE CAMSHAFT BALANCING GEAR, ENGINE CAMSHAFT BALANCING GEAR PLATE, ENGINE CAMSHAFT BALANCING GEAR PLATE BOLT, ENGINE VALVE SEAL (INLET), ENGINE VALVE SEAL (EXHAUST), ENGINE GRINDING VALVE GASKET KIT, ENGINE CYLINDER HEAD GASKET, ENGINE TIMING CHAIN, ENGINE TIMING CHAIN TENSIONER )		3,000.00	2,800.00
	ENGINE OIL FILTER HOUSING COOLER SEAL RING, ENGINE OIL FILTER HOUSING PRESSURE SWITCH, ENGINE BOTTOM RAIL, ENGINE PISTON WITH RING, ENGINE CRANKSHAFT MAIN BEARING, ENGINE CRANKSHAFT CON ROD, ENGINE CRANKSHAFT CON ROD BEARING, ENGINE OIL PUMP, ENGINE OIL PUMP TIMING CHAIN, ENGINE OIL TIMING CHAIN PLATE, ENGINE BOTTOM GASKET KIT, ENGINE OIL SUMP BOLT KIT, ENGINE OIL SUMP SENSOR, PUMP TIMING CHAIN RAIL, ENGINE OIL SUMP DRAIN PLUG, ENGINE OIL SUMP DRAIN PLUG WASHER, ENGINE STARTER MOTOR. )		-	-
	INCLUSIVE OF THE REPAIR OF ENGINE CYLINDER HEAD. )		-	-
	LIFT UP ENGINE ASSY IN ORDER TO FACILITATE REPAIRS. )		800.00	-
	REMOVE AND RENEW AUTOMATIC TRANSMISSION GEARBOX, AUTOMATIC TRANSMISSION OIL, REAR AXLE OIL. )		800.00	-
	REMOVE AND REFIT FRONT UNDER CARRIAGE IN ORDER TO FACILITATE REPAIRS. )		600.00	450.00
	REMOVE AND RENEW ELECTRIC STEERING RACK END PINION. )		400.00	-
	CONDUCT WHEEL ALIGNMENT TEST.		100.00	80.00
			-	-
			-	-
			9,320.00	5,610.00
	<b>GRAND TOTAL</b>		<b>80,648.40</b>	<b>27,775.70</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>22,000.00</b>
	<b>LESS EXCESS</b>			<b>-400.00</b>



NETT LIABILITY			21,600.00
----------------	--	--	-----------

Report Ref No. CS/GAI18000554/M1rd3e2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.