


















PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0451-16-N51

31 October 2016

ACCIDENT VEHICLE SURVEY REPORT

Syed Salim Bin Ahmad Almashor
15 Elias Green #02-03
Singapore 519966

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SJD2017A	<i>Odometer:</i>	268194km
<i>Make & Model:</i>	Mitsubishi Lancer 1.5 A	<i>Colour:</i>	Black
<i>Chassis number:</i>	JMYSRCY2A8U004691	<i>Date of accident:</i>	16/04/2016
<i>Year of Regn.:</i>	13/03/2008	<i>Date inspected:</i>	21/04/2016
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 409849		

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "**Without Prejudice**" basis.

