



19	BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 79.00	\$ 79.00	-
20	BOOTLID LOWER LOCK <i>new</i>	1	\$ 42.00	\$ 42.00	+
21	BOOTLID WEATHERSTRIP <i>at</i>	1	\$ 157.00	\$ 157.00	-
22	BOOTLID REFLECTOR <i>cut</i>	2	\$ 290.00	\$ <del>580.00</del>	- 242.80
23	REAR BUMPER <i>Delaid</i>	1	\$ 563.00	\$ 563.00	-
24	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.00	\$ <u>124.00</u>	64
25	REAR BUMPER BRACKET <i>Dented</i>	2	\$ 89.00	\$ <del>178.00</del>	- 86.40
26	TAILLAMP <i>cut</i>	2	\$ 375.00	\$ <del>750.00</del>	- 579.20
27	TAILLAMP PANEL <i>Dented</i>	2	\$ 456.00	\$ <u>912.00</u>	762.40
28	TAILLAMP LOWER APRON PANEL <i>Delaid</i>	2	\$ 161.50	\$ <u>323.00</u>	179.20
29	TAILLAMP LOWER APRON PANEL RIVET <i>new</i>	10	\$ 8.50	\$ 85.00	-
30	REAR FENDER <i>Repair</i>	2	\$ 795.00	\$ 1,590.00	+
31	REAR FENDER INNER COWLING <i>new</i>	2	\$ 59.00	\$ 118.00	+
32	REAR FENDER INNER TRIM <i>new</i>	2	\$ 176.00	\$ 352.00	2
33	REAR FENDER AIR VENT <i>new</i>	2	\$ 78.00	\$ 156.00	+
34	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 169.00	\$ 169.00	+
35	REAR END PANEL <i>Distorted</i>	1	\$ 708.00	\$ 708.00	-
36	REAR END PANEL TOP GARNISH <i>Delaid</i>	1	\$ 126.00	\$ 126.00	-
37	REAR FLOOR PANEL <i>Repair</i>	1	\$ 899.00	\$ 899.00	+
38	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 121.00	\$ 121.00	2
39	REAR FLOOR PANEL SIDE BOARD <i>new</i>	2	\$ 59.00	\$ 118.00	+
40	REAR EXHAUST PIPE <i>new</i>	1	\$ 955.20	\$ <u>955.20</u>	X

TOTAL PRICE \$ 16,135.60  
 LESS 25% \$ 4,033.90  
 SUB TOTAL PRICE \$ 12,101.70

902530  
 6768-97

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	-
2	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
3	FRONT BUMPER UNDER COVER GARNISH CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
4	FRONT GRILLE CLIP(SET) <i>new</i>	1	\$ 6.50	\$ 6.50	-
5	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	30
6	BOOTLID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	BOOTLID LOGO GARNISH CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
8	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
9	TAILLAMP CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
10	TAILLAMP PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
11	REAR FENDER SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+

12	REAR FENDER COWLING CLIPS(SET) <i>MCW</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
13	REAR FENDER INNER TRIM CLIPS(SET) <i>MCW</i>	1	\$ 20.00	\$ 20.00	<i>-</i>
14	REAR FENDER INNER PANEL SEALANT <i>MCW</i>	2	\$ 80.00	\$ 160.00	<i>+</i>
15	REAR END PANEL TOP GARNISH CLIPS(SET) <i>MCW</i>	1	\$ 22.00	\$ 22.00	<i>-</i>
16	REAR END PANEL INSULATION SEAL <i>MCW</i>	1	\$ 150.00	\$ <del>150.00</del>	<i>60</i>
17	REAR FLOOR PANEL INSULATION SEAL <i>MCW</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
18	REVERSE SENSOR <i>Payd</i>	1	\$ 220.00	\$ <del>220.00</del>	<i>200</i>
			<b>TOTAL</b>	<b>\$ 1,188.50</b>	

*448.50*

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	<i>400</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>600</i>	
3	WIRING CHECK	\$ 150.00	<i>30</i>	
4	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>X</i>	
<b>TOTAL:</b>		<b>\$ 2,210.00</b>		

*1030*

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	<i>1000</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>1000</i>	
3	TUFF COAT	\$ 350.00	<i>60</i>	
4	WIRING CHECK	\$ 150.00	<i>30</i>	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO	\$ 250.00	<i>60</i>	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>	
7	TRANSFER BOOTLID MECHANISM	\$ 80.00	<i>-</i>	
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>X</i>	
9	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	<i>X</i>	
10	TO REMOVE AND REFIX REAR EXHAUST PIPE	\$ 350.00	<i>X</i>	

*2280*

*Nett Value: 9.5k*

**TOTAL \$4,460.00**

**TOTAL PARTS COST** : \$ 13,290.20  
**TOTAL LABOUR COST** : \$ 6,670.00  
**TOTAL REPAIR COST** : \$ 19,960.20

*Adrian Lj* *toled: 1052747*  
*09/01/18* *w/s: 84K.*  
*h/s 12 exp.*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s)
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**APPROVED DETAILS**

EXCESS :

NO. OF WORKING DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :