CITY CAB PTE LTD REPAIR ESTIMATE*

VEHICLE NO: SHA 89U

DATE 9/1/2018



MAKE

LKK-

MODEL	: MERCEDES BENZ	Let					,
Qty	Parts Description/ Labour	Type		Unit Price		Amount	
	Rear Bumper distrans				\$	1,510.00	~
	Rear Bumper Reinforcement				\$	1,150.00	×
	Rear Bumper Bracket Lower (LH/RH)		\$	135.00	\$	270.00	×
	Rear Bumper Bracket Top (LH/RH)		\$	125.00	\$	250.00	×
	Rear Bumper Retainer Mounting (LH/RH)		\$	115.00	\$	230.00	X
	SUB TOTAL				\$	3,410.00	
-	LESS 20%				\$	682.00	
	DISCOUNTED TOTAL				\$	2,728.00	-
					0	220.00	Nott.
	Rear Bumper Sensor Dea				\$	388.00	Nett -
	Rear Bumper Rubber Mat Ake				\$	50.00	Nett -
					\$	438.00	-
	9				•	430.00	1
	Labour Charge						
	Panel Beating				\$	400.00	3001
	Spray Painting Charge				\$	250.00	2001
	Tuff Kote				\$	50.00	HM
	Remove/Refix Reverse Sensor				\$	120.00	100
	TOTAL LABOUR				\$	820.00	
	ESTIMATE TOTAL				\$	3,986.00	
	09/01/2018 P 143m						
	09/01/2018 @ 14300 HA Antru LISAN 2 days.						
	and America						
	2 LISAN						
	my 2 days.						
	3164						
	2Kt husb						
	0						
	l						
	This is an initial estimate based on a visual inspection of the	le above v	hicle	The final renair			1
	quantum will be prepared after the vehicle is surveyed by						
	by the insurance company.	a motor bu	,	. арроппов			
	by the filsurance company.						_