



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

AXA/AIG(SLK6894C)
DOA: 03/01/2018@1630

AIG ASIA PACIFIC INSURANCE PTE LTD

10/01/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SGB 1889 C - TOYOTA COROLLA 1.6
CHASSIS NO: MR053ZEC107107703 (2005)

1 pc	Front fender LH	\$ 184.80
	LESS 25%	\$ 46.20
		<u>\$ 138.60</u>
	Remove and replace the above.	\$ 120.00
	Putty and respray front fender LH	\$ 280.00
		<u>\$ 538.60</u>
	ADD 7% GST	\$ 37.70
		<u><u>\$ 576.30</u></u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....