

Date : 10/01/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
: AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	RADIATOR COOLANT	30.00	ner
1	FRONT NUMBER PLATE	35.00	dd
1	WINDSCREEN SEALANT	60.00	ner
1	IU STICKER	10.00	ner
1	FRONT TYRE LH	480.00	ny
1	FRONT TYRE RH	480.00	ny
1	REPAIR - FRONT SPORT RIM LH	150.00	ny
	Sub Total	1245.00	

Labour & Misc

Date : 10/01/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
: AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	LABOUR TO CARRY OUT FRONT REPAIR	1,000.00	900 ✓
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	✓
	TO SPRAY PAINT ON AFFECTED AREAS	1,000.00	900 ✓
	TO CONDUCT CHASSIS ALIGNMENT	300.00	200 photo.
	TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS	150.00	120 ✓
	TO REMOVE & RENEW FRT UNDERCARRIAGE LH TO ASSIST REPAIR	180.00	X 120 & m
	TO REMOVE & RENEW FRT UNDERCARRIAGE RH TO ASSIST REPAIR	180.00	120 ✓
	TO REMOVE & RENEW FRT CROSSMEMBER TO ASSIST REPAIR	300.00	7.200 photo.

Date : 10/01/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
AXA INSURANCE PTE LTD
Certificate No : GA273348 Accident Date : 08/01/2018
Vehicle No : SKE-7336-D Make & Model : MERCEDES BENZ E 250CGI

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO REMOVE & INSTALL FRONT WINDSCREEN GLASS	150.00	120 ✓
	TO REMOVE & INSTALL DASH BOARD COMPARTMENT	350.00	200 ✓
	TO REMOVE & RENEW AIR BAG COMPONENTS TO FACILITATE REPAIR	200.00	100 ✓
	TO RESET AIR BAG WARNING LIGHT	300.00	150 ✓
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	100.00	80 ✓
	Sub Total	4245.00	

Remarks:

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SUB TOTAL 36,164.00
GST 7.0 % 2,531.48
TOTAL 38,695.48

Surveyor's name: Tan Jiah 97495749 Rent Ex \$600.
Principal's name: TAN KWEE LIM Resurvey before paint 12 days.
Survey Date & Time: 11/1/18 @ 1500 *To check repair limits
suu @ lkkauto.com.
29 034

PAGE: 15

ETHOZ

FINALIZATION REPORT

Date : 26/02/2018
To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<u>List Item</u>			
1	REAR SEAT BELT UPPER GARNISH LH	310.00	310.00
1	REAR SEAT BELT UPPER GARNISH RH	310.00	310.00
1	ENGINE MOUNTING LH	250.00	125.00
1	ENGINE MOUNTING RH	250.00	125.00
1	WIPER TANK	220.00	220.00
1	WIPER TANK MOTOR	100.00	100.00
1	FRONT SEAT BELT LH	840.00	840.00
1	FRONT SEAT BELT RH	840.00	840.00
1	FRONT BONNET	1150.00	1150.00
1	FRONT BONNET HINGE LH	80.00	80.00
1	FRONT BONNET HINGE RH	80.00	80.00
1	FRONT BONNET INSULATOR	140.00	140.00
10	FRONT BONNET INSULATOR CLIP	40.00	40.00
1	FRONT BONNET ABSORBER LH	65.00	65.00

4425

PAGE : 1



Date : 26/02/2018
To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT BONNET ABSORBER RH	65.00	65.00
1	FRONT BONNET ACTUATOR LH	210.00	210.00
1	FRONT BONNET ACTUATOR RH	210.00	210.00
1	FRONT BONNET LOCK CABLE	65.00	65.00
1	FRONT BONNET TOP SPRING LH	12.00	12.00
1	FRONT BONNET TOP SPRING RH	12.00	12.00
1	FRONT BONNET STRICKER LH	18.00	18.00
1	FRONT BONNET STRICKER RH	18.00	18.00
1	FRONT BONNET LOCK CENTRE (UPPER)	40.00	40.00
1	FRONT BONNET LOCK LH (LOWER)	38.00	38.00
1	FRONT BONNET LOCK RH (LOWER)	38.00	38.00
1	FRONT BONNET LOGO	37.00	37.00
1	FRONT FENDER LH RESTORE	0.00	0.00
1	FRONT FENDER RH	480.00	480.00
2	FRONT FENDER EMBLEM LH / RH	70.00	70.00

1313

PAGE : 2



Date : 26/02/2018
To : AXA INSURANCE PTE LTD
Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
Insured By : AXA INSURANCE PTE LTD
Certificate No : GA273348 Accident Date : 08/01/2018
Vehicle No : SKE-7336-D Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAIL ~~SE~~ Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
2	FRONT FENDER CHROME MOULDING LH / RH	44.00	44.00
1	FRONT FENDER INNER SHIELD RH (FRT)	92.00	92.00
1	FRONT FENDER INNER SHIELD RH (REAR)	90.00	90.00
10	FRONT FENDER INNER SHIELD CLIPS	30.00	30.00
1	FRONT GRILLE	600.00	600.00
1	FRONT GRILLE LOGO	28.00	28.00
1	FRONT GRILLE MOUNTING	15.00	15.00
1	HEADLAMP LH	1500.00	1500.00
1	HEADLAMP RH	1500.00	1500.00
1	HEADLAMP BULB RH (HID)	200.00	200.00
1	HEADLAMP HID ECU	550.00	550.00
1	HEADLAMP PANEL LH	138.00	0.00
1	HEADLAMP PANEL RH	138.00	138.00

4787

PAGE : 3



Date : 26/02/2018
To : AXA INSURANCE PTE LTD
Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
Insured By : AXA INSURANCE PTE LTD
Certificate No : GA273348 Accident Date : 08/01/2018
Vehicle No : SKE-7336-D Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	HEADLAMP LOWER PANEL LH	30.00	0.00
1	HEADLAMP LOWER PANEL RH	30.00	30.00
1	HEADLAMP PANEL SEAL LH	25.00	0.00
1	HEADLAMP PANEL SEAL RH	25.00	25.00
1	HEADLAMP NOZZLE JET LH	110.00	0.00
1	HEADLAMP NOZZLE JET RH	110.00	110.00
1	HEADLAMP NOZZLE COVER LH	38.00	0.00
1	HEADLAMP NOZZLE COVER RH	38.00	38.00
1	HEADLAMP NOZZLE HOSE	32.00	32.00
1	FRONT BUMPER	780.00	780.00
10	FRONT BUMPER CLIPS	50.00	50.00
1	FRONT BUMPER SIDE BRACKET LH (ROUND)	11.00	0.00
1	FRONT BUMPER SIDE BRACKET RH (ROUND)	11.00	11.00

1076

PAGE : 4



Date : 26/02/2018
To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT BUMPER TOWING COVER RH	32.00	32.00
1	FRONT BUMPER LOWER GRILLE	580.00	580.00
1	FOG LAMP COVER RH	22.00	22.00
1	FOG LAMP (LED TYPE) RH	350.00	350.00
1	FRONT BUMPER PARKING SENSOR LH (INNER)	125.00	0.00
1	FRONT BUMPER PARKING SENSOR RH (INNER)	125.00	125.00
1	FRONT BUMPER PARKING SENSOR RH (CENTRE)	125.00	125.00
1	FRONT BUMPER PARKING SENSOR RH (OUTER)	125.00	125.00
6	FRONT BUMPER PARKING SENSOR O RING	24.00	24.00
1	FRONT BUMPER PARKING SENSOR WIRE	115.00	115.00
1	FRONT NUMBER PLATE BASE	88.00	0.00

1498

PAGE : 5



Date : 26/02/2018
To : AXA INSURANCE PTE LTD
Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
Insured By : AXA INSURANCE PTE LTD
Certificate No : GA273348 Accident Date : 08/01/2018
Vehicle No : SKE-7336-D Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT BUMPER CENTRE BRACKET	25.00	25.00
1	FRONT BUMPER FOAM (LH)	33.00	0.00
1	FRONT BUMPER FOAM (RH)	33.00	33.00
1	FRONT BUMPER FOAM (CENTRE)	58.00	58.00
1	FRONT BUMPER REINFORCEMENT	265.00	265.00
1	FRONT BUMPER REINFORCEMENT ARM (LH)	140.00	0.00
1	FRONT BUMPER REINFORCEMENT ARM (RH)	140.00	140.00
1	FRONT BUMPER LOWER GARNISH	120.00	120.00
1	SUPPORT PANEL	78.00	78.00
1	SUPPORT PANEL TOP GARNISH	65.00	65.00
1	RADIATOR AIR GUIDE (UPPER)	40.00	40.00
1	RADIATOR AIR GUIDE (LOWER)	110.00	110.00
1	POWER STEERING OIL COOLER TUBE	150.00	150.00

1084

PAGE : 6



Date : 26/02/2018
To : AXA INSURANCE PTE LTD
Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
Insured By : AXA INSURANCE PTE LTD
Certificate No : GA273348 Accident Date : 08/01/2018
Vehicle No : SKE-7336-D Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	CONDENSER	600.00	600.00
1	RADIATOR	450.00	450.00
1	RADIATOR FAN MOTOR ASSY	530.00	530.00
2	RADIATOR TOP BRACKET LH / RH	34.00	34.00
2	RADIATOR TOP BUSH	30.00	30.00
1	INTERCOOLER	580.00	580.00
1	RADIATOR SPARE TANK	70.00	70.00
1	AIR FILTER INTAKE HOSE	210.00	210.00
1	FRONT WHEEL HOUSE PANEL RH	0.00	0.00
1	FRONT CHASSIS MEMBER LH	0.00	0.00
1	FRONT CHASSIS MEMBER RH	0.00	0.00
1	A PILLAR RH	0.00	0.00
1	FRONT CROSSMEMBER	1150.00	1150.00
1	FRONT SHOCK ABSORBER TOP MOUNTING (LH)	98.00	0.00

3650

PAGE: 7



Date : 26/02/2018
To : AXA INSURANCE PTE LTD
Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
Insured By : AXA INSURANCE PTE LTD
Certificate No : GA273348 Accident Date : 08/01/2018
Vehicle No : SKE-7336-D Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT SHOCK ABSORBER TOP MOUNTING (RH)	98.00	0.00
1	FRONT SHOCK ABSORBER (LH)	365.00	0.00
1	FRONT SHOCK ABSORBER (RH)	365.00	365.00
1	FRONT KNUCKLE ARM (LH)	620.00	0.00
1	FRONT KNUCKLE ARM (RH)	620.00	620.00
1	FRONT WHEEL HUB ASSY (LH)	490.00	0.00
1	FRONT WHEEL HUB ASSY (RH)	490.00	490.00
1	FRONT LOWER ARM INNER (LH)	280.00	0.00
1	FRONT LOWER ARM INNER (RH)	280.00	280.00
1	FRONT LOWER ARM OUTER (LH)	230.00	0.00
1	FRONT LOWER ARM OUTER (RH)	230.00	230.00
1	FRONT STABILIZER BAR LINK (LH)	47.00	0.00
1	FRONT STABILIZER BAR LINK (RH)	47.00	47.00
1	STEERING TIE ROD LH	85.00	0.00

2032

PAGE: 8



Date : 26/02/2018
To : AXA INSURANCE PTE LTD
Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
Insured By : AXA INSURANCE PTE LTD
Certificate No : GA273348 Accident Date : 08/01/2018
Vehicle No : SKE-7336-D Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	STEERING TIE ROD RH	85.00	85.00
1	STEERING TIE ROD END LH	85.00	0.00
1	STEERING TIE ROD END RH	85.00	85.00
1	FRONT SPORT RIM RH	450.00	450.00
1	FRONT WINDSCREEN	1250.00	1250.00
1	ROOF MOULDING LH	185.00	0.00
1	ROOF MOULDING RH	185.00	185.00
1	AIR BAG IMPACT SENSOR	62.00	62.00
1	STEERING AIR BAG	1187.00	1187.00
1	AIR BAG CLOCK SPRING	520.00	520.00
1	AIR BAG ECU	500.00	500.00
1	PASSENGER AIR BAG	2300.00	2300.00
1	DASHBOARD	2950.00	2950.00
1	REAR SEAT BELT LH	270.00	270.00
1	REAR SEAT BELT RH	270.00	270.00

10114

PAGE: 9



Date : 26/02/2018
To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM
Insured By : AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	REAR SEAT BELT BUCKLE LH	120.00	0.00
1	REAR SEAT BELT BUCKLE RH	120.00	0.00
	Sub Total	33794.00	29983.00
	Add 0% On Parts	0.00	0.00
Special Nett Item			
1	RADIATOR COOLANT	30.00	30.00
1	FRONT NUMBER PLATE	35.00	35.00
1	WINDSCREEN SEALANT	60.00	60.00
1	IU STICKER	10.00	10.00
1	FRONT TYRE LH	480.00	0.00
1	FRONT TYRE RH	480.00	384.00
1	REPAIR - FRONT SPORT RIM LH	150.00	0.00

519

PAGE: 10

Date : 26/02/2018
To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	1245.00	519.00
	Labour & Misc		
	LABOUR TO CARRY OUT FRONT REPAIR	1000.00	900.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	35.00
	TO SPRAY PAINT ON AFFECTED AREAS	1000.00	900.00
	TO CONDUCT CHASSIS ALIGNMENT	300.00	200.00
	TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS	150.00	120.00
	TO REMOVE & RENEW FRT UNDERCARRIAGE LH TO ASSIST REPAIR	180.00	0.00
	TO REMOVE & RENEW FRT UNDERCARRIAGE RH TO ASSIST REPAIR	180.00	120.00
	TO REMOVE & RENEW FRT CROSSMEMBER TO ASSIST REPAIR	300.00	200.00
			2475



Date : 26/02/2018
To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	TO REMOVE & INSTALL FRONT WINDSCREEN GLASS	150.00	120.00
	TO REMOVE & INSTALL DASH BOARD COMPARTMENT	350.00	200.00
	TO REMOVE & RENEW AIR BAG COMPONENTS TO FACILIATE REPAIR	200.00	100.00
	TO RESET AIR BAG WARNING LIGHT	300.00	150.00
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	100.00	80.00
	Sub Total	4245.00	3125.00

650

PAGE : 12

Date : 26/02/2018
To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : TAN KWEE LIM

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA273348

Accident Date : 08/01/2018

Vehicle No : SKE-7336-D

Make & Model : MERCEDES BENZ E 250CGI

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
-----	-------------	-------------------	-------------------

Sub Total	39,284.00	39,284.00
GST 7.0 %	2,749.88	2,353.89
Total	42,033.	35,980.

COR: \$25,000.00 (Limit REPAIR)

12 DAYS REPAIR

EXCESS : \$ 600.00

Surveyor Name : TAUFIK - LKK

Date & Time : 11/01/2018 3:00:00 PM

Lee Chen Sin

CLAIM DEPARTMENT

DID : 66547520

FAX :

PARTS - \$ 29,983.00

S/N - \$ 519.00

LABOUR - \$ 3,125.00

\$ 33,627.00

20% (1/3 REPAIR)

\$ 26,901.60

PAGE: 13