

REPAIR ESTIMATE*

VEHICLE NO : SHC 1654X

DATE 10/1/2018 10:55

MAKE :

MODEL : HYUNDAI SONATA

Life

H Sam

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Sponge X			\$ 136.30
	Front Bumper Bracket (LH) ?			\$ 20.10
	Headlamp (LH) ?			\$ 797.90
	Front Fender (LH) ✓			\$ 593.00
	Front Fender Shield (LH) X			\$ 86.00
	SUB TOTAL			\$ 2,172.10
	LESS 20%			\$ 434.42
	DISCOUNTED TOTAL			\$ 1,737.68

Front Fender Advertisement Logo (LH) ✓

\$ 100.00 Nett

\$ 100.00

Labour Charge

Panel Beating

300

Spray Painting Charge

\$ 560.00

Wiring Charge

\$ 400.00 0.60

Tuff Kote

\$ 50.00 X

\$ 50.00 20

TOTAL LABOUR

\$ 1,060.00

ESTIMATE TOTAL

\$ 2,897.68

Kalvin (KKK)
 10/1/18 1500hrs
 2 Days
 4/5
 After Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.