

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒奸噴漆
代理保險：車禍
賠償及買賣汽車

M/S YONG LEE SENG MOTOR HOLDINGS PTE LTD DATE: 10/01/2018

DOA : 23/12/2017

ESTIMATE REPAIR FOR VEHICLE NO. SJH 5404 A (SUBARU IMPREZA)

	Description	List Price
1 pc	Front fender (lh) <i>DS/BUC</i>	\$ 290.00 <i>✓</i>
1 pc	Fender innershield <i>To.1</i>	\$ 135.00 <i>✓</i>
10 pcs	Clips @S\$3.80 <i>neu</i>	\$ 38.00 <i>✓</i>
1 pc	Front bumper <i>n</i>	\$ 670.00 <i>X</i>
1 pc	Bumper side retainer (lh) <i>3rd</i>	\$ 25.00 <i>✓</i>
10 pcs	Bumper clips @S\$3.80 <i>neu</i>	\$ 38.00 <i>✓</i>
		\$ 1,196.00
	Less : 20%	\$ (239.20)
		\$ 956.80
	<u>Special Nett Items</u>	
	Labour charges for knocking & replacing parts.	\$ 350.00 <i>250</i>
	Spraypainting	\$ 400.00 <i>360</i>
	TOTAL :	\$ 1,706.80

*not Acknd
wke*

tel. 62583561

*complete After rep -
3 day.*

2 / 5 \$ 800

*P-526
10308*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: