

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: LONPAC INSURANCE BHD	DATE	: 10/01/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBB4614T		
MODEL	: RENAULT KANGOO 1.5 D		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 9-Jan-18
		TIME	: 17:20HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR LH <i>Dented</i>	1	\$ 1,457.00	\$ 1,457.00
2	REAR DOOR EMBLEM 'RENAULT' <i>ren</i>	1	\$ 60.00	\$ 60.00
3	REAR DOOR LOWER PANEL LH <i>Dented</i>	1	\$ 375.00	\$ 375.00
4	REAR DOOR OUTER HANDLE <i>ren</i>	2	\$ 310.00	\$ 620.00
5	REAR DOOR UPPER LOCK <i>Ren & ren</i>	2	\$ 220.00	\$ 440.00 <i>440.00</i>
6	REAR DOOR UPPER LOCK CATCH <i>ren</i>	2	\$ 122.00	\$ 244.00
7	REAR DOOR LOWER LOCK <i>Dented</i>	2	\$ 122.00	\$ 244.00
8	REAR DOOR LOWER LOCK CATCH <i>ren</i>	2	\$ 190.00	\$ 380.00
9	REAR DOOR GLASS RUBBER <i>ren</i>	2	\$ 234.50	\$ 469.00 <i>469.00</i>
10	REAR DOOR RH <i>Dented</i>	1	\$ 1,350.00	\$ 1,350.00
11	REAR DOOR EMBLEM 'KANGOO' <i>ren</i>	1	\$ 65.90	\$ 65.90
12	REAR DOOR LOWER PANEL RH <i>Dented</i>	1	\$ 375.00	\$ 375.00
13	REAR DOOR WEATHERSTRIP <i>wt</i>	1	\$ 360.00	\$ 360.00
14	REAR DOOR GLASS RUBBER <i>ren</i>	2	\$ 234.50	\$ 469.00 <i>469.00</i>
15	REAR BUMPER <i>Dented</i>	1	\$ 685.60	\$ 685.60
16	REAR BUMPER (CENTER) <i>Dented</i>	1	\$ 220.00	\$ 220.00
17	REAR BUMPER (SIDE) <i>RH Dented</i>	2	\$ 190.00	\$ 380.00 <i>380.00</i>
18	REAR BUMPER REFLECTOR <i>ren</i>	2	\$ 40.00	\$ 80.00

19	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 480.00	\$ 480.00	-
20	TAIL LAMP <i>PM called</i>	2	\$ 412.00	\$ 824.00	<i>412</i>
21	REAR END PANEL <i>Pyic</i>	1	\$ 716.00	\$ 716.00	<i>+</i>
22	REAR END PANEL (EXTEND) <i>Pyic</i>	1	\$ 265.00	\$ 265.00	<i>+</i>
23	REAR END PANEL TOP GARNISH <i>the m</i>	1	\$ 253.00	\$ 253.00	<i>+</i>

TOTAL PRICE \$ 10,812.50

LESS 0% \$ -

SUB TOTAL PRICE \$ 10,812.50

6743.50
6069.15

6743.50

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIPS(SET) <i>the m</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
2	REAR DOOR SEALANT <i>the m</i>	2	\$ 100.00	\$ 200.00	<i>+</i>
3	REAR DOOR PROTECTOR CLIP (SET) <i>m</i>	1	\$ 30.00	\$ 30.00	<i>15</i>
4	REAR DOOR INNER TRIM CLIP (SET) <i>the m</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
5	REAR DOOR GLASS SEALANT <i>the m</i>	2	\$ 100.00	\$ 200.00	<i>80</i>
6	REAR DOOR 70KM/H <i>the m</i>	1	\$ 40.00	\$ 40.00	<i>10</i>
7	REAR DOOR 4PAX <i>the m</i>	1	\$ 40.00	\$ 40.00	<i>10</i>
8	REAR END PANEL (EXTEND) SEALANT <i>PM</i>	1	\$ 100.00	\$ 100.00	<i>+</i>
9	REAR END PANEL INSULATION SEALANT	1	\$ 100.00	\$ 100.00	<i>+</i>
10	REVERSE SENSOR <i>Pangd</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

345

TOTAL \$ 1,040.00

415

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,200.00	<i>600</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,200.00	<i>600</i>	
3	Tuff Coat	\$ 250.00	<i>40</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	TRANSFER & REPLACE REAR DOOR <i>the m</i>	\$ 350.00	<i>120</i>	
6	TRANSFER & REPLACE REAR DOOR GLASS	\$ 160.00	<i>80</i>	
7	TO REMOVE AND REFIX REVERSE SENSOR	\$ 160.00	<i>50</i>	
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$180.00	<i>X</i>	

1520

1520

TOTAL

\$5,580.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,852.50

TOTAL LABOUR COST : \$ 5,580.00

TOTAL REPAIR COST : \$ 17,432.50

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

total: 7934.15
A/S: 63K

Adrian Lj
11/01/18.
04 Dyr.
A/S.

5743.50
+ 475.00
+ 1570.00

8688.50
- 2070.1757.70

6950.80

Lump Sum \$ 6950.80
4 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: