

INS. CASE OWNER:

Ernst

CC 4/AXA18000799

1Kj03

LKK:

IDAC:

Surveyor:

KENNETH

DOI:

ASSIGNMENT

16/01/18

Date / Time:

11/01/18

Registered in Merimen:

11/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 5454P

Claim No.:

C0468052

Name of Insured:

TRANS - CAB SERVICES PTE LTD

Policy No.:

VPX/P1680520

Insured Tel No.:

HP:

Make / Model:

RENAULT LATITUDE - 2.0L (17)

Excess Sec II :SS

5,000.00

D.O.A.:

10/01/18

Place of Accident:

COLLYER QUAY TOWARDS FINLAYSON  
GREEN

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

MALIK AKHTAR ALI

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

9188 0935

(V/L / YES / NO)

Insured Liability:

% Final ? Yes / No

SHC 5454P  
OISKX 208L  
TP

UNKNOWN



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP: BH Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

29/01/18 (Joy)

SKX 208L - X ; SHC 5454P - X  
BOLA 27; OI FROM REAR  
LETTER SENT

6-3-18

FOR MANDATE

RECEIVED 03 MAR 2018

RECEIVED 31 MAY 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOI:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 19/01/18

Sent By: Shirley Huen

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

23-5-18

Confirm with:

ANTHONY

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

GST

SS

2,609.99

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

240

(S

60 x 4

days)

Loss of Income (LOI):

SS

-

(S

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOU ☐

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

2,857.44

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2,857.44

Name 1:

BH AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT  
11/6/18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/AXA18000799/Kjs3

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 12-01-2018



Code : AXA2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5494P	Veh. Inspected	SKX 208L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	10/01/2018	Inspection Date	16/01/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

## AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

*Not Authorised*  
*I.B.I.*  
*Revised By point*  
*82439.25*

## ACCIDENT REPAIR ON: SKX208L

MODEL : BMW 318

POLICY NO : P1684166

CHASSIS NO : WBA8E36030NT38750

ENGINE NO : F3411196B38B15A

DATE / TIME OF ACCIDENT: 10/01/2018 Time: 2130Hrs ALONG FINLAYSON GREEN

THIRD PARTY VEHICLE NO: SHC5494P

Date: 15/01/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

## Replacement Of Parts

S/N	Quantity	Unit Price S\$	Condition	Amount S\$
1 Boot Lid	1	1,175.00		<i>R</i> 1,175.00 <i>X</i>
2 Boot Lid Hinge LH	1	77.00		<i>R</i> 77.00 <i>X</i>
3 Boot Lid Hinge RH	1	77.00		<i>R</i> 77.00 <i>X</i>
4 Boot Lid Emblem	1	68.00		<i>R</i> 68.00 <i>X</i>
5 Boot Lid "318" Lettering	1	72.00		<i>R</i> 72.00 <i>X</i>
6 Boot Lid Lamp LH	1	270.00		<i>R</i> 270.00 <i>X</i>
7 Boot Lid Lamp RH	1	270.00		<i>R</i> 270.00 <i>X</i>
8 Rear Bumper	1	1,075.00		<i>R</i> 1,075.00 <i>X</i>
9 Rear Bumper Side Retainer LH	1	12.00		<i>R</i> 12.00 <i>X</i>
10 Rear Bumper Side Retainer RH	1	12.00		<i>R</i> 12.00 <i>X</i>
11 Rear Bumper Upper Centre Bracket	1	35.00		<i>R</i> 35.00 <i>X</i>
12 Rear Bumper Reinforcement	1	425.00		<i>R</i> 425.00 <i>X</i>
13 Rear Bumper Sponge	1			<i>R</i> - <i>X</i>
14 Rear Bumper Under Cover	1	65.00		<i>R</i> 65.00 <i>X</i>
15 Rear Bumper Tow Cover	1			<i>R</i> - <i>X</i>
16 Rear Bumper Sensor	1	235.00		<i>R</i> 235.00 <i>X</i>
17 Rear Bumper Sensor Ring	1	8.00		<i>R</i> 8.00 <i>X</i>
18 Rear Bumper Sensor Bracket	1	68.00		<i>R</i> 68.00 <i>X</i>
19 Rear Bumper Sensor Wiring Harness	1			<i>R</i> - <i>X</i>
20 Rear End Panel	1	595.00		<i>R</i> 595.00 <i>X</i>
21 Rear End Panel Garnish	1	81.00		<i>R</i> 81.00 <i>X</i>
22 Rear Tyre Panel	1	180.00		<i>R</i> 180.00 <i>X</i>
23 Front Bumper	1	960.00		<i>R</i> 960.00 <i>X</i>
24 Front Bumper Side Retainer LH	1	18.00		<i>R</i> 18.00 <i>X</i>
25 Front Bumper Side Retainer RH	1	18.00		<i>R</i> 18.00 <i>X</i>
26 Front Bumper Plate Garnish	1	68.00		<i>R</i> 68.00 <i>X</i>
27 Front Bumper Reinforcement	1	480.00		<i>R</i> 480.00 <i>X</i>
28 Front Bumper Sponge	1	53.00		<i>R</i> 53.00 <i>X</i>
Sub-Total:				6,397.00
Less 5% Discount				319.85
Total Parts:				6,077.15

## Special Nett Items

1 Anti-rust coating	1	80.00	<i>R</i> 80.00 <i>X</i>
---------------------	---	-------	-------------------------

2	Rear Bumper Clips	10	3.50
3	Front Bumper Clips	10	3.90
	Reverse Sensor	1	200.00

*nn* 35.00  
*nn* 39.00  
*nn* 200.00  


---

354.00

**Total Parts: 6,431.15**

**Labour Charges For Front Side Portion**

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Provide skill labour to check and re-adjust wheel alignment
- 5 Provide skill labour to remove and replace wheel rim and tyre with balancing
- 6 Provide skill labour to dismantle and transfer door fittings and mechanism to facilitate repair
- 7 Remove and refit rear end panel lining and garnish to facilitate repair
- 8 Remove and replace bumper sensors

500p  
1,500.00  
660p  
1,200.00  
30p  
60.00  
*nn* 70.00 X  
*nn* 80.00 X  
*nn* 80.00 X  
  
*nn* 100.00 X  
100.00  
60p  
2,990.00  
3190p  
9,421.15  
659.48  
10,080.63

**Total Labour:**

**Total Parts & Labour:**

**GST 7%**

**Grand Total:**

**Estimate Repair Duration**

*4 days* **9 days**

ACCIDENT VEHICLE OF : SKX208L

Page : 2 of 2

**Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

**ESTIMATOR: ANTHONY**

Survey attended by:

Name : *Kenneth*  
Company : *LKK*  
Date : *18/11/18*  
Time : *10.45am*  
Contact No : *96910663*  
Email :

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary claims must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 5414C

### Vehicle Details

Vehicle No.: SKX208L  
Vehicle to be Exported: No  
Intended De-registration Date: 11 Jan 2018  
Vehicle Make: B.M.W.  
Vehicle Model: 318i SEDAN LED NAV  
Primary Colour: Blue  
Manufacturing Year: 2015  
Engine No.: F3411196B38B15A  
Chassis No.: WBA8E36030NT38750  
Maximum Power Output: 100.0 kW (134 bhp)  
Open Market Value: \$31,110.00  
Original Registration Date: 30 Oct 2015  
First Registration Date: 30 Oct 2015  
Transfer Count: 0  
Actual ARF Paid: \$30,554.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 29 Oct 2025  
PARF Rebate Amount: \$22,915.00

### Intended COE Rebate Details

COE Expiry Date: 29 Oct 2025  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$60,000.00  
COE Rebate Amount: \$46,703.00  
**Total Rebate Amount: \$69,618.00**

The information contained herein is correct as at 11 Jan 2018

OK



**SELL YOUR CAR BY BIDDING**  
**HIGHEST SELLING PRICE GUARANTEED!**  
**OR GET \$100 CASH!**



**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

PML Warranty BMW X5 XDrive35d, First Hand Car Now



In House Finance Available  
 Different Loan Package Available  
 Top 1 Choice,  
 Speedo Motoring



4 vehicles

Sort by Date Posted

20 results/page

bmw 318

Basic Search



<b>Price</b> Any price	<b>Depre</b> Any depre	<b>Reg Date</b> Any date	<b>Eng Cap</b> Any	<b>Veh Type</b> All types
<b>Fuel</b> Any fuel	<b>Mileage</b> Any	<b>OMV</b> Any	<b>Gear</b> Any Gear	<b>Past Owners</b> Any
<b>Category</b> All categories	<b>Scheme</b> All schemes	<b>Dealer</b> Any Dealer	<b>Location</b> Any	<b>Status</b> Any status

Make & Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
 <b>BMW 3 Series 318i</b> 1 Owner Only, Condition Good As New, Super Low Mileage, Selling Due To Under Use, Owner Regular Overseas, Lucky Red Exterior Comes With Black Interior, View To Believe Condition, Always Serviced At PM... Prem Roy Motoring Posted: 06-Jan-2018 Tags: 2015 BMW 318i, BMW 318i, BMW, 318i, Used BMW	\$129,800	\$14,890 /yr	30-Sep-2015	1,499 cc	9,000 km	Luxury	Available
 <b>BMW 3 Series 318i Sport</b> 1 Owner With Full PML Agent Servicing History, Beautiful White With Sand Interior, Factory Warranty Till Sept 2018, Make An Appointment With Our Sales Consultant To View Another Pristine Prowined Vehi... Orchard Credit Pte Ltd Posted: 03-Jan-2018 Tags: 2015 BMW 318i, BMW 318i, BMW, 318i, Used BMW	\$125,000	\$14,380 /yr	23-Sep-2015	1,499 cc	37,000 km	Luxury	Available
 <b>BMW 3 Series 318i Sport</b> Full PML Service, Excellent Condition, Still Under PML Warranty, Owner's Consignment, Priced To Sell, High Loan And High Trade In Available, Kindly Call To Arrange For Viewing! Posted: 01-Dec-2017 Tags: 2015 BMW 318i, BMW 318i, BMW, 318i, Used BMW	\$117,000	\$13,030 /yr	27-Oct-2015	1,499 cc	50,000 km	Luxury	Available
 <b>BMW 3 Series 318i Sport</b> Selling On Behalf Of Direct Seller To Private Buyer By SGCarConsign. Posted: 01-Nov-2017 Tags: 2015 BMW 318i, BMW 318i, BMW, 318i, Used BMW	-	N.A	29-Dec-2015	1,499 cc	-	Luxury	SOLD

Make &amp; Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, kick up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 318, bmw 318 Singapore, used bmw 318 Singapore, used bmw 318, used vehicles Singapore or even buy used bmw 318 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article

- About Us
- Careers
- Contact Us
- Sitemap

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ernest Tay

Date: 19 Jan 2018

**Preliminary Advice**

Insured Vehicle No	: SHC5494P	Accident Date	: 10/01/2018
TP Vehicle No	: SKX208L	Assignment Date	: 11/01/2018
Make	: BMW 318i	Est. Duration of Repair	: 4 days
Date of Inspection	: 16/01/2018		
Inspection At	: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....rear and front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,621.15
Revised Amount	:S\$	2,439.25
Check Items (Estimated)	:S\$	2,325.20
Total	:S\$	4,764.45

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.

## Print Received Message

This mail is associated with :

**\*SKX208L (C0468052)**

**[SHC5494P]**

TP

LOH ANDREW

Jan 10 2018 9:00PM

[TRANS-CAB SERVICES PTE LTD]

BH Auto Services Pte Ltd

**From** AXA Insurance Pte Ltd (HQ) (AXA\_SG), sent on 22/03/2018 21:41 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$2439.25) - SKX208L - Claim Handler: Ernest Tay

Approved:2439.25.

## Print Received Message

This mail is associated with :

**\*SKX208L (C0468052)**  
**[SHC5494P]**  
TP  
LOH ANDREW  
Jan 10 2018 9:00PM  
[TRANS-CAB SERVICES PTE LTD]  
BH Auto Services Pte Ltd

**From** AXA Insurance Pte Ltd (HQ) (AXA\_SG), sent on 23/05/2018 14:09 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$2857.44) - SKX208L - Claim Handler: Ernest Tay

Approved:2857.44.

# BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

---

**PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING**

Your Reference: SHC5494P

Our Reference: SKX208L

Date: 01/03/2018

M/s AXA Insurance Pte Ltd  
8 Shenton Way  
#24-01 AXA Tower  
Singapore 068811

BY POST ONLY

Attention: Claims Department

**CLAIMANT: LOH ANDREW**

**PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 10/01/2018 ALONG FINLAYSON GREEN INVOLVING VEHICLE NO SKX208L & SHC5494P.**

We act for LOH ANDREW who was the owner of motor vehicle no. SKX208L.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 10/01/2018 involving our client's vehicle registration number SHC5494P and vehicle registration number SKX208L driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and/or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 2609.99
2	Loss of Use (\$ 120.00 x 4days)	\$ 480.00
3	LTA Search Fee	\$ 7.45
	<b>Total :</b>	<b>\$ 3097.44</b>

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of ;
- (b) Final Repair Bill
- (c) Rental Invoice / Loss Of Use
- (d) LTA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,

Jacelyn Loh

(O): 6559 8944 (F): 6269 2404

Email: Jacelyn.loh@bhauto.com.sg

## Joy Irene (LKKAUTO)

---

**From:** Joy Irene (LKKAUTO)  
**Sent:** Monday, 29 January 2018 2:20 PM  
**To:** 'claims@transcab.com.sg'  
**Cc:** 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'; Admin A  
**Subject:** ACCIDENT INVOLVING SHC 5494P & SKX 208L ALONG COLLYER QUAY TOWARDS FINLAYSON GREEN ON 10/01/2018

Transcab Taxi (Singapore )  
Trans-cab Services Pte Ltd

Dear Sir/Madam,

OUR REF : CC4/AXA18000799/Kjs3  
YOUR REF : VPX/P1680520 (SHC 5494P)

### **ACCIDENT INVOLVING SHC 5494P & SKX 208L ALONG COLLYER QUAY TOWARDS FINLAYSON GREEN ON 10/01/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **BH Auto Services Pte Ltd** acting on behalf of the owner of SKX 208L against your motor insurance policy.

Based on the accident report and accident scenario, we are of the opinion that liability is not in our favour whereby our vehicle hit third-party from the rear. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

We also wish to advise that there is an excess of **S\$5,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)

- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to [cst@axa.com.sg](mailto:cst@axa.com.sg) / [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm (press 1 for GI and option 3 for claims) or [cst@axa.com.sg](mailto:cst@axa.com.sg) / [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com). Please quote our claim reference when you contact us that we can assist you more effectively.

Thank you.

Best Regards,  
 Joy Irene | Case Handler  
 LKK Auto Consultants Pte Ltd  
 DID: 6749-5792 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**AUTHORISATION**Name of owner of m/vehicle: LOH ANDREWAddress: 22 Jalan Meriah Saga Spore 278109.NRIC No: S8725414CRE: ACCIDENT ON 10/01/18 ALONG Finlayson Green.INVOLVING SKC 208L & SHC 5494D.

In consideration of **BH AUTO SERVICES PTE LTD** ("the Workshop") repairing my/our vehicle no. SKC 208L at my/our request, I/we the abovenamed owner of motor vehicle no. SKC 208L hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident.

I/we further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/we further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/we further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/we agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address.

I/we hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis.

I/we further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim.

I/we further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop.

Date this 10 (day) of 01 (month) 2018 (year)Signed: Owner of m/vehicle: Loh AndrewHP: 9760 3113



redefining / insurance

CLAIM REF : C0468052  
INSURED : TRANS-CAB SERVICES PTE LTD

**DISCHARGE VOUCHER**

We/I LOH ANDREW, NRIC NO. S8725414C hereby agree to accept the sum of dollars [ TWO THOUSAND EIGHT HUNDRED FIFTY SEVEN AND FORTY FOUR CENTS ONLY ] (\$\$ 2,857.44 ) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [ SHC 5494P ] as a result of an accident along [ FINLAYSON GREEN ] on [ 10/01/2018 ] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [ SKX 208L ].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [ SHC 5494P ] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [ SHC 5494P ].

Dated this 25<sup>th</sup> day of MAY 2018

Claimant's Signature : [Signature]



NRIC no. / Company Stamp : S8725414C

Occupation/ Business : INDOOR

Address : 32 JALAN MERAH SUSA

Telephone No. : 97603113

Witness's Name : ANDREW LUN

Witness's Signature : [Signature]

Witness's NRIC No. : S8113716A

This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.

**BH AUTO SERVICES PTE LTD****BLK 1 SIN MING INDUSTRIAL ESTATE  
SECTOR C #01-115 SINGAPORE 575636****Tel: 6743 3494****Fax: 6269 2404****CO. REG. NO. 201006106C****GST REG NO. 201006106C****TAX INVOICE****Final Repair Bill****Our Ref: SKX208L****Date: 01/03/2018****M/s AXA Insurance Pte Ltd  
8 Shenton Way  
#24-01 AXA Tower  
Singapore 068811****BY POST ONLY****Vehicle No : SKX208L  
Make/ Model : BMW 318I  
Year of Manufacture : 2015  
Chassis No. : WBA8E36030NT38750  
Colour : BLUE  
D.O.A : 10/01/2018**

<b>QTY</b>	<b>ITEM/PARTICULARS</b>	<b>AMOUNT (\$\$)</b>
------------	-------------------------	----------------------

1. Repair Cost for Motor Vehicle No. **SKX208L**  
Type of repair: Part By Part **:\$\$ 2439.25**

**GST @ 7% : \$ 107.74****GRAND TOTAL:\$ 2609.99****Total : Singapore Dollars Two Thousand Six Hundred and Nine Dollars and Ninety  
– Nine Cents Only.**

---

**Company's Stamp & Signature**



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 11 Jan 2018 / 11:05:21

Receipt Date/Time : 11 Jan 2018 / 11:05:21

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-180111-000556

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
	Result of Insurance Enquiry - SHC5494P As at 10 Jan 2018/21:30:00 Insurance Co: AXA INSURANCE PTE LTD			
1	Insurance Enquiry - SHC5494P Enquiry Fee 20180111110304018032	7.00	0.49	7.49
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45

Paid By

xxxxxxxxxxxx0664 Credit Card:  
Visa/MasterCard 7.45

Total 7.45  
Cash Change 0.00  
Tendered Amount 7.45  
Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt OK Save as PDF

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jan 2018		11 Jan 2018 15:12 <a href="#">Edit Adj Rpt</a>	<b>\$2,439.25</b> <a href="#">Edit Estimates</a>	<b>\$2,439.25</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	LOH ANDREW, ID: S8725414C		
Vehicle Reg. No.:	SKX208L	Date of Loss:	10/01/2018 21:00 - :59 [26 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0468052	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHC5494P	Policy No. (Claimant):	P1684166
		Excess:	S\$5,000.00
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Ernest Tay - 6880 4835]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/01/2018]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AXA\_SG (23/05/2018): Alert - Adj Mandate Approved (S\$2857.44) - SKX208L - Claim Handler: Ernest Tay
- AXA\_SG (22/03/2018): Alert - Adj Mandate Approved (S\$2439.25) - SKX208L - Claim Handler: Ernest Tay
- AXA\_SG (29/01/2018): TP settlement - C0468052/P1680520
- AXA\_SG (11/01/2018): WP / New TP Assignment - /P1680520

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKX208L (C0468052)  
[SHC5494P]  
TP  
LOH ANDREW  
Jan 10 2018 9:00PM  
[TRANS-CAB SERVICES PTE LTD]  
BH Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/01/18 11:31	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/03/18 15:26	General View	1	Load JPG	
2	22/03/18 15:26	General View	1	Load JPG	
3	22/03/18 15:26	General View	1	Load JPG	
4	22/03/18 15:26	General View	1	Load JPG	
5	22/03/18 15:26	General View	1	Load JPG	
6	22/03/18 15:26	General View	1	Load JPG	
7	22/03/18 15:26	General View	1	Load JPG	
8	22/03/18 15:26	General View	1	Load JPG	
9	22/03/18 15:26	General View	1	Load JPG	
10	22/03/18 15:26	General View	1	Load JPG	
11	22/03/18 15:26	General View	1	Load JPG	
12	22/03/18 15:26	General View	1	Load JPG	
13	22/03/18 15:26	General View	1	Load JPG	
14	22/03/18 15:26	General View	1	Load JPG	
15	30/05/18 14:07	Reinspection Photo	1	Load JPG	
16	30/05/18 14:07	Reinspection Photo	1	Load JPG	
17	30/05/18 14:07	Reinspection Photo	1	Load JPG	

Documentation

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	11/01/18 13:24	EMAIL	1	Load PDF	
2	11/01/18 13:24	SAS2339253.PDF_safe	1	Load PDF	
3	11/01/18 13:24	SKM_C224e18011111200_0001	1	Load JPG	
4	11/01/18 15:11	Email to Transcab - NR	1	Load TIF	
5	29/01/18 11:08	Singapore Accident Statement - SHC5494P/ INSD	1	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/01/18 11:36	TP ESTIMATE- MARKED	1	Load PDF	
2	20/03/18 17:05	LTA SEARCH	1	Load PDF	
3	20/03/18 17:05	LETTER TO OI	1	Load PDF	
4	31/05/18 13:38	WORKSHOP INVOICE	1	Load PDF	
5	31/05/18 13:38	AUTHORISATION TO ACT FORM	1	Load PDF	
6	31/05/18 13:38	DISCHARGE VOUCHER	1	Load PDF	
7	31/05/18 13:38	LOD	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHC5494P (Insd veh)	Model:	BMW 318i 1.5 SEDAN LED
	SKX208L (TP veh)		NAV (A)
Date of Accident:	10/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	10,294.63	
Final Repair Cost	:	\$	2,609.99	
Loss of Use	:	\$	240.00	4.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	7.45	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	2,857.44	

**Is Third Party Workshop GIA Registered?** ☐ YES ☒ NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	BH Auto Services Pte Ltd	:	\$ 2,857.44
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

31 May

2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18000799/KJB3Q2

Date: 31/05/2018

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : SKX208L

Insured Vehicle No :

SHC5494P

Date of Loss: 10/01/2018

Nature of Claim:

TP

Claim No: C0468052

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKX208L

Make &amp; Model:

BMW 318I, 1.5 SEDAN LED NAV (A)

Engine No:

F3411196B38B15A

Reg. Date:

30/10/2015 (Man. Year: 2015)

Chassis No:

WBA8E36030NT38750

Colour:

Metallic Dark Blue

Odometer:

24650 km

Engine Capacity:

1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:

225/50 R17

Rear Tyre Size:

225/50 R17

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,351.15	1,189.25	5,161.90	81.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,250.00	2,020.00	61.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,621.15</b>	<b>2,439.25</b>	<b>7,181.90</b>	<b>74.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>673.48</b>	<b>170.75</b>	<b>502.73</b>	<b>74.65</b>
<b>Nett Amount (S\$)</b>	<b>10,294.63</b>	<b>2,610.00</b>	<b>7,684.63</b>	<b>74.65</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		<b>240.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>7.45</b>		
<b>Nett Liability (S\$)</b>		<b>2,857.45</b>		

### INSPECTION

Date of Assignment:

11/01/2018

Date Inspected:

16/01/2018 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)

Blk 1 Sin Ming Industrial Estate Sector C,

#01/111/113/115/117

Singapore 575636

Estimated Period of Repair:

4.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2018)
<b>Parts:</b> 143	BMW 318i 1.5 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKX208L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID (CONSISTENT)	Repair	1,175.00 FL	*- FL
2	1		*BOOT LID HINGE LH (CONSISTENT)	Repair	77.00 FL	*- FL
3	1		*BOOT LID HINGE RH (CONSISTENT)	Repair	77.00 FL	*- FL
4	1		*BOOT LID EMBLEM (CONSISTENT)	Necessary	68.00 FL	*68.00 FL
5	1		*BOOT LID 318 LETTERING (CONSISTENT)	Necessary	72.00 FL	*72.00 FL
6	1		*BOOT LID LAMP LH (CONSISTENT)	Serviceable	270.00 FL	*- FL
7	1		*BOOT LID LAMP RH (CONSISTENT)	Serviceable	270.00 FL	*- FL
8	1		*REAR BUMPER (CONSISTENT)	Buckled	1,075.00 FL	*1,075.00 FL
9	1		*REAR BUMPER SIDE RETAINER LH (CONSISTENT)	Serviceable	12.00 FL	*- FL
10	1		*REAR BUMPER SIDE RETAINER RH (CONSISTENT)	Serviceable	12.00 FL	*- FL
11	1		*REAR BUMPER UPPER CENTRE BRACKET (CONSISTENT)	Repair	35.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Repair	425.00 FL	*- FL
13	1		*REAR BUMPER SPONGE (CONSISTENT) (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*REAR BUMPER UNDER COVER (CONSISTENT)	Serviceable	65.00 FL	*- FL
15	1		*REAR BUMPER TOW COVER (CONSISTENT) (NPA)	Not Necessary	0.00 FL	*- FL
16	1		*REAR BUMPER SENSOR (CONSISTENT)	Serviceable	235.00 FL	*- FL
17	1		*REAR BUMPER SENSOR RING (CONSISTENT)	Serviceable	8.00 FL	*- FL
18	1		*REAR BUMPER SENSOR BRACKET (CONSISTENT)	Serviceable	68.00 FL	*- FL
19	1		*REAR BUMPER SENSOR WIRING HARNESS (CONSISTENT) (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*REAR END PANEL (CONSISTENT)	Repair	595.00 FL	*- FL
21	1		*REAR END PANEL GARNISH (CONSISTENT)	Serviceable	81.00 FL	*- FL
22	1		*REAR TYRE PANEL (CONSISTENT)	Repair	180.00 FL	*- FL
23	1		*FRONT BUMPER (CONSISTENT)	Repair	960.00 FL	*- FL
24	1		*FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	Serviceable	18.00 FL	*- FL
25	1		*FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	Serviceable	18.00 FL	*- FL
26	1		*FRONT BUMPER PLATE GARNISH (CONSISTENT)	No such part	68.00 FL	*- FL
27	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Repair	480.00 FL	*- FL
28	1		*FRONT BUMPER SPONGE (CONSISTENT)	Serviceable	53.00 FL	*- FL
29	10		*REAR BUMPER CLIPS (CONSISTENT)	Necessary	35.00 FS	*35.00 FS
30	10		*FRONT BUMPER CLIPS (CONSISTENT)	Not Necessary	39.00 FS	*- FS
31	1		*REVERSE SENSOR (CONSISTENT)	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)**    **6,671.00**    **1,250.00**  
**- List Item Discount on L Items 5.00/5.00% (\$\$)**    **319.85**    **60.75**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	6,351.15 1,189.25
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	ANTI-RUST COATING	New	80.00	0.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,500.00	500.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	1,200.00	660.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	30.00
5	PROVIDE SKILL LABOUR TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	70.00	0.00
6	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE WHEEL RIM AND TYRE WITH BALANCING	New	80.00	0.00
7	PROVIDE SKILL LABOUR TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO FACILITATE REPAIR	New	80.00	0.00
8	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	100.00	0.00
9	REMOVE AND REPLACE BUMPER SENSORS	New	100.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,270.00</b>	<b>1,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >