

CASE OWNER:

Stacey

CC 4

ASM1800

0802

K ea3

LKK:
IDAC:18/01/18
S8m00715

Surveyor:

KSC

DOI:

ASSIGNMENT

16/1/18

Date / Time:

12/01/18

Registered in Merimen:

Pre-assign / CCU / FTE

SBB6916J



Insured Vehicle No.:

Name of Insured:

KOH YEN CHUAN @ Peter Koh

Insured Tel No.:

HP:

90093443

Excess Sec II : S5

D.O.A.:

09/01/18

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

GBC7MSH



INSRS:

WSP:

Tel:

Liability:

RMKS:

Alan's United



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE: 15/1/18 7:51h HAWA

After call ltr to OE: 08/02/18 - sic ok

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

15/1/18 : 9:42 am. called OE, Mr Peter Koh, 90093443 but no response.

" : 10:11 am. spoke to OE, Mr Peter Koh, 90093443 agreed to settled on the claim - amount of USD 1500. mention he also have already make a police report.

08/02/18 - email letter to OE.

3/2/18 file pass to typist to prepare report.

RECEIVED 15 FEB 2018

RECEIVED 03 SEP 2018

PRELIMINARY ADVICE

Date/Time: 11/1/18

Sent By: AMK

FINALIZATION

Date/Time:

Confirm with: KSC

Confirm by: KSC

Repair Cost:

45 S\$ 3,280

(5 days) Reduction:

20 %

Email

Call

FINAL SETTLEMENT

Date/Time: 28-8-18

Confirm with: KSC

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

01/05/18 S\$ 3,471.50

01 REPAIR ENDED TP

Loss of Rental (LOR):

S\$ 400.00

(4 days) x 100

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 0.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 3,871.50

Global Sum S\$:

FINAL PAYMENT

Date/Time: 28-8-18

Confirm with:

Email

Call

Payee 1:

S\$ 3,871.50

Name 1:

ALAN'S UNITED AUTO PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

31/9/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +350

ASS. REC. BY:

REF:

AA1

Jury Lea3

(1)

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

43266

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBC 72254

Yr Regn:

13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

707 High

cc

2982

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

117456

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JT1HT02P001 22367

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

9

mm

R/Bal.

6

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

9/1/18

D.O.I.

16/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/1

File parts to Coroner.

45:43.250

(RED: 1.148.18

26/1)

NEED:

MKT VALUE, (OE PARTS)

SIGN SIGNATURE BELOW

30/1

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Report Format:

Lump Sum / L.B.I: (\$

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee

Transportation

S + RS \$

Photos

Others

TOTAL

13/2/2018



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00715

Our ref: CC4/ASM18000802/Kea3

Date: 17.01.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBC 7225H


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.01.2018 at the premises of M/s Alan's United Auto Pte Ltd - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	4,203.78
Revised Estimate Amount	: S\$	3,667.69
"Check" Items Amount	: S\$	115.76
Market Value	: S\$	
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18000802/ea3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 12-01-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBB 6916J	Veh. Inspected	GBC 7225H
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	12/01/2018
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	09/01/2018	Inspection Date	
	Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05705

Date : 11-Jan-2018

PAGE : 1

Vehicle Insured : SBB6916J
Accident Date : 09-Jan-2018

Our Ref : 218010 (AXA) / CHAN

NEOASIA (S) PTE LTD
6 TAGORE DRIVE #04-06/07
TAGORE INDUSTRIAL BUILDING
Singapore 787623

Not authentic
1/10/18 8325d
Returning After Repair
Qdang

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE 3.0 GBC7225H

- 1 pc Tail gate
- 1 pc Tail gate "TOYOTA" sticker
- 1 pc Tail gate "HIACE" sticker
- 1 pc Tail gate logo
- 1 pc Rear bumper fascia
- 4 pcs Rear bumper clip @ S\$ 3.00
- 1 pc Rear o/s bumper bracket
- 2 pcs Rear o/s bumper side bracket @ S\$ 23.30
- 1 pc Rear o/s fender air duct
- 1 pc Rear End panel-outer
- 1 pc O/s taillamp
- 1 pc Rr o/s taillamp lower garnish

R 1,872.72 —
m 37.50 —
m 32.10 —
m 30.10 —
R 443.02 —
m 12.00 —
R 43.30 *X*
R 46.60 *X*
m 64.45 *X*
R 309.25 —
m 286.90 —
m 147.10 *X*

Less 25% :

3,325.04
831.26

- 1 pc Rear bumper reverse sensor
- 1 pc Rear w/s glass sealant

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

To remove & refix rear windscreen
glass and conduct water leak test.

3023.59
735.96

2287.63
Ad 2,493.78 *200sn*
m 300.00 *sn*
m 60.00 *sn 40sn*

 600.00 *50cl*

 600.00 *54cl*

 150.00 *12cl*

Total : S\$ 4,203.78

Singapore Dollars Four Thousand Two Hundred and
Three and Cents Seventy Eight Only.

L/Sum
3250.00

Kenneth
Plus Customer

P2267.69
SN 240.00
L 1160.00
SP 195.00

 3862.69
-15% 579.40

 3283.29

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SBB6916J (AXA)

Date : 19-01-2018

Accident Date : 09-01-2018

Our Ref : 218100 /CHAN

NEOASIA (S) PTE LTD

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR TOYOTA HIACE 3.0 GBC7225H

TO INSTALL TAIL GATE COMPANY LETTERING

\$180.00

1 PC TAIL GATE 70km/h STICKER

per \$15.00 SN

\$195.00

Singapore Dollars One Hundred Ninety Five Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SBB6916J
Accident Date : 09-Jan-2018

Our Ref : 218010 (AXA) / CHAN

NEOASIA (S) PTE LTD
6 TAGORE DRIVE #04-06/07
TAGORE INDUSTRIAL BUILDING
Singapore 787623

No. : 05705

Date : 11-Jan-2018

PAGE : 1

Not Authentic
1/10/18
Revised After Repair
5 days

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE 3.0 GBC7225H

1 pc Tail gate
1 pc Tail gate "TOYOTA" sticker
1 pc Tail gate "HIACE" sticker
1 pc Tail gate logo
1 pc Rear bumper fascia
4 pcs Rear bumper clip @ S\$ 3.00
1 pc Rear o/s bumper bracket
2 pcs Rear o/s bumper side bracket @ S\$ 23.30
1 pc Rear o/s fender air duct
1 pc Rear End panel-outer
1 pc O/s taillamp
1 pc Rr o/s taillamp lower garnish

Rt 1,872.72 ✓
Mc 37.50 ✓
Mc 32.10 ✓
Mc 30.10 ✓
Rt 443.02 ✓
Mc 12.00 ✓
43.30 ?
46.60 ?
64.45 ?
Rt 309.25 ✓
CM 286.90 ✓
Sm 147.10 X

3,325.04

Less 25% : 831.26

1 pc Rear bumper reverse sensor
1 pc Rear w/s glass sealant

nd 2,493.78 *200sn*
Mc 300.00 *sn*
Mc 60.00 *sn 40sn*

To putty and spray replaced parts

600.00 *500*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *540*

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 *120*

Total : S\$ 4,203.78

Singapore Dollars Four Thousand Two Hundred and
Three and Cents Seventy Eight Only

LKK Auto Consultants hence notify

the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Stacey

RE: Re:Direct Settlement - Accident Involving SBB 6916J (OI : AXA - S8M00715) and GBC 7225H (TP : LKK REF - CC4/ASM18000802/Kea3) on 09/01/2018

Type

i Information

Message

Liability: Insured hit TP rear. Spoken to insured and he aware that his NCD is affected and AXA to settle at best.
Settlement: Repair Cost : \$3,477.50 (w/GST) Loss of Rental: \$400.00 (4days x \$100) LTA: \$2.00 Total: \$3,879.50

Reply



**Re:RE: Re:Direct Settlement - Accident Involving SBB
6916J (OI : AXA - S8M00715) and GBC 7225H (TP : LKK
REF - CC4/ASM18000802/Kea3) on 09/01/2018**

Type

 Information

Message

pls proceed

Reply

NEOASIA (S) PTE LTD

c/o Blk 7 Sin Ming Industrial Estate
#01-76

Singapore 575642

Date: 2-2-2018

AAA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01

AAA TOWER

SINGAPORE 068811

LKK

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES

ALONG BUKIT TIMAH RD TOWNS CITY ON 09-01-2018

I / We, the owner of Vehicle No. GBC 7225 H which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

- | | | |
|---|---|-------------------|
| 1. Costs of repair | - | \$ 3477.50 |
| 2. Loss of Use /Rental fees 4 Days | - | \$ 560.00 |
| 3. Police / GIA report / LTA fees | - | \$ 2.00 |
| 4. Surveyor report fees | - | |
| 5. Others | - | |
| Total: | | <u>\$ 4039.50</u> |

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

22 JANUARY 2018

KOH YEW CHUAN @ PETER KOH
132A LORONG KISMIS
SINGAPORE 598060

Dear Sir/Madam,

OUR REF : CC4/ASM18000802/Kea3
YOUR REF : SBB 6916J
ACCIDENT INVOLVING SBB 6916J AND GBC 7225H ALONG DUNEARN ROAD
TWRDS NEWTON CIRCUS ON 09.01.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from ALAN'S UNITED AUTO PTE LTD, acting on behalf of the owner of GBC 7225H against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle GBC 7225H. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Siti
Case Handler
DID: 6256 3561
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORITY

ACCIDENT INVOLVING GBC 7225 H AND SBB 6916 J
ALONG BUKIT TIMAH RD THRS CITY
ON 09-01-2018

BY THE LETTER OF AUTHORITY, I/We, NEOASIA (S) PTE LTD
NRIC NO. 199504326 C The owner of Vehicle No. GBC 7225 H

Hereby irrevocably appoint Messrs **Alan's United Auto Pte. Ltd.** at Block 7, Sin Ming Industrial Estate, Sector C, #01-76, Singapore 575642, and/or their representative to process the Third Party claim on my/our behalf and to do all and/or any of the followings:-

1. To submit, negotiate/compromise and to resolve settlements of my/our above mentioned claim.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favor of **Alan's United Auto Pte. Ltd.**
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever as they deem necessary for the purpose of settling my/our said claim.

I / We hereby declare that all the processing and documents done by virtue of this letter of authority on my/our behalf by my/our repairers or any person authorized by them shall be as good valid and effectual to all intends and purposes whatsoever as if the same had been done or executed by me/us in person.

I / We further confirm that the acceptance by Messrs **Alan's United Auto Pte. Ltd.** of the settlement amount constitute the full discharge of my/our claim(s) in respect of the above accident.

Signed on the 09 (day) 01 (month) 2018 (year)



Acknowledged by Owner
(company stamp if applicable)



redefining / insurance

CLAIM REF : S8M00715
INSURED : KOH YEW CHUAN @ PETER KOH

DISCHARGE VOUCHER

We/I **[NEOASIA (S) PTE LTD, NRIC NO. 199504326C]** hereby agree to accept the sum of dollars **[THREE THOUSAND EIGHT HUNDRED SEVENTY NINE AND CENTS FIFTY ONLY.] [S\$3,879.50]** paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. **[SBB 6916J]** as a result of an accident along **[BUKIT TIMAH ROAD TOWARDS CITY]** on **[09/01/2018]** of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. **[GBC 7225H]**.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. **[SBB 6916J]** in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. **[SBB 6916J]**.

Dated this 29th day of August 2018

Claimant's Signature :



REC
NRIC no./ Company Stamp :

199504326C

Occupation/ Business :

Address :

6 TAGORE DRIVE #04-06/07 TAJURIE IND BUILDING 5787623

Telephone No. :

Witness's Name :

Company Reg. No. 201113651M

Witness's Signature :

801-75 Singapore

Witness's NRIC No. :

S162308812

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SBB6916J
Accident Date : 09-Jan-2018
Our Ref : 218010 (AXA) / CHAN

No. : 15470

Date : 23-Jan-2018

PAGE : 1

NEOASIA (S) PTE LTD
6 TAGORE DRIVE #04-06/07
TAGORE INDUSTRIAL BUILDING
Singapore 787623

FINAL REPAIR COST FOR TOYOTA HIACE 3.0 GBC7225H
=====

To supply spare parts

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

To remove & refix rear windscreen
glass and conduct water leak test.

To install tail gate company
lettering

	3,250.00
Add 7% GST :	227.50

Total :	S\$ 3,477.50
	=====

Singapore Dollars Three Thousand Four Hundred
and Seventy Seven and Cents Fifty Only

160 Sin Ming Drive #02-19 Sin Ming AutoCity Singapore 575722

Co. Reg. No: 201612109H

No. : CDS 18715

Date : 20.01.2018

Vehicle No : GBA7782B
TOYOTA HIACE

RENTAL CHARGES FOR VEHICLE FROM
16.01.2018 TO 20.01.2018
4 DAYS X S\$ 140.00

AGREEMENT NO.: 80203

REMARK : GBC7225H

AMOUNT

560.00

TOTAL \$	560.00
----------	--------

Cheque should be crossed and made payable to **CDS CAR RENTAL PTE LTD**

Issued By

CDS CAR RENTAL PTE LTD

Co. Reg. No.: 201612109H

Blk 34 Sin Ming Drive #01-104 Singapore 575708

Tel: 6452 7127 Fax: 6454 9575

160 Sin Ming Drive #02-19
Ming AutoCity Singapore 575722

RENTAL AGREEMENT

No: CDS 80203

Vehicle No.	Make / Model
GBA 7782 B	Toyota Hiace (M)

Date: 16/1/2018

HIRER'S PARTICULARS	
Name	NEOASIA(S) PTE LTD
Address	6 TAGORE DRIVE #04-06/07/08 TAGORE RD. BOON SC 787123
Telephone (Home)	
(Office)	6552 7787
H/Phone	
NRIC or Passport No	
Nationality	
Date of Birth	Age
Driving Licence No	Expires
Type	Local / Int'l Issued
Driving Experience	

DRIVER'S PARTICULARS (If different from Hirer)	
Name	Hoon Theng Kwon
Address	BLK 602 ANH MO KO AVENUE #10-2643 SC 560602
Telephone (Home)	
(Office)	
H/Phone	9727 8910
NRIC or Passport No	S 0716443 B
Nationality	
Date of Birth	21-11-1986 Age
Driving Licence No	Expires
Type	Local / Int'l Issued
Driving Experience	33 yrs

CHARGES		
4	Day(s) @ S\$ 140.00	S 560.00
	Week(s) @ S\$	
	Month(s) @ S\$	
	Insurance	/
	Additional Rental Payable	
	Surcharge of Fuel	
	Total	560.00
	Less Deposit (Cash / Cheque No.)	
	Balance Payable / Refundable	
	Refund Received (Cash / Cheque No.)	

Note: 1) Hirer is liable for all parking fines and traffic violations.

2) Excess - In the event of any accident, the Hirer is liable to pay first (S\$ 2500.00) plus loss of earnings before the damaged vehicle is being repaired.

3) Young (≤ 27 yrs), Inexperienced (≤ 2 yrs) or Aged driver (≥ 65 yrs), additional excess of (S\$ 3500.00) will apply.

4) Windscreen claim of \$100 will apply if hit by stone, otherwise full price will apply.

I/We declare that the above particulars are true and correct in every respect and I/We have read and understood the terms and conditions of the Hire Agreement printed overleaf.



Stamp & Signature of Hirer

Signature of Driver
(If different from Hirer)

Date

Date

Date Out	16/1/18	Date In	20-1-2018
Time Out	9.40 AM	Time In	11 AM
Mileage at Delivery / Pick-up	206508	Mileage on Returning	207033
Fuel Level at Delivery / Pick-up	E 1/4 1/2 3/4 F	Fuel on Returning	E 1/4 1/2 3/4 F
Surcharge of Fuel will be at S\$	per 1/4 tank		

Remarks: Kindly note the following:

- No work permit holders are allowed to drive;
- No drivers below 23 years old are allowed to drive;
- Driving to Malaysia is strictly not allowed.

GBC 72854



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-005621

Date of Request: 11/01/2018

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd
Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Dear Sir/Madam,

Enquiry Date 11/01/2018
Enquiry By Chan Yew Siah
TP Vehicle No. SBB6916J
Accident Date 09/01/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SBB6916J	AXA Insurance Pte Ltd	18/05/2017-17/05/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-005621

Date of Request: 11/01/2018

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd
Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Dear Sir/Madam,

Enquiry Date 11/01/2018
Enquiry By Chan Yew Siah
TP Vehicle No. SBB6916J
Accident Date 09/01/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SBB 6916J (Insd veh)	Model:	TPVD TOYOTA HIACE-3.0
	GBC 7225H (TP veh)		D(M)
Date of Accident:	09/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,706.69
Final Repair Cost	:	\$	3,477.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	3,879.50

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ 100 _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown		
1)	ALAN'S UNITED AUTO PTE.LTD.	\$ 3,879.50

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

12/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim	58H400715	Actions		Vehicle Information
Reference	CC4/ASM18006802/Koa3o2 	Next Step	Wait for: Approve Invoice	Incident Vehicle Registration #
Loss Date	9 January 2018	<div>Send Invoice</div>		Make
Request Date	12 January 2018			Model
Due Date				Service Address
Vendor Name	L&K AUTO CONSULTANTS PTE LTD (TP)			...
Type of Loss	Third Party Vehicle Damage			Primary Contact/Insured
Services	Direct settlement			MOH YEW CHUAN PETER 132A LORONG KISMIS, 598060, Singapore 67442689 ANGELA.YAP@FINEXIS.COM.SG
				Claim Handler
				NG Stacey 6548804351 stacey.ng@axa.com.sg

Additional Instructions						
Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type		Document SubType				
<div></div>		<div></div>				
<div>➕ Upload Documents</div>						
NAME		TYPE		SUB-TYPE	AUTHOR	DATE UPLOADED
LORInvoice1 (a).pdf		Invoice		Surveyor/ Assessor expense	L&K AUTO CONSULTANTS PTE LTD (ITP)	12 November 2018

Assessment Details

General & Workshop Details			Vehicle & Driver Details			Vehicle Condition			Taxes & Ratio			Parts & Labour			Miscellaneous			Summary			Parts		
EDIT	SR NO	QTY	QUAN TITY	MATERIAL	SIZE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ STRRN	DISC. QUNTY	BALV. AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE							
		1	1			TAIL GATE			Bent	1872.72		25		1404.54	Approve								
		2	1			TAIL GATE "TOYOTA" STICKER			Necessary	37.5		25		28.13	Approve								
		3	1			TAIL GATE "HACE" STICKER			Necessary	32.1		25		24.08	Approve								
		4	1			TAIL GATE LOGO			Necessary	30.1		25		22.58	Approve								
		5	1			REAR BUMPER FASCIA			Bent	443.02		25		332.27	Approve								
		6	4			REAR BUMPER CLIP			Necessary	3		25		9	Approve								
		7	1			REAR O/S BUMPER BRACKET			Repair	0	0	0	0	0	Deny								
		8	2			REAR O/S BUMPER SIDE BRACKET			Repair	0	0	0	0	0	Deny								
		9	1			REAR O/S FENDER AIR DUCT			Serviceable	0	0	0	0	0	Deny								
		10	1			REAR END PANEL - OUTER			Bent	309.25		25		231.94	Approve								
		11	1			O/S TAILLAMP			Cracked	286.9		25		215.18	Approve								

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ration

Parts & Labour

ajayc@cs.wisc.edu

Summary

SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<div><div></div><div>1</div></div>	DAYS OF REPAIR:5 DAYS	Approve			<div><div></div><div></div></div>
<div><div></div><div>2</div></div>	REAR BUMPER REVERSE SENSOR	Approve	200	DENIED	<div><div></div><div></div></div>
<div><div></div><div>3</div></div>	REAR W/5 GLASS SEALANT	Approve	40	NECESSARY	<div><div></div><div></div></div>
<div><div></div><div>4</div></div>	TAIL GATE LOCKER STICKER	Approve	15	NECESSARY	<div><div></div><div></div></div>

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Fees	Parts & Labour	Miscellaneous	Summary	Claim Amount
Claim Amount		\$3,832.72							\$3,832.72
CATEGORY		ESTIMATE			REVISED AMOUNT				
Spare Parts		\$2,267.72			\$2,267.72				
Labour		\$1,310.00			\$1,310.00				
Miscellaneous		\$255.00			\$255.00				

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Radio	Parts & Labour	Miscellaneous	Summary	Claim Amount	\$3,250.00
Claim Amount		\$3,250.00								
CATEGORY		ESTIMATE		REVISED AMOUNT						
Miscellaneous		\$3,250.00		\$3,250.00						