

From (Person): Marcel ASSIGNMENT (Office)

From (Person): Serene Ter of FCI Date/Time: 5:50pm @ 15/11/18

Estimated Cost: _____ Bill to: _____

OD: (P) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FZ1746S Insured: SHD 3329S

at Workshop no: Unique Motorsports Tel: 6292 5578

of 11 Tennyson Lane

Policy No: 115072701MFSH Claim No: D18000330MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 31/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS wp?

R.O.D. Endorsement: _____

Date/Time: 9:04am @ 16/11/18 Person Contacted: Alvin

Veh: (IN) OUT

Date/Time: _____ Action/Instructions: (✓) FCI

FZ1746S -X

SHD 3329S - NA / CFI18000011/k4

D.O.A: 10/01/2018

19/11/18 @ 3:27pm revised to Serene by email

MV: \$2800 (est); LTA: 1243; NV: \$1557

Quintessence mercus

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FZ 17465
 at Workshop m/s: unique m/s
 of: _____
 Insured: _____
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh.: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 2800
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

27/4/2020
 Vehicle: IN / OUT

Veh No: FZ 17465 Yr Regn: 4 05
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda wave C.C. 125
 Colour: white A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 45002 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NF125MP0037330
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 70/90-17
 R: 80/90-17
 BS / BN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 3.12/17 D.O.I. 16/1/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
L.R. N/S, O/S only
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2 yrs 4 mths.

9/2/18 L/S 1500 confirmed with A/Via (Red to 1004, 40%)

RECEIVED 09 FEB 2018

Date/Time: File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee
 Transportation

110
 50

65

225

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Inv (\$)
☐ : Weekend (\$)

Report Format:

Lump Sum / I.B. (\$)

7p
150



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000835/Uqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3329S	Veh. Inspected	FZ 1746S
Policy No.	1700059280	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	15/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/12/2017	Inspection Date	16/01/2018
Survey held at	UNIQUE MOTORSPORTS 1 KAKI BUKIT AVE 6 #02-54 AUTOBAY KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000330MFSH

Date: 19 January 2018

Our Ref: CS/FCI18000835/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FZ 1746S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/01/2018 at the premises of M/s UNIQUE MOTORSPORTS, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,504.00</u>
Revised Estimate Amount	: S\$ <u>1,875.40</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the front portion, n/s & o/s body.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Policy Type: OD / (TP) TP RES / TL / EVA

Typist

Y-Date	N-Date
--------	--------

C Excess

N	Des.of Damages
---	----------------

C Resurvey photo Uploaded

Date _____

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	15-01-2018	Our Ref No. D18000330MFSH
Accident Date	31-12-2017	Claim Type. Third Party
Insured Vehicle	SHD3329S	Third Party Vehicle. FZ1746S
Survey Location	11 TANNERY LANE	
Contact Person.	ALVIN KOH	
Contact No.	6292 5578/ 0	Fax No. 6295 5579
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	UNIQUE MOTORSPORTS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232776)



PRI Documents



Close



PRI Header Details

Claim No	D18000330MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & UNIQUE M
Workshop Name	UNIQUE MOTORSPORTS PTE LTD (Contact Person : ALVIN KOH)	Survey Location & Contact Details	11 TANNERY LANE Mobile: 0 , Phone: 6292 5578 , Fax: 6295 5579 EmailId: ALVIN@UNIQUEMOTORSPORTS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3329S	TP Vehicle No	FZ1746S
PRI Recieved Date	15-01-2018 07:20:22 PM	Surveyor Appointed Date	15-01-2018 05:49:10 PM	Surveyor Accept Date	16-01-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	16-01-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 19 January 2018 3:27 PM
To: 'Claim Workflow System'; assignments
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000330MFSH/1
Attachments: CSFCI18000835Uqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of FZ 1746S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 16 January 2018 2:04 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000330MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 15 January, 2018 5:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000330MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7910H
Vehicle Details	
Vehicle No.:	FZ1746S
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	WAVE 125R A
Primary Colour:	Green
Manufacturing Year:	2005
Engine No.:	NF125MPE0037330
Chassis No.:	NF125MP0037330
Maximum Power Output:	-
Open Market Value:	\$1,642.00
Original Registration Date:	28 Apr 2005
First Registration Date:	28 Apr 2005
Transfer Count:	2
Actual ARF Paid:	\$247.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	<u>27 Apr 2020</u>
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,643.00
COE Rebate Amount:	\$1,243.00
Total Rebate Amount:	\$1,243.00
Message Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Jan 2018

OK

Honda Wave 125

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda Wave 125 (/listing/usedbike/model/honda-wave-125/)
Engine Capacity	125cc
Classification	2B
Registration Date	25/01/2005
COE Expiry Date	24/01/2020 (2 years left)
Mileage	47451km
No. of owners	-
Type of Vehicle	Cubs (/listing/usedbikes/listing/?bike_type=3)

Price: SGD\$2500

Details

Honda Wave 125 for sale. Welcome trade in. Loan available. Ambra Enterprises is located at Blk 5034 Ang Mo Kio Industrial Park 2 #01-327.



Similar Bikes

[View All \(/listing/usedbikes/listing/\)](/listing/usedbikes/listing/)



UNIQUE MOTORSPORTS PTE LTD

11 Tannery Lane Singapore 207930 (Head Office)
 1007/1009 Serangoon Road Singapore 328168 (Show Room)
 1 Kaki Bukit Ave 6 #02-54/55 Autobay @ Kaki Bukit Singapore 417883
 48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586
 280 Woodlands Industrial Park E5 #01-43 Harvest Singapore 757322

Tel: 6292 5578 (3 lines) Fax: 6295 5579
 Tel: 6341 5378 (3 lines) Fax: 6341 7379
 Tel: 6844 6378 (3 lines) Fax: 6844 6379
 Tel: 6515 4978 (3 lines) Fax: 6515 4979
 Tel: 6339 2178 (3 lines) Fax: 6339 3379

Date: 13/01/2018

Make / Model: Honda Wave 125

Registration No: FZ1746S

Damage Assessment

S/N	Description	Condition	Qty	Unit Price	Total Price	
1	FRONT COWLING	BROKEN	1	\$60.00	\$60.00	SW
2	FRONT MUDGUARD	BROKEN	1	\$46.00	\$46.00	SW
3	HEADLAMP	GRAZED	1	\$79.00	\$79.00	CH
4	HEADLAMP STAY	DEFORM	1	\$56.00	\$56.00	CH
5	FRONT SIGNAL - L/H	GRAZED	1	\$49.00	\$49.00	SW
6	FRONT SIGNAL - R/H	GRAZED	1	\$49.00	\$49.00	SW
7	MIRROR - R/H	NECESSARY	1	\$32.00	\$32.00	SW
8	MIRROR - L/H	NECESSARY	1	\$32.00	\$32.00	SW
9	METER CABLE	NECESSARY	1	\$26.00	\$26.00	Dye
10	THROTTLE CABLE	NECESSARY	1	\$28.00	\$28.00	Dye
11	HANDLEBAR	BENT	1	\$53.00	\$53.00	CH
12	HANDLE BAR BRACKET	BENT	1	\$46.00	\$46.00	CH
13	HANDLE BAREND	NECESSARY	1	\$18.00	\$18.00	CH
14	HORN ASSY BRACKET	NECESSARY	1	\$35.00	\$35.00	CH
15	STEERING CONE - UPPER	NECESSARY	1	\$34.00	\$34.00	CH
16	STEERING CONE - LOWER	NECESSARY	1	\$37.00	\$37.00	CH
17	FORK OIL SEAL	NECESSARY	2	\$22.00	\$44.00	CH
18	FORK DUST COVER	NECESSARY	2	\$21.00	\$42.00	CH
19	FORK OIL (15WT)	NECESSARY	1	\$33.00	\$33.00	CH
20	FUEL CORK	NECESSARY	1	\$27.00	\$27.00	CH
21	BRAKE LEVER	GRAZED	1	\$25.00	\$25.00	SW
22	IGNITION SWITCH ASSY	NECESSARY	1	\$95.00	\$95.00	CH
23	FRONT RIM	NECESSARY	1	\$160.00	\$160.00	CH
24	FRONT DISC BRAKE	NECESSARY	1	\$116.00	\$116.00	CH
25	FOOTREST RUBBER - R/H	GRAZED	1	\$24.00	\$24.00	CH
26	BRAKE PEDAL	NECESSARY	1	\$42.00	\$42.00	CH
27	REAR FOOTREST RUBBER - R/H	GRAZED	1	\$28.00	\$28.00	CH
28	FOOTSTEP BAR	WARPPED	1	\$62.00	\$62.00	CH
29	IU UNIT	NECESSARY	1	\$156.00	\$156.00	CH
30	IU UNIT BRACKET	NECESSARY	1	\$15.00	\$15.00	CH
31	FRONT BASKET	NECESSARY	1	\$30.00	\$30.00	CH
32	REAR BOX	GRAZED	1	\$120.00	\$120.00	CH

is hereby notified
 that the above
 is subject to the terms and conditions of the insurance policy
 and that the assessment is made on a "Without Prejudice" basis
 and that the assessment is subject to the final approval of the Insurance Company

33	FORK ALIGNMENT	NECESSARY	1	\$120.00	\$120.00
34	FRAME ALIGNMENT	NECESSARY	1	\$250.00	\$250.00
35	RESPRAY FRONT COWLING	NECESSARY	1	\$60.00	\$60.00
36	RESPRAY FRONT MUDGUARD	NECESSARY	1	\$60.00	\$60.00
37	PERFORM ELECTRICAL CHECK	NECESSARY	1	\$20.00	\$20.00
38	TOWING FROM ACCIDENT SCENE TO WORKSHOP	NECESSARY	1	\$35.00	\$35.00
39	LABOUR TO REPLACE PARTS DUE TO ACCIDENT	NECESSARY	1	\$260.00	\$260.00

Sub Total \$2,504.00

GST 7% \$175.28

Grand Total \$2,679.28

50
240
40
40
X
✓
✓



UNIQUE MOTORSPORTS PTE LTD
GST Reg. No. 200907910H
11 Tannery Lane
Singapore 347774
Tel / Fax: 6292 5578 / 6295 5579

Prepared By: Alvin Koh

7-1366
128.4

not Admit
LM
↓ / 5 = 1500/-
6 day.
16/1/18
negotiate TOTAL LOSS?
John H. Atkinson
Tel. 67418438



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000835/Uqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3329S	Veh. Inspected	FZ 1746S	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D18000330MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA WAVE	c.c	125	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	NF125MP0037330	Colour	WHITE	
Odometer	45082	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90-17	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-17	DUNLOP	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION,N/S AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2017	Inspection Date	16/01/2018	
Survey held at	UNIQUE MOTORSPORTS 1 KAKI BUKIT AVE 6 #02-54 AUTOBAY KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FZ 1746S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT COWLING	BROKEN	60.00	60.00
1	FRONT MUDGUARD	BROKEN	46.00	46.00
1	HEADLAMP	CRACKED	79.00	79.00
1	HEADLAMP STAY	BENT	56.00	56.00
1	FRONT SIGNAL-L/H	BROKEN	49.00	49.00
1	FRONT SIGNAL-R/H	BROKEN	49.00	49.00
1	MIRROR-R/H	BROKEN	32.00	32.00
1	MIRROR-L/H	BROKEN	32.00	32.00
1	METER CABLE	DAMAGED	26.00	26.00
1	THROTTLE CABLE	DAMAGED	28.00	28.00
1	HANDLEBAR	BENT	53.00	53.00
1	HANDLE BAR BRACKET	BENT	46.00	46.00
1	HANDLE BAREND	BENT	18.00	18.00
1	HORN ASSY BRACKET	BENT	35.00	35.00
1	STEERING CONE-UPPER	BENT	34.00	34.00
1	STEERING CONE-LOWER	BENT	37.00	37.00
2	FORK OIL SEAL @\$22.00	NECESSARY	44.00	44.00
2	FORK DUST COVER @\$21.00	NECESSARY	42.00	42.00
1	FORK OIL (15WT)	NECESSARY	33.00	33.00
1	FUEL CORK	CRACKED	27.00	27.00
1	BRAKE LEVER	SCRATCHED	25.00	25.00
1	IGNITION SWITCH ASSY	CRACKED	95.00	95.00
1	FRONT RIM	BENT	160.00	160.00
1	FRONT DISC BRAKE	BENT	116.00	116.00
1	FOOTREST RUBBER-R/H	TORN	24.00	24.00
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	42.00	-
1	REAR FOOTREST RUBBER-R/H	TORN	28.00	28.00
1	FOOTREST BAR	BENT	62.00	62.00
1	IU UNIT BRACKET	TO REPAIR SEE LABOUR	15.00	-

Report Ref No. CS/FCI18000835/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BASKET	BENT	30.00	30.00
	LESS 10% DISCOUNT		-	-136.60
			1,423.00	1,229.40
	<u>SPECIAL NETT ITEMS</u>			
1	IU UNIT (SN)	CRACKED	156.00	156.00
1	REAR BOX (SN)	CUT	120.00	120.00
			276.00	276.00
	<u>LABOUR</u>			
	FORK ALIGNMENT.		120.00	50.00
	FRAME ALIGNMENT.		250.00	240.00
	RESPRAY FRONT COWLING.		60.00	40.00
	RESPRAY FRONT MUDGUARD.		60.00	40.00
	PERFORM ELECTRICAL CHECK.	NOT NECESSARY	20.00	-
	TOWING FROM ACCIDENT SCENE TO WORKSHOP.		35.00	35.00
	LABOUR TO REPLACE PARTS DUE TO ACCIDENT.INCLUSIVE OF THE REPAIR OF BRAKE PEDAL AND IU UNIT BRACKET.		260.00	260.00
			805.00	665.00
	GRAND TOTAL		2,504.00	2,170.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/FCI18000835/Uqd3n2

MARKET VALUE: \$2,800.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,243.00=NETT VALUE: \$1,557.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.