

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 5349B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	CLIP BUMPER (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	FACE KIT, REAR BUMPE (SN) (CONSISTENT)	DEFORMED	639.00	639.00
1	COVER, RR BUMPER (SN) (CONSISTENT)	NOT NECESSARY	17.10	-
1	BRKT,R/BMPR FACE SUP (SN) (CONSISTENT)	NECESSARY	14.40	14.40
1	BRKT,R/BMPR FACE SUP (SN) (CONSISTENT)	NECESSARY	14.40	14.40
1	REINFORCEMENT, RR BUM (SN) (CONSISTENT)	* CHECK	198.00	-
1	REINFORCEMENT, RR BUM (SN) (CONSISTENT)	BENT	76.50	76.50
1	MARK, THREE-DIA (SN) (CONSISTENT)	NECESSARY	44.10	44.10
1	MARK - EX (SN) (CONSISTENT)	NECESSARY	36.00	36.00
1	MARK, LANCER (SN) (CONSISTENT)	NECESSARY	48.60	48.60
1	CLIP, SPLASH SHIELD (SN) (CONSISTENT)	NECESSARY	2.70	2.70
1	CLIP, COVER (SN) (CONSISTENT)	NECESSARY	18.00	18.00
1	REAR NUMBER PLATE WITH CASING (SN) (CONSISTENT)	BENT	50.00	50.00
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	280.00	280.00
1	C&C LOGO (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	MIVEC EMBLEM (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			1,533.80	1,318.70
	LABOUR			
	TO REPLACE REAR END PNL, REAR REINFORCEMENT, REAR BUMPER ETC STRAIGHTEN, PERFORM, ALIGN ON REPAIR ACCIDENT AFFECTED AREAS.		2,400.00	1,200.00
	TO CHECK LIGHTING & WIRING ON REAR ACCIDENT AFFECTED AREAS.		80.00	60.00
	TO REMOVE AND RE-INSTALL REAR CARPETS & UPHOLSTERY FOR GIVE AWAY TO REPAIR ON REAR ACCIDENT AFFECTED AREAS.		600.00	300.00
	SPRAY PAINTING ON REAR ACCIDENT AREAS.		2,520.00	1,260.00
	TO APPLY SEALANT ON REAR ACCIDENT AFFECTED AREAS.		200.00	100.00
			5,800.00	2,920.00
	GRAND TOTAL		7,333.80	4,238.70

Report Ref No. CC4/ASM18000873/Gjb3s2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,000.00
(TO ITS PRE-ACCIDENT CONDITION)		
(REPAIR COST NOT CONCLUDE)		
(EXCLUDE CHECK ITEMS S\$198.00 NETT)		

Report Ref No. CC4/ASM18000873/Gjb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

HO LEONG CHUAN

**Automotive Assessor** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.