

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 45462  
Date Estimated : 10/01/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Fang Deqi  
28 Huddington Avenue

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 557598

| REGN NO     | CHASSIS NO     | REGN DATE  | MODEL | MILEAGE |
|-------------|----------------|------------|-------|---------|
| SKH6048B    | DX50743        | 28/12/2012 | 520iA | 0       |
| DESCRIPTION | ORIGINAL PRICE | DISC. %    | NETT  |         |

| DESCRIPTION             | UNIT PRICE | QTY  | DISC. % | NETT  |
|-------------------------|------------|------|---------|-------|
| # COVERING REAR RIGHT * | 84.20      | 1.00 |         | 84.20 |
| # PLUG BLACK D=5MM *    | 0.90       | 7.00 |         | 6.30  |

*Handwritten notes: 799-6, de, nec*

|                        |       |
|------------------------|-------|
| Total Labour :         |       |
| Total Parts :          | 90.50 |
| Total Labour & Parts : | 90.50 |