

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000909/T1vd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 05-02-2018 Code: FCI2		
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 3679Y	Veh. Inspected	SJK 8068B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D18000546MFSH	Excess (\$)	0.00	
	Assign From	TEO SWEE KEONG	Assign Date	15/01/2018	
2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN GOLF GT	c.c	1390	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	WVWZZZ1KZ9U010502	Colour	BLACK	
	Odometer	277510	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
	L/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
	R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
	L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	12/01/2018	Inspection Date	17/01/2018	
	Survey held at	eld at VOLKSWAGEN GROUP SINGAPORE PTE LTD			
		247 ALEXANDRA ROAD SINGAPORE 159934			
5a.	. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				