



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000928/Avbn2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-03-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2399L	Veh. Inspected	PA 9715S
Policy No.		Coverage (\$)	0.00
Claim No.	SHA 2399L (DOA: 11/1/2018)	Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	15/01/2018

### 2. Vehicle Particulars & Condition

Make & Model	NISSAN URVAN	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JN1TG4E25Z0787277	Colour	BLUE
Odometer	146029	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	11/01/2018	Inspection Date	16/01/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------