

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1021H

DATE 15/1/2018

MAKE :

MODEL : HYUNDAI SONATA

Ang Asia - 4S IS

LKK - Calvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover ?			\$ 185.80	
	Rear Bumper Protector (RH) ✓			\$ 38.00	
	Rear Fender (RH) <i>x repair</i>			\$ 1,935.90	
	Rear Fender Inner Lining (RH) <i>x</i>			\$ 74.10	
	Rear Windscreen Moulding <i>x</i>			\$ 60.00	
	SUB TOTAL			\$ 3,514.90	
	LESS 20%			\$ 702.98	
	DISCOUNTED TOTAL			\$ 2,811.92	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
	Rear Windscreen Sealant <i>x</i>			\$ 46.00	Nett
				\$ 431.70	
	Labour Charge			<i>400</i>	
	Panel Beating			\$ 850.00	<i>360</i>
	Spray Painting Charge			\$ 400.00	
	Wiring Charge			\$ 50.00	<i>x</i>
	Tuff Kote			\$ 50.00	<i>x</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	<i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00	<i>x</i>
	Remove/Refix Reverse Sensor			\$ 120.00	<i>20</i>
	TOTAL LABOUR			\$ 1,740.00	
	ESTIMATE TOTAL			\$ 4,983.62	

Calvin LKKK
15/1/18 150 hrs
3 Days
4S
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.