

Assigned To: Marcus ASSIGNMENT (Office)

From (Person): Rachel Tan of GAI Date/Time: 16/01/2018 @ 2.51pm

Estimated Cost: _____ Bill to: _____

OD ☒ WS / IP RES / OD RES / EXA / INV / MV / CS

To Inspect Vehicle No: GBC 8181T Insured: _____

at Workshop no: Hock Weh Motor Workshop Tel: 6441 5655
or Blk 3011, Bedok North Ave 4 #01-2008

Policy No: _____ Claim No: C1MDMYC000002338

Sum Insured: _____ Excess: 18A 600

Make of Veh: _____ Date: 13/01/2018

Client's Record: _____ 17/01/2018

CA ☒ REV / REP. / REV 24 HRS

RECD Endorsement: _____

Date/Time: 3:04pm @ 16/01/18 Person Connected: Anysia Status: ☒ OUT

Date/Time: _____ Action/Description: ☒ _____

GBC 8181T - 01/GAI18000976/41d302/1116 12/01/2018

17/1/2018 revert na menmen

17/1/2018 @ 5:04pm - inform by Rachel authorise repair

17/1/2018 - 5:14pm - authorise repair. inform Anysia.

GAI

Date 17/01/2018

GBC 8181 T

10/16

Estimated Cost

① TR MS TR RES OD RES EVALUATION

Thru Report Verbal GBC 8181 T
Huck Wah Motor Workshop
Blk 3011, Bedok North Ave 4 #01-2008

Insured

Policy No

Damage

Sum Insured

Excess


TBA

Damage Record

Make of Car

Policy Condition

Remark: The car had commenced its repair at the time of inspection.



Salvage/Market Value

68

DAC Accident Report

Consistent? Yes or No

GIA - PR Seen

Consistent? Yes or No

Est. Repairs

A

days

Repair Yes or No

Est. Sum

131

days

Repair Yes or No

OD

REP

REP. 24 HRS

94730

Date

Person Contacted

Vehicle IN/OUT

The UO Chassis/frame Body Structure affected due to collision

Date Time

Person Inspection

Syris 94730

LTA 40012

Damage consistent but no detail for front vehicle? for vehicle of A

7/2/18 confirmed final by 7230.70 with Angie. (Red: 84049.75; 52%)

Double check DVA: Should be 13/10/2018

REPAIR WORK COMPLETED 2018

Pre-File Report



Pre-File Report

Final Report

8/2 Typist

Days Of Repair

8

Resurvey No. of TOL

1

Survey Fee

450

Add Fee



One Visit

Two Visits

Three Visits

Four Visits

Five Visits

Receipt Printing

OD

Printed

0

7230.70

Underwritten by Angie

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18000976/Utd3

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 16-01-2018



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	GBC 8181T
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From RACHEL TAN	Assign Date	16/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/01/2018	Inspection Date	16/01/2018
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Tuesday, 16 January 2018 2:51 PM
To: assignments
Subject: FW: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Tuesday, 16 January 2018 2:34 PM
To: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018

Hi Hock Wah

Noted on the OD claim request, please provide estimates.

Hi LKK

Please assist on OD survey, too.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Hock Wah Motor Pte Ltd [<mailto:motor@hockwah.com.sg>]
Sent: Monday, January 15, 2018 4:12 PM
To: General Claims <GeneralClaims@sg.gaig.com>
Subject: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018

Dear sir/madam

Attached herewith our client's GIA report that claim Own Damage Claim.

Please arrange survey for above mention vehicle at Bedok workshop.

Thank you.

Best Regards

Anysia Foo

Senior Claims Advisor

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977
Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 17 January 2018 4:12 PM
To: 'Tan, Rachel'; SUR
Subject: RE: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018
Attachments: PRELI ADVISED GBC 8181T.pdf; Full page photo.pdf

Dear Sir/Madam,

Enclosed preliminary revised and photograph of vehicle **GBC8181T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Wednesday, 17 January 2018 3:26 PM
To: SUR <sur@lkkauto.com>
Subject: FW: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018

Hi
Await your OD report once available.

Thanks,
Rachel

From: Hock Wah Motor Pte Ltd [<mailto:motor@hockwah.com.sg>]
Sent: Wednesday, January 17, 2018 11:36 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: admin-a@lkkauto.com
Subject: RE: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018

Dear Rachel

Surveyor Marcus from LKK has been surveyed above mention vehicle on 17/01/2018.

Please revert on authorisation.

Thank you.

Best Regards

Anysia Foo

Senior Claims Advisor

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 17/1/2018

Our Ref: CS/GAI18000976/Utd3

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. GBC 8181T.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/01/2018 at the premises of M/s Hock Wah and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 15,280.45</u>
Revised Estimate Amount	: <u>S\$ 5,586.20</u>
Check" Items Amount	: <u>S\$ 5,491.25</u>
Market Value	: <u>S\$ 68,000.00</u>
LTA Reimbursement Value	: <u>S\$ 40,012.00</u>
Nett Value	: <u>S\$ 27,988.00</u>

Description of Damage:

The vehicle sustained at the front portion.



Comments/ Present Status:

Damage consistent
Repair cost Economical
Repair on Part by part

Yours faithfully

Marcus
Motor Surveyor

Denise Tay (LKKAUTO)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 17 January 2018 5:04 PM
To: Denise Tay (LKKAUTO); SUR
Subject: RE: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018

Hi Denise

Please proceed as per your recommendation
OD excess \$600/-

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, January 17, 2018 4:36 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>; SUR <sur@lkkauto.com>
Subject: RE: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018

Dear Rachel,

Enclosed estimate marking.

Kindly have your authorization.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 17 January 2018 4:12 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; SUR <sur@lkkauto.com>
Subject: RE: OWN DAMAGE CLAIM_GBC8181T_DOA:12/01/2018

Dear Sir/Madam,

Enclosed preliminary revised and photograph of vehicle **GBC8181T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car


Directory

Products

Articles

Forum

Tools & Tips



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more

SGCARMART CONNECT
BRIDGING BUYERS & SELLERS

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

BMW 523i Highline. PML Car. Highline Model.



Low Mileage. Regular Service
And Well Maintained. Selling To
Relocated.
Direct Owner StarAd



Browse by Category

Sort by Date Posted 20 results/page

15 vehicles

Dyna

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Dyna		Any	Any	2016	Any	Any	Any	Available

**Toyota Dyna 150****Fuel Type:** Diesel**\$67,888****\$8,280 /yr****29-Mar-2016****2,982 cc****-****Truck****Available**

1 Owner, Best Selling Toyota Dyna 10 Feet Lorry Come With Canopy. 100% Loan Available, \$0 Drive Away, High Trade In. Act Fast, Don't Miss It, Call Now.

Posted: 17-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****Fuel Type:** Diesel**\$69,800****\$8,180 /yr****29-Jul-2016****2,982 cc****-****Truck****Available**

1 Owner, Owner Going To Oversea To Work So Ask Me To Help Him To Sell, He Hope The Dyna Can Entrust To Someone Can Cherish It, Come And View The Smooth And Buttery Drive That Can Carry You With Your D...

ABWIN Bus Pte Ltd

Posted: 16-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****Fuel Type:** Diesel**\$77,800****\$8,790 /yr****23-Nov-2016****2,982 cc****-****Truck****Available**

Almost New! 100% Loan Available! Ready Stock! Color Silver, White And Blue! Any Trade In Welcome! Limited Stock Only! Call Now To Fix An Appointment!

ABWIN Bus Pte Ltd

Posted: 16-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****Fuel Type:** Diesel**\$63,800****\$7,820 /yr****15-Mar-2016****2,982 cc****-****Truck****Available**

1 Ownership Only, Maintain By Borneo Motor. Comes With Full Length Canopy & Fully Covered Checkered Plate. Saving Of Almost 2K. SUPERB Condition, View To Appreciate. Financing Available And Competitive I...

Posted: 15-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Buy Tyres Online!
Latest Special Offers from Tyrepack

**Toyota Dyna 150****Fuel Type:** Diesel**\$67,888****\$8,270 /yr****01-Apr-2016****2,982 cc****-****Truck****Available**

1 Owner, Best Selling Toyota Dyna 10 Feet Lorry. Like New, Showroom Condition. 100% Loan Available, \$0 Drive Away. High Trade In. Act Fast, Don't Miss It, Call Now For More Details.

Posted: 15-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****Fuel Type:** Diesel**\$79,800****\$9,020 /yr****22-Nov-2016****2,982 cc****-****Truck****Available**

Cabin Height Thermoking Freezer Worth \$16,000. Goes Up To -30 Degrees, Suitable For Ice Cream And Many Frozen Products. Almost New Condition, Come Down And View Before This Rare Beauty Disappears.

Posted: 13-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****Fuel Type:** Diesel**\$70,800****\$8,230 /yr****24-Aug-2016****2,982 cc****-****Truck****Available**

A Super Excellent Condition Dyna, Low Mileage, Only Drive For 2 Years, Look Like New, Hope To Find A True Lover To Take Over The Vehicle, With A Smooth And Buttery Drive To Carry You With Your Daily L...

ABWIN Bus Pte Ltd

Posted: 12-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 9473D

Vehicle Details

Vehicle No.: GBC8181T

Vehicle to be Exported: No

Intended De-registration Date: 17 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA DYNA 150
MANUAL

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: 1KD2657009

Chassis No.: JTFAT35Y50K207037

Maximum Power Output: -

Open Market Value: \$24,946.00

Original Registration Date: 28 Oct 2016

First Registration Date: 28 Oct 2016

Transfer Count: 0

Actual ARF Paid: \$1,248.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Oct 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10



QP Paid: \$45,589.00

COE Rebate Amount: \$40,012.00

Total Rebate Amount: \$40,012.00

The information contained herein is correct as at 17 Jan 2018

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	13/01/2018 13:59
Date Of Accident	12/01/2018 09:20
Exact Location Of Accident	CTE TWDS CITY AFT BRADDELL EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBC8181T
Insured/Policyholder	
Name Of Registered Owner	IBUILDERS PTE LTD
Co Reg No	200509473D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	MT20175620
Driver	
Name of Driver	WEI LIWEN
Passport No/FIN	F2668786K
Date Of Birth	17/02/1979
Occupation	OUTDOOR
Date Of Driving Pass	02/06/2010
Driving Experience	7 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91189966
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along CTE towards (city after Brackley exit). The vehicle in front of me came to a stop suddenly, I could not stop in time and collided onto vehicle (B). When I got down, I realised I was involved in a 3 car chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6724 0010 Fax (65) 6724 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S646888296 / GST Reg. No.: M409917736

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MNA118006637 Vehicle Registration No: QBC8181T
Name (as shown in NRIC): WEI LIWEN NRIC/FIN/Passport No: F2668786K
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate 349217
Address: 45 KALLANG PUDDING RD #10-11 Singapore()
Contact (Tel): _____ Mobile No.: 91189966
Email Address: _____
Date of Accident: 12/01/18 Time of Accident: 09:00
Place of Accident: CTE TOWNS CITY AFT BRADDELL EXIT
Insurance Company: GREAT AMERICAN

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMEND DATE OF ACCIDENT

Policyholder / Driver's Signature
Date: 08/02/18

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____
Date: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 13/01/2018 13:59
Date Of Accident 13/01/2018 09:20
Exact Location Of Accident CTE TWDS CITY AFT BRADDELL EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBC8181T
Insured/Policyholder
Name Of Registered Owner IBUILDERS PTE LTD
Co Reg No 200509473D
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-NOPHONE

Vehicle Particulars

Manufacturer TOYOTA
Model DYNA
Exact Purpose for which vehicle was being used at time of accident WORKING
Are you claiming under your own insurance policy for repair to your vehicle? YES
If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number

Cover Note Number MT20175620

Driver

Name of Driver WEI LIWEN
Passport No/FIN F2668786K
Date Of Birth 17/02/1979
Occupation OUTDOOR
Date Of Driving Pass 02/06/2010
Driving Experience 7 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91189966
Fax Number
Contact Number
EMail Address NOEMAIL

Address 45 KALLANG PUDDING RD
#10-11
Postcode 349317
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HOCK WAH MOTOR WORKSHOP PTE LTD

3011 BEDOK INDS PARK E

#01-2008

[NEED PO]

SINGAPORE 489977

TEL : 64415655 FAX : 62438121

ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934



Dept Direct: 6417 8791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9911

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade, Fuel Filter, Air Filter, Oil Filter, Spark plug, Ignition Coil, Timing Belt, Water Pump, etc.

Spark plug, Ignition Coil, Timing Belt, Water Pump, etc.

TAX INVOICE : AR201801-10627**DATE : 18/01/2018****CUSTOMER ID : HOC001****VEH REG. NO. : GBC8181T****TERMS : 30 days****PO NO. : 00025180****PAGE NO. : Page 1 of 1****CURR. : SGD**

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53114-37010 KDY231	FRT GRILLE ASSY	PA PI.2-G1-050	1	155.00	155.00
2. T75315-37010/1 KDY231	FRT EMBLEM	PA PI.2-J1-08I.	1	35.00	35.00
3. T90467-10161/2 RAV4,LY235DYNA	CLIPS-RAD GRILLE-LOW	PA PI.2-P1-05D	8	2.50	20.00
4. T55078-37070 LY235 /231	FRT WIPER PANEL	PA PL2-G1-050	1	110.00	110.00
5. T55700-37310/110 KDY231	FRT PANEL	PA PI.2-C1-010	1	330.00	330.00
6. T53928-37010/1 LY235	FRT PANEL CENTER GARNISH	PA PI.2-I11-10A	1	135.00	135.00
7. T81130-37200/1 KDY231	HEAD LAMP RH	PA PI.2-G1-040	1	245.00	245.00
8. T75311-25070/90 LY235	FRT PANEL (DYNA) EMBLEM	PA PL2-K1-06N	1	45.00	45.00
9. T53921-25010/1 LY235 DYNA'02	FRT SIDE GARNISH RH	PA PI.2-J1-04I.	1	65.00	65.00

SUB-TOTAL : 1,140.00

ADD GST 7.00 % 79.80

E. & O.E

TOTAL AMOUNT SGD : 1,219.80

[P] 05/02/2018 8:59:37


[E] 18/01/2018 9:02:23AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : SAM



* AR201801-10627 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HOCK WAH MOTOR WORKSHOP PTE LTD

3011 BEDOK INDS PARK E

#01-2008

[NEED PO]

SINGAPORE 489977

TEL : 64415655 FAX : 62438121

ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

Dept Direct: 6417 9791 / 6745 5939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9

Wiper blades: per 1000 on 1 per 1000 on 1 per 1000 on 1
Per 1000 on 1 per 1000 on 1
Spunk plug: 1000 on 1 per 1000 on 1 per 1000 on 1

TAX INVOICE AR201801-10628
DATE : 18/01/2018
CUSTOMER ID : HOC001
VEH REG. NO. : GBC8181T
TERMS : 30 days
PO NO. : 00025180
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53801-37020/1 LY235 DYNA'02	SIDE PANEL RH	U1	1	110.00	110.00
2. T53119-37080-B0 KDY231	FRONT GRILLE RUBBER	U1	1	28.00	28.00
3. T85221-37250 KDY231	WIPER ARM LH	U1	1	100.00	100.00
4. T55301-37012-B1 KDY231	DASHBOARD	U1	1	550.00	550.00

SUB-TOTAL : 788.00
ADD GST 7.00 % 55.16

E. & O.E TOTAL AMOUNT SGD : 843.16

[E] 18/01/2018 9:02:40AM

[P] 05/02/2018 9:00:08


Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : SAM



* AR201801-10628 *

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

JAE AUTO PTE LTD
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 5305 9610



Dept Direct: 6305 9611



Dept Direct: 6417 9792



Dept Direct: 6417 9793



Dept Direct: 6417 9794



Dept Direct: 6417 9795



Dept Direct: 6417 9796



Dept Direct: 6417 9796



Dept Direct: 6417 9796



Dept Direct: 6417 9796




Dept Direct: 6417 9796



Dept Direct: 6417 9796



Dept Direct: 6417 9796



Dept Direct: 6417 9794



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795

Alphas blades: 14V8 (4000cc) 16V8 (4000cc) 16V8 (4000cc) 16V8 (4000cc)
Turbo: 16V8 (4000cc) 16V8 (4000cc) 16V8 (4000cc) 16V8 (4000cc)
Spark plug: 14V8 (4000cc) 16V8 (4000cc) 16V8 (4000cc) 16V8 (4000cc)

HOCK WAH MOTOR WORKSHOP PTE LTD

3011 BEDOK INDS PARK E

#01-2008

[NEED PO]

SINGAPORE 489977

TEL : 64415655 FAX : 62438121

ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

TAX INVOICE : AR201801-12749

DATE : 22/01/2018

CUSTOMER ID : HOC001

VEH REG. NO. : GBC8181T

TERMS : 30 days

PO NO. : 00025227

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T55330-25020 LY235 DYNA'02	INSTRUMENT PANEL ASSY	PA PI.2-G1-10B	1	220.00	220.00
2. T87130-25041 KDY231	AIR CON BLOWER ASSY	PA PI.2-IT1-030	1	660.00	660.00
3. T87150-25040 KDY231	HEATER UNIT	PA PI.2-M1-100	1	550.00	550.00

SUB-TOTAL : 1,430.00
ADD GST 7.00 % 100.10

E & O E

TOTAL AMOUNT SGD : 1,530.10

[P] 05/02/2018 8:58:50


[E] 22/01/2018 10:53:54AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : SAM



* AR201801-12749 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Dep't Direct: 6417 9791 / 6745 9939



Dep't Direct: 6305 9610

Dep't Direct: 6305 9611

Dep't Direct: 6417 9742



Dep't Direct: 6417 9794

Dep't Direct: 6417 9795

Dep't Direct: 6417 9796

Dep't Direct: 6417 9793

Washer blades: BMW, (Mazda), (Ford), (Kia), (Hyundai), (Honda), (Subaru), (Nissan), (Mitsubishi), (Suzuki), (Audi), (VW), (Jaguar), (Land Rover), (Volvo)

Spark plug: Nippon Denso, (Ford), (Kia), (Hyundai), (Honda), (Subaru), (Nissan), (Mitsubishi), (Suzuki), (Audi), (VW), (Jaguar), (Land Rover), (Volvo)

HOCK WAH MOTOR WORKSHOP PTE LTD

3011 BEDOK INDS PARK E

#01-2008

[NEED PO]

SINGAPORE 489977

TEL : 64415655 FAX : 62438121

ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

TAX INVOICE : AR201801-10672

DATE : 18/01/2018

CUSTOMER ID : HOC001

VEH REG. NO. : GBE8181T

TERMS : 30 days

PO NO. : 00025180

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	WT56111-37120	FRT W/S GLASS LH	MO	1	550.00	550.00
	LY235 DYNA'02 / KDY231		01-103			
2.	MLD.T56121-37030/1/25040	FRT W/S RUBBER	MO	1	110.00	110.00
	LY235 DYNA '02		1A84E			

SUB-TOTAL : 660.00

ADD GST 7.00 % 46.20

E. & O.E

TOTAL AMOUNT SGD : 706.20

[P] 18/01/2018 9:40:15AM

[E] 18/01/2018 9:39:55AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : WEI JIAN



★ A R 2 0 1 8 0 1 - 1 0 6 7 2 ★

Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 200509473D

GREAT AMERICAN INSURANCE COMPANY
NO 3 TEMASEK AVENUE
16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL : 6804 6000 FAX : 6235 2616
PH :
ATTN :

Term:

ESTIMATE BILL

Number : EB00004716
Date : 15/01/2018
Case No : AD00009506
Vehicle No : GBC8181T
Chassis : JTFAT35Y50K207037
Year of Mfr : 2016
Policy No : MT20175620
Model : TOYOTA DYNA

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT GRILLE <i>3/20</i>	1.0	155.00	(15)	178.25
2	FRONT GRILLE RUBBER <i>2000</i>	1.0	28.00	(15)	32.20
3	FRONT GRILLE EMBLEM <i>1200</i>	1.0	35.00	(15)	40.25
4	FRONT GRILLE CLIP <i>1200</i>	8.0	2.50	(15)	23.00
5	FRONT WINDSCREEN GLASS <i>3/20</i>	1.0	550.00	(15)	632.50
6	FRONT WINDSCREEN GLASS RUBBER <i>1200</i>	1.0	110.00	(15)	126.50
7	FRONT WIPER ARM RH <i>12</i>	1.0	100.00	(15)	115.00
8	FRONT WIPER ARM LH <i>300</i>	1.0	100.00	(15)	115.00
9	FRONT WIPER BLADE RH <i>12</i>	1.0	35.00	(15)	40.25
10	FRONT WIPER BLADE LH <i>12</i>	1.0	45.00	(15)	51.75
11	FRONT WIPER LINK <i>12</i>	1.0	165.00	(15)	189.75
12	FRONT WIPER MOTOR <i>12</i>	1.0	605.00	(15)	695.75
13	FRONT WIPER PANEL <i>20/1200</i>	1.0	110.00	(15)	126.50
14	FRONT WIPER SIDE GARNISH RH <i>12</i>	1.0	55.00	(15)	63.25
15	FRONT WIPER SIDE GARNISH LH <i>12</i>	1.0	55.00	(15)	63.25
16	FRONT PANEL <i>3.5/1200</i>	1.0	330.00	(15)	379.50
17	FRONT PANEL TOP CENTER GARNISH <i>300/1200</i>	1.0	135.00	(15)	155.25
18	FRONT PANEL TOP GARNISH RH <i>cut</i>	1.0	65.00	(15)	74.75
19	FRONT PANEL TOP GARNISH LH <i>12</i>	1.0	65.00	(15)	74.75
20	FRONT CABIN SHALF <i>12</i>	1.0	400.00	(15)	460.00
21	FRONT CABIN BAR <i>12</i>	1.0	385.00	(15)	442.75
22	FRONT CABIN BUSH RH <i>12</i>	1.0	220.00	(15)	253.00
23	FRONT CABIN BUSH LH <i>12</i>	1.0	220.00	(15)	253.00
24	HEADLAMP LH <i>12</i>	1.0	245.00	(15)	281.75
25	HEADLAMP RH <i>12</i>	1.0	245.00	(15)	281.75
26	FRONT CABIN MOUNTING LH <i>12</i>	1.0	220.00	(15)	253.00
27	FRONT CABIN MOUNTING RH <i>12</i>	1.0	220.00	(15)	253.00
28	CORNER PANEL LH <i>12</i>	1.0	110.00	(15)	126.50
29	CORNER PANEL RH <i>20/1200</i>	1.0	110.00	(15)	126.50
30	FRONT BRAKE BOOSTER <i>12</i>	1.0	530.00	(15)	609.50
31	FRONT BRAKE CYLINDER MASTER PUMP <i>12</i>	1.0	220.00	(15)	253.00
32	DASHBOARD <i>200/1200</i>	1.0	550.00	(15)	632.50
33	DASHBOARD CROSSMEMBER <i>cut</i>	1.0	200.00	(15)	230.00
34	DASHBOARD CENTER <i>12</i>	1.0	200.00	(15)	230.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

4018

7230-7

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4.
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 200509473D

GREAT AMERICAN INSURANCE COMPANY
NO 3 TEMASEK AVENUE
16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL : 6804 6000 FAX : 6235 2616
PH :
ATTN :

ESTIMATE BILL

Number : EB00004716
Date : 15/01/2018
Case No : AD00009506
Vehicle No : GBC8181T
Chassis : JTFAT35Y50K207037
Year of Mfr : 2016
Policy No : MT20175620
Model : TOYOTA DYNA

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
35	AIR CON BLOWER HOUSING <i>me</i>	1.0	660.00	(15)	759.00
36	HEATER HOSUING <i>me</i>	1.0	550.00	(15)	632.50
37	FRONT PANEL INNER LOWER PANEL <i>me</i>	1.0	310.00	(15)	356.50
38	FRONT PANEL LOGO - DYNA <i>me</i>	1.0	45.00	(15)	51.75
39	FRONT DOOR STICKER RH <i>NI</i>	1.0	90.00	(15)	103.50
40	FRONT DOOR STICKER LH <i>NI</i>	1.0	90.00	(15)	103.50
Nett Price - Parts Sub Total					9,870.45
41	FRONT BUMPER - REPAIR <i>me X</i>	1.0			
42	FRONT DOOR RH - REPAIR <i>me X</i>	1.0			
43	FRONT DOOR LH - REPAIR <i>me X</i>	1.0			
44	FRONT FLOOR PANEL - REPAIR <i>me X</i>	1.0			
45	FRONT DOOR REAR CENTER PANEL RH - REPAIR <i>me X</i>	1.0			
46	FRONT DOOR PILLAR LH - REPAIR <i>me X</i>	1.0			
47	FRONT DOOR PILLAR RH - REPAIR <i>me X</i>	1.0			
48	FRONT CROSS MEMBER - REPAIR <i>me X</i>	1.0			
49	FRONT CHASSIS RH - REPAIR <i>me X</i>	1.0			
50	FRONT CHASSIS LH - REPAIR <i>me X</i>	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					9,870.45
51	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	2,500.00	0 1300	2,500.00
52	SPRAY PAINT ON THE AFFECTED AREAS	1.0	2,000.00	0 1000	2,000.00
53	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0 80	180.00
54	WIRING	1.0	80.00	0 30	80.00
55	TO REMOVE & REFIT DASHBOARD	1.0	350.00	0 200	350.00
56	LABOUR TO REPAIR FRONT CHASSIS	1.0	300.00	0 400	300.00
Labour 1 Sub Total					5,410.00
SINGAPORE DOLLARS : SIXTEEN THOUSAND THREE HUNDRED FIFTY AND CENTS EIGHT ONLY					2610
Less Excess					0.00
SUBTOTAL					15,280.45
GST 7.00%					1,069.63
TOTAL					16,350.08

Date of accident : 12/01/2018 09:20 AM. This is hereby notified to the following:

E. & O. E.

- The survey is done after spray painting
- Supply of the part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Any supplementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Acknowledged by Partner

Page 2 of 2

* N = Item not subjected to GST

Issued by : Anysia



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18000976/Utd3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 14-02-2018



Code : GAI

1. Policy Particulars : OWN DAMAGE

Insured Veh.		Veh. Inspected	GBC 8181T
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000002338	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	16/01/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTFAT35Y50K207037	Colour	SILVER
Odometer	49461	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/70 R15	GOODYEAR	6 mm
L/H Front Tyre	195/70 R15	GOODYEAR	6 mm
R/H Rear Tyre	155 R12 (D)	GOODYEAR	6/6 mm
L/H Rear Tyre	155 R12 (D)	GOODYEAR	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/01/2018	Inspection Date	17/01/2018
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A) THE MARKET VALUE IS S\$68,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 8181T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT GRILLE	BROKEN	155.00	155.00
1	FRONT GRILLE RUBBER	TORN	28.00	28.00
1	FRONT GRILLE EMBLEM	NECESSARY	35.00	35.00
8	FRONT GRILLE CLIP @\$2.50	NECESSARY	20.00	20.00
1	FRONT WINDSCREEN GLASS	BROKEN	550.00	550.00
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	110.00	110.00
1	FRONT WIPER ARM RH	NOT NECESSARY	100.00	-
1	FRONT WIPER ARM LH	BENT	100.00	100.00
1	FRONT WIPER BLADE RH	NOT NECESSARY	35.00	-
1	FRONT WIPER BLADE LH	NOT NECESSARY	45.00	-
1	FRONT WIPER LINK	NOT NECESSARY	165.00	-
1	FRONT WIPER MOTOR	NOT NECESSARY	605.00	-
1	FRONT WIPER PANEL	DENTED / BENT	110.00	110.00
1	FRONT WIPER SIDE GARNISH RH	NOT NECESSARY	55.00	-
1	FRONT WIPER SIDE GARNISH LH	NOT NECESSARY	55.00	-
1	FRONT PANEL	BADLY DENTED	330.00	330.00
1	FRONT PANEL TOP CENTER GARNISH	BENT / CRACKED	135.00	135.00
1	FRONT PANEL TOP GARNISH RH	CUT	65.00	65.00
1	FRONT PANEL TOP GARNISH LH	NOT NECESSARY	65.00	-
1	FRONT CABIN SHALF	NOT NECESSARY	400.00	-
1	FRONT CABIN BAR	NOT NECESSARY	385.00	-
1	FRONT CABIN BUSH RH	NOT NECESSARY	220.00	-
1	FRONT CABIN BUSH LH	NOT NECESSARY	220.00	-
1	HEADLAMP LH	NOT NECESSARY	245.00	-
1	HEADLAMP RH	CRACKED	245.00	245.00
1	FRONT CABIN MOUNTING LH	NOT NECESSARY	220.00	-
1	FRONT CABIN MOUNTING RH	NOT NECESSARY	220.00	-
1	CORNER PANEL LH	TO REPAIR SEE LABOUR	110.00	-
1	CORNER PANEL RH	DENTED / BENT	110.00	110.00
1	FRONT BRAKE BOOSTER	NOT NECESSARY	530.00	-
1	FRONT BRAKE CYLINDER MASTER PUMP	NOT NECESSARY	220.00	-
1	DASHBOARD	BENT / TWISTED	550.00	550.00
1	DASHBOARD CROSSMEMBER	BENT	220.00	220.00

Report Ref No. CS/GAI18000976/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DASHBOARD CENTER	NOT NECESSARY	200.00	-
1	AIR CON CLOWER HOUSING	CRACKED	660.00	660.00
1	HEATER HOUSING	CRACKED	550.00	550.00
1	FRONT PANEL INNER LOWER PANEL	NOT NECESSARY	310.00	-
1	FRONT PANEL LOGO - DYNA	NECESSARY	45.00	45.00
1	FRONT DOOR STICKER RH	NOT INSURED	90.00	-
1	FRONT DOOR STICKER LH	NOT INSURED	90.00	-
	COST PLUS 15%		1,290.45	602.70
			9,893.45	4,620.70
	SPECIAL NETT ITEMS			
1	FRONT BUMPER (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR RH (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR LH (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FLOOR PANEL (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR REAR CENTER PANEL RH (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR PILLAR LH (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR PILLAR RH (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT CROSS MEMBER (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT CHASSIS RH (SN) (NPA)	NOT NECESSARY	-	-
1	FRONT CHASSIS LH (SN) (NPA)	NOT NECESSARY	-	-
			-	-
	LABOUR			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF CORNER PANEL LH, FRONT BUMPER, FRONT DOOR RH, FRONT DOOR LH, FRONT FLOOR PANEL, FRONT DOOR REAR CENTER PANEL RH, FRONT DOOR PILLAR LH, FRONT DOOR PILLAR RH AND FRONT CROSS MEMBER.		2,500.00	1,300.00
	SPRAY PAINT ON THE AFFECTED AREAS.		2,000.00	1,000.00
	TO REMOVE & REFIT WINDSCREEN.		180.00	80.00
	WIRING.		80.00	30.00
	TO REMOVE & REFIT DASHBOARD.		350.00	200.00

Report Ref No. CS/GAI18000976/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REPAIR FRONT CHASSIS.	NOT NECESSARY	300.00	-
			5,410.00	2,610.00
GRAND TOTAL			15,303.45	7,230.70

RECOMMENDED COST OF REPAIRS			7,230.70
LESS EXCESS			-600.00
NETT LIABILITY			6,630.70

Report Ref No. CS/GAI18000976/Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.