

King's Auto Spray Paint Pte Ltd
Blk 176 Sin Ming Drive #02-10
Sin Ming Autocare Singapore 575721

CHU Hui PING

Not Authoritative 15-1-18
Lily B?

Re: Estimate cost for SKMSS6P TO %OTA

SUPPLY OF PARTS:

1pc rear bumper
1pc rear bumper retainer
1pc rear bumper reflector
8pc rear bumper clips @ 3.50
1pc rear sprocket rim

Butler \$492.00 ✓
 Dr 113.00 ✓
 130.00 ✓
 Mr 28.00 ✓
 Per 680.00 ✓

 \$ 1443.00
 360.75

 \$ 1082.25

Less 25%

LABOUR:

1 Set rear bumper sensor

To check & align wheel alignment - computerise

To renew the above mentioned parts
knocking, cutting welding rear
damaged parts

Spray paintings

500. ~ 22a

500. ~ 22a

2412.25

LKK Auto Care will provide hourly
the Repair of the following:

- To insure the vehicle is safe to drive
- To insure the vehicle is ready for delivery
- Parts and labor charges on a "no fault" basis
- To insure the vehicle is ready for delivery
- No charge for towing and delivery
- Supply of parts and labor for the vehicle and
to insure the vehicle is ready for delivery

Admission: \$10.00 per hour
Sign: \$10.00