

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : 17/01/18 GRAB RENTALS 2 PTE LTD 28, SIN MING LANE, #07-71 MIDVIEW CITY SINGAPORE 573969 Attn : Tel : Fax :
---	--

Confirmed
LTS \$1650.00
LKE maras
17/01/2018 209ah

Not Allowed
 1/5 = 1650/2
 3 day
 17/1/18

Quotation No : QO18/01-1078	Quotation Date : 11/01/2018	Terms : 30 DAYS
Vehicle No : SLQ9260A	Chassis No : JM6BN22A8H0152924	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLR9682K, DATE OF ACCIDENT: 10.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR FENDER N/S <i>1</i>	1	1,175.0000	1,175.00 <i>x</i>
2	REAR FENDER INNER COWLING N/S <i>1</i>	1	146.0000	146.00 <i>x</i>
3	REAR FENDER INNER COWLING CLIPS <i>1</i>	6	5.0000	30.00 <i>x</i>
4	REAR FENDER AIR VENT N/S <i>1</i>	1	72.0000	72.00 <i>x</i>
5	REAR BUMPER <i>deep cut</i>	1	1,075.0000	1,075.00 <i>—</i>
6	REAR BUMPER SIDE RETAINER N/S <i>1</i>	1	37.0000	37.00 <i>—</i>
7	REAR BUMPER SIDE HOLDER N/S <i>1</i>	1	46.0000	46.00 <i>x</i>
8	REAR BUMPER SIDE HOLDER RIVETS <i>1</i>	4	6.0000	24.00 <i>x</i>
9	REAR WINDSCREEN GLASS WEATHERSTRIP <i>1</i>	1	68.0000	68.00 <i>x</i>
10	REAR WHEEL HUB CAP N/S <i>ground</i>	1	120.0000	120.00 <i>—</i>
11	LESS 20% (ITEM 1 - 10)	1	-558.6000	-558.60
12	REAR WINDSCREEN GLASS SEALANT <i>1</i>	1	180.0000	180.00 <i>x</i>
13	REAR WINDSCREEN GLASS SPONGE <i>1</i>	1	100.0000	100.00 <i>x</i>
14	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. TO REPAIR N/S REAR DOOR	1	850.0000	850.00 <i>400</i>
15	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	780.0000	780.00 <i>600</i>
16	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00 <i>50</i>
17	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	180.0000	180.00 <i>11</i> <i>x</i>
18	TO RUST-PROOFING OF THE AFFECTED AREAS	1	80.0000	80.00 <i>11</i> <i>x</i>
19	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	150.00 <i>11</i> <i>x</i>
20	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	120.0000	120.00 <i>60</i>

1232

985.60

2095.6

C/F 0.00

Page 1 of 2

PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 28, SIN MING LANE, #07-71 MIDVIEW CITY SINGAPORE 573969 Attn : Tel : Fax :
---	---

Quotation No : QO18/01-1078	Quotation Date : 11/01/2018	Terms : 30 DAYS
Vehicle No : SLQ9260A	Chassis No : JM6BN22A8H0152924	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLR9682K, DATE OF ACCIDENT: 10.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	4,794.40
GST(7.00%)	335.61
Total (SGD)	5,130.01

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216