

LKK:
IDAC

Date / Time :

Registered in Merimint:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :S\$

Is driver the owner?

If **NO**, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. _____

Policy No.

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :	%	Final ? Yes / No
1. General Liability		
2. Professional Liability		
3. Directors and Officers		
4. Employment Practices		
5. Fidelity and Bonding		
6. Automobile Liability		
7. Aircraft Liability		
8. Watercraft Liability		
9. Umbrella Liability		
10. Other		



INSRS:
WSP:
Tel :
Liability:
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time		STAGE		DATE / PIC	
18/1/18 VIC		Non-Reporting ltr (1st):			
		Non-Reporting ltr (2nd):			
		Non-Reporting ltr (Final):			
		Notification ltr (if non-pickup):			
		Call OE: 18/1/18 7:54 AM			
18/1/18 3:01 pm		After call ltr to OE: 18/01/18 - vic ok			
		Documentation Check List:		Handler	
				Typist	
		Notification ltr (if non-pickup)		<input type="checkbox"/>	
		After call ltr to OE:		<input checked="" type="checkbox"/>	
		Authorisation To Act:		<input checked="" type="checkbox"/>	
		Release Voucher:		<input checked="" type="checkbox"/>	
		Final Repair Bill:		<input checked="" type="checkbox"/>	
		Car Rental Invoice:		<input checked="" type="checkbox"/>	
		Towing Invoice		<input type="checkbox"/>	
		LTA / GIA:		<input checked="" type="checkbox"/>	
		Medical Bill:		<input type="checkbox"/>	
		PIR:		<input type="checkbox"/>	
		Mandate/Reject Instruction:		<input checked="" type="checkbox"/>	
		LOD		<input checked="" type="checkbox"/>	
		Payment Breakdown Form:		<input type="checkbox"/>	
		Post-Repair Photos:		<input type="checkbox"/>	
		Others:		<input type="checkbox"/>	
PRELIMINARY ADVICE		Date/Time: 18/01/18		Sent By: b3	
FINALIZATION		Date/Time:		Confirm with:	
Repair Cost: 1/18		SS 650.00 (2 days) Reduction: 77 %		Confirm by:	
				Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT		Date/Time: 21/02/18		Confirm with: MICHAEL	
Final Liability:		% 100 (Agreed / Assessed) BOLA S/N No. :		Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Repair Cost: (w/60r)		SS 695.50		CO1 KATE - ENVELO TP)	
Loss of Rental (LOR):		SS 350.46 (3 days) X \$116.82			
Loss of Use (LOU):		SS 150.00 (\$ 50 x 3 days)			
Loss of Income (LOI):		SS - (\$ x days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>		LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/> (Tick only one)		COPY SENT 21/4/18	
GIA/LTA Search		SS 2.00		KEEP ORIGINAL DOCS	
Medical:		SS -		1) Claim status: Normal/Reject/Private Settle	
Disbursement:		SS - (e.g. Tow/ Independent)		2) Report Format:	
Legal Cost		SS -		3) Survey fee: \$400.00	
Total:		SS 1,197.96		Global Sum SS: -	
FINAL PAYMENT		Date/Time:		Confirm with:	
Payee 1:		SS 1,197.96		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 2: (Strike if N.A.)		SS -		Name 1: DING AUTOMOTIVE PTG LTD	
Payee 3: (Strike if N.A.)		SS -		Name 2: -	
				Name 3: -	

Tanpoh

QBE

Date 17/01/2018

SHB4588P

2017 Jan

Estimated Cost

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Polinsbest Vehicle No SHB 4588P
Ding Automotive
31 Corporation Road

Insured

Policy No

Claims No

Sum Insured

Excess

Claims Record

Make of Ven

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Bel on Market Value

ODAC Accident Report Consistent? Yes or No

GLA / PR Seen Consistent? Yes or No

Est Repairs (days) Res: Yes or No

Lum Sur: % 3 Yr: Yes or No

QA / REV / REP. / 24 HRS 'up'

Vehicle IN / OUT

Date Person Contacted

Make

Hyundai 140

1685

Colour

Yellow

Sp Reading

207 824

Engine

CNO

1CMHLB4H4MH4098352

Gen Cond Good / Fair / Poor / Burnt

Steering Incident / Jammed / Leaked / Burnt or

Brake Incident / Jammed / Leaked / Burnt or

Mod Nil / STD / STD A / R

Tyre Size

205/60R16

R

BS / DUN / EXNOVA / GY / FS / LIZA / MID / GHTSU / RIR / SUM

TOYO / YOKO or

Tv. angle

Front

R.Ba

6

mm

R.Ba

6

L.Ba

6

mm

L.Ba

6

D.O.A

D.O.I

17/1/18 @ 1330

Survey holder

Ding Auto Corporation Rd

Des of Damages FR / REAR / OS / NS / UO / Rooftop or

The UO / Chassis frame Body Structure effected due to collision

Date / Time Action / Instruction

4/54650, 2 days
CRAB: 2,203.30 (77%)

Cost Time Fee Pass or



Prel. Report

Final Report

Days Of Repair

Resurvey No. of Trip

Estimate Fee

Transportation

Cost of Road

Cost of

Cost

Cost Time Fee Return or

Add Fee



Site Inspect

Cleaning

Repair

As per

Report Format

Up to Sum 100






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC4/QBE18001047/T1hb3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 17-01-2018	
			Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 9627D	Veh. Inspected	SHB 4588P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/01/2018	Inspection Date		
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/QBE18001047/T1hb3

Date: 18.01.2018

The Motor Claims Department
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB4588P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.01.2018 at the premises of M/s Ding Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,858.30
Revised Estimate Amount	: S\$	956.90
"Check" Items Amount	: S\$	619.60
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

MOHD, TAUFIKH
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 16 January, 2018 4:29 PM
To: assignments
Subject: FW: ACCIDENT INVOLVING SHB4588P AND SLG9627D ON 11/01/2018 - ARRANGE SURVEYOR
Attachments: SAS2339594.PDF; 3P insurance.html

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

16.01.2018 @ 4.43pm
AIX ver in
17.01.2018
Tauflich.

From: Joyce Foo [mailto:joyce.foo@qbe.com]
Sent: Tuesday, 16 January 2018 4:06 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: ACCIDENT INVOLVING SHB4588P AND SLG9627D ON 11/01/2018 - ARRANGE SURVEYOR

Our Ref. V0016096


Hi

Please assist to arrange TP survey.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Jenny Toh


Sent: Tuesday, 16 January, 2018 4:02 PM

To: Joyce Foo <joyce.foo@qbe.com>

Subject: FW: ACCIDENT INVOLVING SHB4588P AND SLG9627D ON 11/01/2018 - ARRANGE SURVEYOR

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: taxiscs@stengg.com [<mailto:taxiscs@stengg.com>]

Sent: Tuesday, 16 January, 2018 3:46 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: ACCOUNTS@DINGAUTO.SG, ADMIN@DINGAUTOMOTIVE.COM.SG

Subject: Re: ACCIDENT INVOLVING SHB4588P AND SLG9627D ON 11/01/2018 - ARRANGE SURVEYOR

Dear Jenny,

This vehicle(SHB4588P) now at 31 Corporation Road Singapore 649825 , please arrange surveyor ASAP and update liability .
vehicle is in workshop for 2 days already .

Thank you.
Best Regard
Ding Automotive PTE LTD
Alex Khong
83039588

From: Taxis Customer Service/KAS/CBG/ST Kinetics
To: jenny.toh@qbe.com, angeline.koh@qbe.com
Cc: "ACCOUNTS@DINGAUTO.SG", "ADMIN@DINGAUTOMOTIVE.COM.SG"
Date: Thu 11 Jan 2018 06:52 PM
Subject: ACCIDENT INVOLVING SHB4588P AND SLG9627D ON 11/01/2018 - ARRANGE SURVEYOR

Dear All ,


This vehicle(SHB4588P) now at 31 Corporation Road Singapore 649825 , Please arrange surveyor come to 15 Jan 2018 .

Thanks

Best Regard
Ding Automotive PTE LTD
Alex Khong
83039588

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]



[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

2/19/2018

Ding Auto Mail - SHB4588P - Finalize Amount & After Repair Photo.



Accounts Ding Auto <accounts@dingauto.sg>

SHB4588P - Finalize Amount & After Repair Photo.

Thu, Feb 15, 2018 at 11:11 AM

Taufikh (LKK Auto) <taufikh@lkkauto.com>

To: taxiscs@stengg.com

Cc: ACCOUNTS@dingauto.sg, ADMIN@dingautomotive.com.sg, vicalpeh@lkkauto.com

Hi Alex,

COR I/s \$650 , 2 days.

Regards

Taufikh

LKK Auto

From: taxiscs@stengg.com [mailto:taxiscs@stengg.com]

Sent: Friday, 19 January 2018 1:58 PM

To:taufikh@lkkauto.com

Cc: ACCOUNTS@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG

Subject: SHB4588P - Finalize Amount & After Repair Photo.

Hi Taufikh

Please see below for the finalize according to our conversion to finalize for SHB4588P

Finalize Amount

Total Repair - 2 Days

Labour - \$420

Special Netts - \$0

Parts - \$536.90

Parts after 20% discount = \$429.52

Total L+S+P = \$849.52 -20% LUMP SUM

Final Amount = \$679.616

Please help to close this case ASAP

Thanks

Best Regards

Ding Automotive Pte Ltd

Alex Khong

Hp :83039588

SHB4588P - Finalize Amount & After Repair Photo.

Taxis Customer Service to: taufikh







Fri 19 Jan 2018 01:58 PM

Cc ACCOUNTS, ADMIN

[We encourage everyone to do his / her part in helping to preserve the environment. Kindly refrain from printing this email unless it is absolutely necessary.]

Hi Taufikh ,

Please see below for the finalize according to our conversion to finalize for SHB4588P

     
DSC02023.JPG DSC02024.JPG DSC02025.JPG DSC02027.JPG DSC02028.JPG DSC02029.JPG

Finalize Amount

Total Repair - 2 Days

Labour - \$420

Special Netts - \$0

Parts - \$536.90

Parts after 20% discount =\$429.52

Total L+S+P =849.52 -20% LUMP SUM

Final Amount = \$679.616

Please help to close this case ASAP

Thanks

Best Regards

Ding Automotive Pte Ltd

Alex Khong

Hp :83039588

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

0077221



NRIC No. S1486583G



Blood Group: B+ Date of Issue: 09-09-1991

100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1486583G



Name: NEO KIM SIAH

梁金城


Race: CHINESE

Date of Birth: 11-07-1961 Sex: M

Country of Birth: SINGAPORE

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	26/03/2002
03	BUS VL	18/02/2002
04	BUS ATTENDANT	18/02/2002



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1486583G

Name: NEO KIM SIAH

Birth Date: 11 Jul 1961


Issue Date: 02 Jul 2003



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	27 Apr 1988
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	29 Sep 1963
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	04 Aug 1968
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	25 Apr 1989

Licence No: S1486583G



NP 428A

Land Transport Authority


VOCATIONAL LICENCE

Licence No: S1486583G

Name: NEO KIM SIAH

Issue Date: 8/2/2014

Please visit www.lta.gov.sg to check the status of this vocational licence



Vehicle No: SHB4588P (Hirer/Relief) (driver) Job Card No. 50110447

Reporting Date: 11/01/18 Time: 15:30 hrs FSMS REP.NO.CC 18010309

Accident Date: 11/01/18 Time: 13:00 hrs SAS No.MSK. 118605493

[OD/TP/WE/Cash] [PG: 0] [SPD: 0 Km/H] Mileage: 205584

[HP: 97468347] [Weather Condition: Clear/Raining/other: Clear] [Road surface: Wet/Dry/other: Dry]

[Location: Along Kallang Ave Aperia building]

TP1: Number Plate SLG9627D Name: Loh Poh Hong NRIC: S2625277 HP: 97468347

TP2: Number Plate _____ Name: _____ NRIC: _____ HP: _____

TP3: Number Plate _____ Name: _____ NRIC: _____ HP: _____

[Witness: _____] [HP: _____] [Tow: Y/N]

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S16049991



Name

WONG CHOON HWA

Race

CHINESE

Date of Birth

10-03-1963

Country of Birth

SINGAPORE

Sex

M

S16049991



NRIC No. S16049991



Blood Group

O+

Date of Issue

06-03-1994

Address

APT BLK 943 JURONG WEST STREET 91
#10-529
SINGAPORE 2264

REPUBLIC OF SINGAPORE DRIVING LICENCE

S16049991



Birth Date: 10 Mar 1963

Issue Date: 07 Apr 2003




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles not exceeding 200 cc
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

13 Mar 1994

26 May 1991



NP 426A

Land Transport Authority

VOCATIONAL LICENCE

Licence No : S16049991

Name : WONG CHOON HWA

Issue Date : 8/4/2005

Please visit www.lta.gov.sg to check the status of this vocational licence



This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type Description
02 TAXI VL

Issue Date

09/05/1997



Vehicle No: SHB4S88 (Hirer/Relief)

Reporting Date: 11/01/18 Time: 15:30hrs

Accident Date: 11/01/18 Time: 13:00hrs

[OD/TP/WC/Cash] [PG: Q] [SPD: 0 Km/H]

[HP: 8116321] [Weather Condition: Clear/Raining/other:]

[Location:]

TP1: Number Plate SLC7 96270 Name: Loh pah heng NRIC: S26252272 HP: 97468347

TP2: Number Plate Name: NRIC: HP:

TP3: Number Plate Name: NRIC: HP:

[Witness:]

[HP:]

[Tow: Y/N]

Job Card No. 5010447

FSMS REP.NO.CC 18010309

SAS No.MSK. 118005493

Mileage: 205584

[[Road surface: Wet/Dry/Other:]]

Ding Automotive Pte Ltd

Blk 10 Sin Ming Industrial Est. Sector C, #01-20, Singapore 575645

Tel:6452 1208, Fax:6452 0614

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

15/01/2018 8:33

JOB-NO: 50110447

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

VEHICLE DETAILS

LICENSE NO: SHB4588P
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: FIRST CAPITAL INSURANCE LIMITED
JOB-CODE: TP
TRANS: AUTO
SA: Ding Auto User 1

CHASSIS: KMHLB41UMHU098352
ENGINE: D4FDGU707360

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 PANEL BEAT & STRAIGHTEN CHASSIS	1.00	800.00	0.00	800.00	Y		200
2 CHECK WIRING	1.00	60.00	0.00	60.00	Y		20
3 R & R BOOTLID COMPOENENT	1.00	80.00	0.00	80.00	Y		X
4 RUST PROOFING	1.00	60.00	0.00	60.00	Y		X
5 SPRAY BOOTLID AND REAR BUMPER	1.00	600.00	0.00	600.00	Y		200
TOTAL:		1,600.00	0.00	1,600.00			
MATERIALS							
1 REAR BUMPER	1.00	536.90	0.00	536.90	Y		de
2 REFLECTOR RRHS	1.00	30.60	0.00	30.60	Y		X
3 REFLECTOR RLHS	1.00	30.60	0.00	30.60	Y		X
4 REAR BUMPER REINFORMENT	1.00	428.40	0.00	428.40	Y		X
5 REAR REINFORMENT BRACKET RHS	1.00	80.30	0.00	80.30	Y		X
6 REAR REFLECTOR BRACKET LHS	1.00	80.30	0.00	80.30	Y		X
7 REAR BUMPER SIDE BRACKET RHS	1.00	35.60	0.00	35.60	Y		X
8 REAR BUMPER SIDE BRACKET LHS	1.00	35.60	0.00	35.60	Y		X
TOTAL:		1,258.30	0.00	1,258.30			
TOTAL PARTS & LABOUR:		2,858.30	0.00	2,858.30			

EXCESS/LOADING:\$\$ 0.00

No. Of Day:

02

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY:

17/1/18

SURVEYED BY:

Tanphin

CONTACT NO:

9749574

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Labar 420
Parts 536.90 - 200
= 429.52
Total = 849.52
= 679.6167

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	-----------------	---------	-----------------	-----	----------	--------------

Ding Automotive Pte Ltd

Blk 10 Sin Ming Industrial Est. Sector C, #01-20, Singapore 575645

Tel:6452 1208, Fax:6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

15/01/2018 8:33

JOB-NO: 50110447

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 57517 0

CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHB4588P
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: FIRST CAPITAL INSURANCE LIMITED
JOB-CODE: TP
TRANS: AUTO
SA: Ding Auto User 1

CHASSIS: KMHLB41UMHU098352
ENGINE: D4FDGU707360

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 PANEL BEAT & STRAIGHTEN CHASSIS	1.00	800.00	0.00	800.00	Y		200
2 CHECK WIRING	1.00	60.00	0.00	60.00	Y		20
3 R & R BOOTLID COMPOENENT	1.00	80.00	0.00	80.00	Y		X ny
4 RUST PROOFING	1.00	60.00	0.00	60.00	Y		X un
5 SPRAY BOOTLID AND REAR BUMPER	1.00	600.00	0.00	600.00	Y		200
TOTAL:		1,600.00	0.00	1,600.00			420

MATERIALS

1 REAR BUMPER	1.00	536.90	0.00	536.90	Y		del
2 REFLECTOR RRHS	1.00	30.60	0.00	30.60	Y		X
3 REFLECTOR RLHS	1.00	30.60	0.00	30.60	Y		X
4 REAR BUMPER REINFORMENT	1.00	428.40	0.00	428.40	Y		X
5 REAR REINFORMENT BRACKET RHS	1.00	80.30	0.00	80.30	Y		X
6 REAR REFLECTOR BRACKET LHS	1.00	80.30	0.00	80.30	Y		X
7 REAR BUMPER SIDE BRACKET RHS	1.00	35.60	0.00	35.60	Y		X
8 REAR BUMPER SIDE BRACKET LHS	1.00	35.60	0.00	35.60	Y		X
TOTAL:		1,258.30	0.00	1,258.30			

TOTAL PARTS & LABOUR :

2,858.30 0.00 2,858.30

EXCESS/LOADING:\$ 0.00

No. Of Day: 02

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 17/1/18

SURVEYED BY: Tanphu

CONTACT NO: 97495579

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00

336.90
20% - 429.52
420
849.52
438 750
\$650
02 days

CLAIM DETAILS							
DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE

Vic (LKKAuto)

From: Accounts Ding Auto <accounts@dingauto.sg>
Sent: Tuesday, 27 March, 2018 11:28 AM
To: Vic (LKKAuto)
Cc: Kenneth Ding; Kelly Ding; DAMtaxi; Sales Ding Auto; Admin Ding Auto; Ding Ding Auto; Admin A; Asher Sng (LKKAuto)
Subject: Re: (REF : CC4/QBE18001047/T1hb3) BILLING FOR SHB4588P TP CLAIMS AGAINST SLG9627D ON 11/1/2018
Attachments: SHB4588P (DV).pdf; SHB4588P (REPAIR INVOICE).pdf

Dear Vic,

Please view attached file for signed DV and repair invoice.
We will also mail both original invoice to your office.

Kindly revert back regarding payment as soon as possible.
*NOTE: Payment is to be made to Ding Automotive Pte Ltd.

Thank you so much.

Yours Sincerely,
Fang XinYi Michelle
Office Contact : 92394128
Ding Automotive Pte Ltd

On Mon, Mar 26, 2018 at 4:55 PM, Vic (LKKAuto) <vicalpeh@lkkauto.com> wrote:

RESEND

WITHOUT PREJUDICE

Dear Michelle,

We refer to your below email and kindly ignore our previous offer made due to type error.

On a without prejudice basis and purely for an amicable settlement on a without admission of liability to our Insured's part, we have our principal mandate and we offer settlement as follows:

Cost of Repair (w/gst)	\$ 695.50
Loss of Rental (\$116.82 x 3 days)	\$ 350.46
Loss of Income (\$50 x 3 days)	\$ 150.00
GIA Search Fee	\$ 2.00
TOTAL	\$ 1,197.96

If agreeable, kindly let the owner chop and sign the attached DV and forward back to us the **original signed copy (hard copy) together with LOD, Authorization Letter, Final Repair Bill, etc. (original hard copy)** for our Principal to process the payment.

The above amount is to be made payable to **DING AUTOMOTIVE PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Accounts Ding Auto [mailto:accounts@dingauto.sg]
Sent: Friday, 23 March, 2018 3:20 PM
To: Vic (LKKAuto)
Cc: Kenneth Ding; Kelly Ding; DAMtaxi; Sales Ding Auto; Admin Ding Auto; Ding Ding Auto
Subject: Re: (REF : CC4/QBE18001047/T1hb3) BILLING FOR SHB4588P TP CLAIMS AGAINST SLG9627D ON 11/1/2018

Dear Vic,

We have already e-mailed all supporting document.

But we still have not get back any update at your end.

Kindly update us on the states so that we can close the case as soon as possible.

Thank you so much.

Yours Sincerely,

Fang XinYi Michelle

Office Contact : 92394128

Ding Automotive Pte Ltd

On Sat, Mar 3, 2018 at 11:48 AM, Accounts Ding Auto <accounts@dingauto.sg> wrote:

Dear Vic,

We have already e-mailed all supporting document.

But we still have not get back any update at your end.

Kindly update us on the states so that we can close the case as soon as possible.

Thank you so much.

Yours Sincerely,

Fang XinYi Michelle

Office Contact : 92394128

Ding Automotive Pte Ltd

On Mon, Feb 19, 2018 at 11:19 AM, Accounts Ding Auto <accounts@dingauto.sg> wrote:

Dear Vic,

Ref : CC4/QBE18001047/T1hb3

Please see attached supporting document to claims against your insured .

We have completed the repair, driver has collected the vehicle and your surveyor has finalize the repair at \$650 - total 2 days repair job.

We would like to claim for our insured as per following :

Total Number of days : 3

Repair Cost : $\$650 + 7\% = \695.50

Loss of Rental : $\$116.82 \times 3 = \350.46

Loss of Income : $\$80 \times 3 = \240

LTA Search Fee : $\$1.87 + 7\% = \2

Kindly revert back with our offer so that we can issue our LOD & invoice and close the case as soon as possible.

Thank you so much.

Yours Sincerely,

Fang XinYi Michelle

HP Contact : 87483145

Office Contact : 92394128

Ding Automotive Pte Ltd

Satisfaction Voucher

17 JAN '18 17:36

Date: 17/01/2018

FIRST CAPITAL INSURANCE LIMITED

Attention: MOTOR CLAIMS DEPT

Dear Sir/Madam

Wong Cheon Hwa

I/We hereby acknowledge having received from Singapore Technologies Kinetics

Ltd., 249 Jalan Boon Lay, Singapore 619523, my/our vehicle number SHB4588P

which has been repaired to my/our satisfaction and acceptance. I/We admit that

the payment of SGD _____ account for such repairs is in full discharge

of my/our claim upon the corporation under the policy number D-15072702MFSH

reference claim number 50110447 in respect of the damage caused to the

said vehicle in an accident that occurred thereto or about the 11/01/2018

at ALONG KALLANG AVE APER

Dated this day of _____, 201 _____

Signature: _____

NRIC No: _____

Name: CityCab PTE LTD (Fleet)

Address: 383 SIN MING DRIVE
SINGAPORE 575717 0


Company Stamp if applicable

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18001047/T1hb3n2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 04-04-2018		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 9627D	Veh. Inspected	SHB 4588P	
Policy No.	8-V0016096-MVA	Coverage (\$)	0.00	
Claim No.	VC011083	Excess (\$)	0.00	
Assign From	JOYCE	Assign Date	16/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHLB41UMHU098352	Colour	YELLOW	
Odometer	207824	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/01/2018	Inspection Date	17/01/2018	
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4588P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	536.90	536.90
1	REFLECTOR RRHS	NOT NECESSARY	30.60	-
1	REFLECTOR RLHS	NOT NECESSARY	30.60	-
1	REAR BUMPER REINFORMENT	NOT NECESSARY	428.40	-
1	REAR REINFORMENT BRACKET RHS	NOT NECESSARY	80.30	-
1	REAR REFLECTOR BRACKET LHS	NOT NECESSARY	80.30	-
1	REAR BUMPER SIDE BRACKET RHS	NOT NECESSARY	35.60	-
1	REAR BUMPER SIDE BRACKET LHS	NOT NECESSARY	35.60	-
	LESS 20% DISCOUNT		-	-107.38
			1,258.30	429.52
	<u>LABOUR</u>			
	PANEL BEAT & STRAIGHTEN CHASSIS.		800.00	200.00
	CHECK WIRING.		60.00	20.00
	R&R BOOTLID COMPONENT.	NOT NECESSARY	80.00	-
	RUST PROOFING.	NOT NECESSARY	60.00	-
	SPRAY BOOTLID AND REAR BUMPER.		600.00	200.00
			1,600.00	420.00
	GRAND TOTAL		2,858.30	849.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			650.00

Report Ref No. CC4/QBE18001047/T1hb3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.