

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : EQ Insurance Company Ltd
Motor Claims Dept

Date : 18 Jan 2018

Dear Sirs :

Fax : 6223 4190

RE : ESTIMATE COST FOR TOYOTA KDY2318017748 - GBD7741D
ACCIDENT INVOLVING GBD7741D & GBB1091X ON 16/01/2018

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear tailgate	1pc	\$ 1,461.20
2	Rear tailgate lock @\$255ea	2pcs	\$ 510.00
3	Rear tailgate hinge @\$119ea	4pcs	\$ 476.00
4	Rear lamp @\$269.6ea	2pcs	\$ 539.20
5	Rear end panel.	1pc	\$ 494.67
6	Rear lamp bracket @\$56.42ea	2pcs	\$ 112.84
7	Rear number plate garnish	1pc	\$ 88.30
8	Rear mudflat panel.	1pc	\$ 128.90
9	Rear mudflat rubber.	1pc	\$ 35.00
			<u>\$ 3,846.11</u>
	Less 25%		<u>\$ (961.52)</u>
			\$ 2,884.59
10	Rear number plate.	1pc	\$ 25.00
11	Tool box -sn.	1pc	\$ 350.00
12	Rear stopper o/s -sn.	1pc	\$ 15.00
	Sum Carried Forward		\$ 3,274.59

Sum Carried Forward		\$ 3,274.59
----------------------------	--	--------------------

Labour Charge & Misc

To remove, replace, repair & install damaged parts.	} }	\$ 800.00
--	--------	-----------

To R & R rear exhuast.		\$ 120.00
------------------------	--	-----------

To R & R wiring.		\$ 60.00
------------------	--	----------

To putty & spray painting.		\$ 800.00
----------------------------	--	-----------

Total		\$ 5,054.59
--------------	--	--------------------

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.