

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT Ref: CS3/ASM18001079/R1be2 Date: 08-02-2018 **AXA TOWERSINGAPORE 068811**

Page No.:1 of 1

ATTN : STACEY NG			Code: ASM			
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLG 546M	Veh. Inspected	SJW 909P		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	S8M006YQ	Excess (\$)	0.00		
	Assign From	STACEY NG	Assign Date	10/01/2018		
2.	Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ GLA200 A	c.c	1595		
	Engine No.	HIDDEN	Year of Reg.	2015		
	Chassis No.	WDC1569432J103908	Colour	GREY		
	Odometer	73457 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	FAIR				
3. Conditions of Tyres						
		Size	Make	Balance		
	R/H Front Tyre	235/50 R18	PIRELLI	6 mm		
	L/H Front Tyre	235/50 R18	PIRELLI	6 mm		
	R/H Rear Tyre	235/50 R18	PIRELLI	6 mm		
	L/H Rear Tyre	235/50 R18	PIRELLI	6 mm		
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						

5.	General Information					
	Accident Date	08/01/2018	Inspect Date / Time	11/01/2018 (02:27 PM)		
	Survey held at	GOLD AUTOWORKS PTE LTD				
		48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/ASM18001079/R1be2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.