

REPAIR ESTIMATE

VEHICLE NO : SHA 6086M

MAKE :

MODEL : TOYOTA PRIUS

AZH

17/1/2018 10:03

Cheng

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR BUMPER ✓			\$ 458.60	
REAR BUMPER RE-INFORCEMENT ?			\$ 318.80	
REAR BUMPER UNDER COVER ✓			\$ 552.60	
REAR BUMPER SIDE RETAINER ?			\$ 112.70	
REAR BUMPER SPONGE X			\$ 143.40	
REAR BUMPER CLIPS ✓			\$ 22.00	
<i>tailgate repair</i>				
SUB TOTAL			\$ 1,608.10	
LESS 25%			\$ 402.03	
DISCOUNTED TOTAL			\$ 1,206.08	
REAR BUMPER REVERSE SENSOR ✓			\$ 135.70	NETT
REAR BUMPER RUBBER MAT ✓			\$ 50.00	NETT
			\$ 185.70	
Labour Charge				
Panel Beating			\$ 350.00	
Spray Painting Charge			\$ 400.00 360	
Wiring Charge			\$ 50.00 X	
Remove/Refix Reverse Sensor			\$ 120.00 20	
TOTAL LABOUR			\$ 720.00	
ESTIMATE TOTAL			\$ 2,111.78	

1 Calm LKK
 17/1/18 1045hr.
 2 Rep.
 PIP
 Before Paint photo

LKK Auto Consultants hence notify the Reparer of the following:

- To repair the damaged part
- To provide a written estimate of the repair
- To provide a written estimate of the cost of the repair
- To provide a written estimate of the time required for the repair
- To provide a written estimate of the materials required for the repair
- To provide a written estimate of the labour required for the repair
- To provide a written estimate of the total cost of the repair
- To provide a written estimate of the time required for the repair
- To provide a written estimate of the materials required for the repair
- To provide a written estimate of the labour required for the repair
- To provide a written estimate of the total cost of the repair

Acknowledged by Reparer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.