

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MOVON SOLUTIONS PTE LTD

c/o 46 Lentor Plain
Singapore 786548

Date: 18/1/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: TRAILER / TRD808C</u>	
1 pc	rear end centre beam (container) R X	2,070.00
2 pcs	customised rear door 4000 @ 5,320.00 37 ✓	10,640.00 8000
4 pcs	customised rear door lock lever 900 @ 1,260.00 37 ✓	5,040.00 3600
4 pcs	customised rear door lock catch 150 @ 385.00 37 ✓	1,540.00 1000
1 pc	rear end centre beam (Trailer) 37 ✓	1,830.00
1 pc	customised rear door rubber 37 TM -	465.00
2 pcs	tail lamp @ 570.00 X	1,140.00
	Sub Total	22,725.00 14895
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	1800 2,800.00
	To spray painting on affected areas.	400 1,200.00
	total	26,725.00 2700

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MOVON SOLUTIONS PTE LTD

c/o 46 Lentor Plain
Singapore 786548

Supp.

Date: 15/3/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: TRAILER / TRD808C/Supplementary</u>	
4 pcs	customised rear door lever bracket 180 @ 295.00	bt✓ 1,180.00 720
4 pcs	customised rear door lever handle 400 @ 520.00	bt✓ 2,080.00 1600
4 pcs	customised rear door handle lock 150 @ 280.00	bt✓ 1,120.00 600
4 pcs	customised rear door hinge 220 @ 386.00	bt✓ 1,544.00 880
1 pc	customised rear door rubber R/H	tn✓ 465.00
	Total	6,389.00
	14895 2700 4265 21860 4/5 \$17500 # 9 days LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____	4265