

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MOVON SOLUTIONS PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Date: 18/1/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: TRAILER / TRD808C	
1 pc	rear end centre beam (container) <i>Ry</i>	
2 pcs	customised rear door <i>bt</i>	
4 pcs	customised rear door lock lever <i>bt</i>	
4 pcs	customised rear door lock catch <i>bt</i>	
1 pc	rear end centre beam (Trailer) <i>Ry bt</i>	
1 pc	customised rear door rubber <i>fu</i>	
2 pcs	tail lamp <i>x</i>	
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	<i>1800</i>
	To spray painting on affected areas.	<i>2800.00</i>
		<i>900</i> 1,200.00
	total	2,700.00

LKK Auto Care wants to notify the Repaired the following:

- To resurvey later after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by: _____
Signature: _____
Date: _____

Taufik 97495744
WP
18/1/18 @ 1pm.
8 days.
taufik@lkkauto.com
sur@lkkauto.com
Lumpsum
Resurvey after repair.