

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MOVON SOLUTIONS PTE LTD

c/o 46 Lentor Plain
Singapore 786548

Date: 18/1/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: TRAILER / TRD808C</u>	
1 pc	rear end centre beam (container)	2,070.00
2 pcs	customised rear door	10,640.00
4 pcs	customised rear door lock lever	5,040.00
4 pcs	customised rear door lock catch	1,540.00
1 pc	rear end centre beam (Trailer)	1,830.00
1 pc	customised rear door rubber	465.00
2 pcs	tail lamp	1,140.00
	Sub Total	22,725.00
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	2,800.00
	To spray painting on affected areas.	1,200.00
	total	26,725.00

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MOVON SOLUTIONS PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Date: 15/3/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: TRAILER / TRD808C/Supplementary</u>	
4 pcs	customised rear door lever bracket	180 @ 295.00
4 pcs	customised rear door lever handle	400 @ 520.00
4 pcs	customised rear door handle lock	150 @ 280.00
4 pcs	customised rear door hinge	220 @ 386.00
1 pc	customised rear door rubber R/H	
		bt✓ 1,180.00 720
		bt✓ 2,080.00 1600
		bt✓ 1,120.00 600
		bt✓ 1,544.00 880
		tn✓ 465.00
	Total	6,389.00
		4265
		14895
		2700
		4265
		21860
		1/5 \$17500 #
		9 days
	<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	