

Pre-assign / CCU / FTE

STP 300B → → →

	INSRS: WSP: <i>Cheng Hao (Tshun)</i> Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:
--	--	---	---	---	---	---	---

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	() days) Reduction:	% Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 29-8-18	Confirm with: KJUNKE	Email ☐ Call ☐
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 27		If NO or B 28, Ass. Lia:
Repair Cost: 65T	SS 2,500.80		
Loss of Rental (LOR): 65T	SS 400.00 (4 days) 93.46		
Loss of Use (LOU):	SS - (\$ x days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐			[Tick only one]
GIA/LTA Search:	SS 8.00		
Medical:	SS		1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS - (e.g. Tow/Independent)		2) Report Format:
Legal Cost:	SS		3) Survey fee:
Total:	SS 2,908.80	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 2,908.80	Name 1:	CHENG HUE MOTOR PTE LTD
Payee 2: (Strike if N.A.)	SS x	Name 2:	x
Payee 3: (Strike if N.A.)	SS	Name 3:	

ASS. REC. BY:

REF: EQ1Hennerh

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Cheng Hae

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STP 3500B Yr Regn: OP, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NIS Qash Qash c.c. 1988Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 20861 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STNFBAT11U1F52068Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD / Rlm orTyre Size: F: 225/45R19

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 10/1/18 D.O.I. 16/1/18

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11 PM pass to Corbin8 2337.20 Confirmed JunePrinci
(4 X 100 + 6-11)R (1,278.54 / 357.2)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Phones

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJP3500B
TP/EA

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department

FAX: 62243903

WS Ref: TP-EQ
Claim Type: Third Party
Accident Date: 10/01/2018
TP Veh Reg No: SKD5405G

Claim No: ES1890039
Estimate No: ES1890039/WS
Date: 16 Jan 2018
Policy No: PNPV2017-00007731
Veh Reg No: SJP3500B
Make/Model: NISSAN QASHQAI 2.0
CVT ABS
Chassis No: SJNFB AJ11U1752068
Engine No: MR20425629W
Reg. Date: 30/09/2016

Not Authorised

1-B1
Heavy B4 paint

4 days

Estimate Repair Cost to Vehicle No : SJP3500B

Pages: 1/1

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Cost Plus				
1 REAR BUMPER	420.00	1 PC	420.00	✓
2 REAR BUMPER REINFORCEMENT	280.00	1 PC	280.00	X
3 REAR BUMPER CLIPS	4.00	6 PCS	24.00	✓
4 REAR PANEL	260.00	1 PC	260.00	X
5 TAILGATE INNER LOCK	115.00	1 PC	115.00	✓
6 TAILGATE INNER LOCK SWITCH	90.00	1 PC	90.00	✓
7 TAILGATE INNER RUBBER	95.00	1 PC	95.00	✓
8 TAILGATE LOGO	38.00	1 PC	38.00	✓
9 TAILGATE EMBLEM (QASHQAI)	35.00	1 PC	35.00	✓
10 TAILGATE EMBLEM	34.00	1 PC	34.00	✓
			1,391.00	
	Add 20%		278.20	1,669.20
Special Net				
11 REVERSE SENSOR (4 PCS)	280.00	1 SET	280.00	✓
				280.00
Labour				
12 PANEL BEATING	700.00	1 LA	700.00	400
13 PUTTY AND RESPRAY	700.00	1 LA	700.00	600
14 RUSTPROOFING	30.00	1 LA	30.00	X
				1,430.00

Total S\$ 3,379.20

Add GST @ 7% 236.54

Total Amount payable S\$ 3,615.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7234H
Vehicle Details	
Vehicle No.:	SJP3500B
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 Jan 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	MR20425629W
Chassis No.:	SJNFBAJ11U1752068
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$19,615.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,615.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2026
PARF Rebate Amount:	\$14,711.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,501.00
COE Rebate Amount:	\$44,400.00
Total Rebate Amount:	\$59,111.00

The information contained herein is correct as at 16 Jan 2018

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No, 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI18001148/Kjb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 18-01-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKD 5405G	Veh. Inspected	SJP 3500B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/01/2018	Inspection Date	16/01/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQ118001148/Kjs3

Date: 19.01.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SJP 3500B


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.01.2018 at the premises of M/s Cheng Hoe Motor Pte Ltd (Yishun) and have the following to report:-

Workshop Estimate Amount	: S\$	3,379.20
Revised Estimate Amount	: S\$	1,320.80
"Check" Items Amount	: S\$	1,402.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4-5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

Date: 25 AUG 2018

EQ Insurance Co Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SJP3500B & SKD5405G ON 10/01/2018
PIE (TUAS) ON THOMSON FLYOVER.**

We are authorized by SJP3500B for their above matter.

Record reveals that you are the insurer of SKD5405G. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 2500.80
2. Loss of Use	S\$ 0.00
3. Hire of Vehicle	S\$ 400.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 2908.80

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 9 April 2018 5:43 PM
To: 'ericongjl@gmail.com'
Cc: Admin A; Vivian Lau (LKKAuto)
Subject: ACCIDENT INVOLVING SKD 5405G AND SJP 3500B ON 10/01/2018 ALONG PIE (TUAS) ON THOMSON FLYOVER

Our Ref: **CC6/EQI18001148/Kjb3**

ONG JEAU LEANG

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SKD 5405G AND SJP 3500B ON 10/01/2018 ALONG PIE (TUAS) ON THOMSON FLYOVER

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORISATION

(FOR PROPERTY DAMAGE CLAIM ONLY)

Re: Motor Insurance Claim SJP3500B
in respect of the traffic accident on 10/1/2018
at/along PIE (Tuas) on Thomson Flyover

I/We, Loh Mew Fong
NRIC S1427234H of 53 Thong Soon Green Singapore 787359


owner of motor vehicle SJP3500B, insured by FWD Singapore Pte Ltd
under policy no. PNPV2017-00007731

hereby authorise **M/s CHENG HOE MOTOR PTE LTD** on Blk 1019 Yishun Industrial Park A #01-374 Singapore 768761, to act as my/our representative in my/our claim against the owner /driver of motor vehicle SKD5405G in respect of the above-mentioned accident.

I/We further authorise that any payment due to me/us from the aforesaid claim is to be directed to my/our abovenamed representative.

And I/We hereby indemnify my/our abovenamed representative against any claim and/or damage which may arise from any action taken on my/our behalf.

I/We affirm all the above by my/our signature below.

Signed : 

Date : 11/1/2018

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

WS Ref: TP-EQ
Claim Type: Third Party
Accident Date: 10/01/2018
TP Veh Reg No: SKD5405G

NO: CL8180816
Date: 01 Aug 2018
Policy No: PNPV2017-00007731
Veh Reg No: SJP3500B
Make/Model: NISSAN QASHQAI 2.0
CVT ABS
Job No: JC1597976

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	S\$ 2,337.20	S\$ 2,337.20

Total	S\$ 2,337.20
Add GST @ 7%	163.60
Total Amount payable	S\$ 2,500.80

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

38 WOODLANDS IND PARK E1
#05-05, SINGAPORE 757700
TEL : 64595278

GST Reg No. : 53068927L

DATE : 28-Nov-17

E & O.E.

PERFECT DRIVING & SERVICE



38 WOODLANDS IND PARK E1
#05-05 SINGAPORE 757700
(ROC/GST NO. 53068927L)

TEL : 64595278
OPERATING HOURS :
MONDAY TO SATURDAY
(9AM TO 6PM)

Hirer's Name Loh Mew Fong				Date of Birth 18/08/1960		Passport/ Nric No. S1427234H		Nationality Singaporean	
Address 53 Thong Soon Green				Occupation		Driving License No.		Date Obtained/Expiry 04/10/1980	
				Postal Code 787359		Contact No.		Mobile Phone No. 96213500	
Joint Hirer's/Guarantor's Name Tan Jun Liang				Date of Birth 08/09/1989		Passport/ Nric No. S8933506Z		Nationality Singaporean	
Address 53 Thong Soon Green				Occupation		Driving License No.		Date Obtained/Expiry 06/03/2008	
				Postal Code 787359		Contact No.		Mobile Phone No. 97561156	
VEHICLE NO. SDF 43 Y 1U-1125580696				MODEL					
FROM				RETURN *Estimated Date For actual return see CHECK IN.					
CHECK OUT		Date 16/1/18	Time 10:30am	Mileage KM		E % % % F			
CHECK IN		Date 19/1/18	Time 7.40pm	Mileage KM		Remarks			

- 1) This vehicle is restricted to SINGAPORE use only.
- 2) Only Persons above 26 years of age with more than 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
- 3) The hirer shall be liable to pay the first S\$2000 insurance policy excess for damage to vehicle plus loss of earnings while damaged vehicle is under repairs.
- 4) Third party Liability is the first \$2000.00 in any accident involving Third Party Claims
- 5) Hirer is responsible for all parking fines & traffic summon
- 6) Vehicle should be returned at the same time as collection except on Saturday where return time is before 12pm
Hourly extension is charged at 1/5 of the daily rate.
- 8) As preventive maintenance, please check water & engine oil daily.
- 9) For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge S\$100 will be imposed for smoky or dirty vehicle.
- 10) Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings
- 11) The vehicle is NOT covered by a motor insurance policy covering personal accident insurance for the hirer, his passengers or authorised driver
- 12) No replacement of vehicle in any accident

	UNIT		RATE (\$\$)	TOTAL (\$\$)
RATE		@		
DISCOUNT				
GST @ 5%				
TOTAL				
EXTENSION				
DEPOSIT (refundable) \$\$				
CHANGED OVER FROM VEH.			DATE	

1/We declare that all information given on this form is true and accurate

Lairer's Signature

Joint Hirer's/ Guarantor's Signature

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B018/ 2018	
YOUR REF:			
OUR REF : ACS.CH.LTA.2018 (JAN 2018)		DATE : 5/2/18	
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.			
LTANET SEARCHES FOR THE MONTH JAN 2018			
S/NO	TP NO.	CHM	DOA
			sub-total b/f
25	15/1/2018	SJN9683C	SKP6152R
26	16/1/2018	SKD5405G	SJP3500B
27	17/1/2018	GBG615R	SFX6763U
28	17/1/2018	SJW303L	SLM4724H
29	17/1/2018	GY8620T	SGT8436K
30	21/1/2018	GBE8451D	XD9687D
31	22/1/2018	SGD4560U	SDU6000C
32	24/1/2018	GBD3604T	SBM2882R
33	25/1/2018	SGX2007J	SKV8477J
34	29/1/2018	SJH6095B	SLR6969D
35	29/1/2018	SKV9347U	SJU4495A
36	29/1/2018	SKQ326R	SJV9789P
37	29/1/2018	SFR3060R	SJF2298U
38	29/1/2018	SJR6677U	SKW6736U
39	29/1/2018	SKH303D	SLE614K
40	30/1/2018	GBE7282G	SGZ3288Y
41	30/1/2018	GW2503Z	SKD8932G
42	30/1/2018	SGA6150Y	SKU4939A
			\$ 192.00
42 searches @8.00 per search			Total:
			\$ 336.00
[SINGAPORE DOLLARS: THREE HUNDRED THIRTY-SIX ONLY.]			
M/s. A C SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 05/09/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SKD 5405G (Insd Veh)	Your Ref. No. : DMPPHQ17-001906
	SJP 3500B (TP Veh)	Our Ref. No. : CC6/EQI18001148/Kjb3q2
Date of Accident	10/1/2018	

Liability	100%	
Final Repair Cost	: \$ 2,500.80	
Loss of Use	: \$	days
Rental (If any)	: \$ 400.00	4 days
Others:	: \$ 8.00	
	: \$	
	2,908.80	
Final Settlement Sum	: \$ 2,908.80	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	CHENG HOE MOTOR PTE LTD	: \$ 2,908.80
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQI18001148/Kjb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 05-09-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKD 5405G	Veh. Inspected	SJP 3500B	
Policy No.	DMPPHQ17-001906	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	16/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SJNFBAJ11U1752068	Colour	METALLIC SILVER	
Odometer	20861	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R19	DUNLOP	8 mm	
L/H Front Tyre	225/45 R19	DUNLOP	8 mm	
R/H Rear Tyre	225/45 R19	DUNLOP	8 mm	
L/H Rear Tyre	225/45 R19	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/01/2018	Inspection Date	16/01/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 3500B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (WCP)	BUCKLED	420.00	420.00
1	REAR BUMPER REINFORCEMENT (WCP)	TO REPAIR SEE LABOUR	280.00	-
6	REAR BUMPER CLIPS @\$4.00 (WCP)	NECESSARY	24.00	24.00
1	REAR PANEL (WCP)	TO REPAIR SEE LABOUR	260.00	-
1	TAILGATE INNER LOCK (WCP)	DENTED	115.00	115.00
1	TAILGATE INNER LOCK SWITCH (WCP)	SHORTED	90.00	90.00
1	TAILGATE INNER RUBBER (WCP)	DENTED / CUT	95.00	95.00
1	TAILGATE LOGO (WCP)	NECESSARY	38.00	38.00
1	TAILGATE EMBLEM (QASHQAI) (WCP)	NECESSARY	65.00	65.00
1	TAILGATE EMBLEM (WCP)	NECESSARY	34.00	34.00
	COST PLUS 20% (PARTS SUPPLIED BY WORKSHOP)		284.20	176.20
			1,705.20	1,057.20
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (4 PCS) (SN)	DENTED	280.00	280.00
			280.00	280.00
	<u>LABOUR</u>			
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR PANEL		700.00	400.00
	PUTTY AND RESPRAY		700.00	600.00
	RUSTPROOFING	NOT NECESSARY	30.00	-
			1,430.00	1,000.00
GRAND TOTAL			3,415.20	2,337.20
RECOMMENDED COST OF REPAIRS				2,337.20

Report Ref No. CC6/EQ118001148/Kjb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.