



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001153/R1td3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-11-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7031D	Veh. Inspected	JSB 5231
Policy No.		Coverage (\$)	0.00
Claim No.	D18000368MFSH/1	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	26/01/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHA FZ150I (S)	c.c	150
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	PMYRG3410H0010822	Colour	RED
Odometer	27184	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90-80/17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	90-80/17	MAXXIS	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/01/2018	Inspection Date	24/01/2018
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------