

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7494L

DATE 17/1/2018 15:19

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover			\$ 185.80	
	Rear Bumper Protector (LH/RH) X		\$ 38.00	\$ 76.00	
	SUB TOTAL			\$ 1,482.90	
	LESS 20%			\$ 296.58	
	DISCOUNTED TOTAL			\$ 1,186.32	
	Rear Bumper Reverse Sensor X not fitted			\$ 135.70	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 350.00 200	
	Spray Painting Charge			\$ 200.00 180	
	Wiring Charge			\$ 50.00 X	
	Remove/Refix Reverse Sensor			\$ 120.00 X	
	TOTAL LABOUR			\$ 720.00	
	ESTIMATE TOTAL			\$ 2,092.02	
Kalvin LUCK 19/1/18 1000hr 2 Pys. P/P Before Paint photo					
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from the insurance company Acknowledged by Repairer: Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					