

KIM KEAT MOTOR CO
Blk 10 Ang Mo Kio Industrial Park 2A
Avenue 5 #05-34 AMK Autopoint
Singapore 568047
Tel: 64833167 Fax: 64835764
Email: kkmotor@singnet.com.sg

17 Jan 2018

India International Insurance Pte Ltd
Survey Dept.

Re: Quotation for damaged to FBH8054B

Item	Description of Parts	Qty	Amount
1.	Mirror RH	1pc	\$ 45.00
2.	Brake Lever	1pc	25.00
3.	Handle Bar	1pc	85.00
4.	Weight RH	1pc	15.00
5.	Footrest Bar Front RH	1pc	35.00
6.	Heat Shield	1pc	65.00
7.	Cover Muffler	1pc	45.00
8.	Mudguard Rear	1pc	98.00
9.	Footrest Assy Front LH	1pc	65.00
			Total \$ 478.00
			Less 10% - 47.80
			Sub-total \$ 430.20
Nett Item			
10.	Visor Shield	1pc	\$ 55.00
11.	Number Plate Front	1pc	10.00
12.	Cowl Cover Lower	1pc	85.00
13.	Carriage Box	1pc	280.00
14.	To Repair Frame Stem Stopper Plate		100.00
15.	Transport Fee		50.00
16.	Labour		200.00
Grand Total			\$ 1210.20