

MA71 ON 19.01.2018 P.O. 12006

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216
Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :
2/18 -
Confirmed
LS \$3500.00

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :
2/5 #3500
4 days
Whisper to Alvin
22/1/18
L64
@ 10-30am

Quotation No : QO18/01-1136	Quotation Date : 18/01/2018	Terms : 30 DAYS
Vehicle No : SLK7214D	Chassis No : JM6BN22A8H0136078	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: LONPAC ; TP VEHICLE NUMBER: XD3964T ; DATE OF ACCIDENT: 18.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR FENDER O/S 30 days/rent	1	1,175.0000	1,175.00
2	REAR FENDER INNER LINER O/S 11	1	146.0000	146.00 X
3	REAR FENDER INNER LINER CLIPS 11	4	5.0000	20.00 X
4	REAR FENDER AIR VENT O/S 11	1	72.0000	72.00 X
5	REAR FENDER LOWER PANEL O/S 11	1	102.0000	102.00 X
6	REAR BUMPER Deep cut	1	1,075.0000	1,075.00
7	REAR BUMPER SIDE RETAINER O/S 11	1	37.0000	37.00
8	REAR BUMPER SIDE HOLDER O/S 11	1	46.0000	46.00 X
9	REAR BUMPER SIDE HOLDER RIVETS 11	4	6.0000	24.00 X
10	REAR DOOR O/S 11	1	1,006.0000	1,006.00 X
11	REAR DOOR OUTER WEATHERSTRIP MOLDING CHROME 11	1	141.0000	141.00 X
12	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP 11	1	117.0000	117.00 X
13	REAR WHEEL HUB CAP O/S 11	1	120.0000	120.00
14	REAR LAMP O/S 11	1	509.0000	509.00
15	REAR LAMP CLIP HOLDER 11	2	8.0000	16.00
16	REAR WINDSHIELD GLASS WEATHERSTRIP 11	1	124.0000	124.00
17	LESS 20% (ITEMS 1-16)	1	-946.0000	-946.00
18	REAR WINDSHIELD GLASS WEATHERSTRIP SEALANT 11	1	180.0000	180.00 405.00
19	REAR WINDSHIELD GLASS WEATHERSTRIP SPONGE 11	1	100.0000	100.00 305.00
20	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	1	120.0000	120.00 60
21	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	1	180.0000	180.00 120
22	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000	150.00 80

P-3040 S.N70
2432.00 1000-1880
4382

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD
 GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/01-1136	Quotation Date : 18/01/2018	Terms : 30 DAYS
Vehicle No : SLK7214D	Chassis No : JM6BN22A8H0136078	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: LONPAC ; TP VEHICLE NUMBER: XD3964T ; DATE OF ACCIDENT: 18.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	50.0000	20 50.00
24	TO TRANSFER OF REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.	1	120.0000	11 X 120.00
25	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	50 120.00
26	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	900.0000	700 900.00
27	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,000.0000	850 1,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alteration/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Sub Total	6,704.00
GST(7.00%)	469.28
Total (SGD)	7,173.28

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216