


13.2	Remove & replace rear both door rubberasket	
2	Additional Services	
2.1	Towing Service From Station to Workshop (SOR 8)	250.00
2.2	Return Service From Workshop to Station (SOR 7)	100.00
		SUB-TOTAL
		Labour
		GRAND TOTAL
		Total sum billed under SOR 8 and 7
		Total sum billed under C/P 8 and 7
Contractor shall complete the entire repair within <u>50</u> working days upon quotation approved date. (Include parts awaiting time)		

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	KONG SEW KUI	Name:		Name:	
Date:	17.01.2017	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: