

REF: ALG

CC3/ALG18001233/Agber

ASSIGNMENT

From: _____ Date: 18012018

Estimated Cost:

OD / TF / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 1082D

at Workshop no: Premium

of 55 Ubi Rd 1

Insured:

Policy No: 1700080971

Claims No: 753905458 SK

Sum Insured: _____ Excess: of

(Client's Record)

Make of Veh: Tony

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 64 88% days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLU 1082D Page: 2017 NOV 22.

Type: ~~M. Car~~ / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: And. Q21.0 TFB2 999

Colour: Red A.C. Insured / Std / NI / NA

So. Reading: 3586 T. Radio: Insured / Std / NI / NA

Eng No:

C.No: W44222GA2IA034952

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BSX DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 12/1/2018 D.O.I. 18/1/18

Survey held at: As Above

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rcoftop or

Right Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action Instruction

12/1/2018 Report - Estimate Given Qus Rie ny
 22/1/18 @ 3:37pm revert to Victor via Messenger.
 23/1/18 @ 11:46pm Victor informed C/A via Messenger.
 23/1/18 @ 3:24pm informed Jeffrey C/A to ex 6 of by email.
 27/3/18 @ 12:02pm confirmed with new box firm fig to 7760.80, 4 days.
 (Red to 5117.20, 40%)

RECEIVED 12/1/2018

Date/Time File Pass to?

☐

Preli. Report

03/4 1/18/18

☐

Final Report

Date/Time File Return to?

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee

Transponder

3-4-18

Photo

Time

Add Fee: ☐ Site Insp. \$☐ Intensive \$☐ Technical \$☐ Rebrand \$

Report Format:

Lump Sum / I.B.L. : 7760.80

MER-00

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 23 January 2018 3:24 PM
To: 'Claims'; Admin-D (LKKAUTO)
Subject: RE: SLU 1082D
Attachments: SLU1082 EST.pdf

Dear Jeffrey,

As instructed by our client, please proceed to repair the insured vehicle **SLU 1082D (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Saturday, 20 January 2018 7:31 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: SLU 1082D

Dear Catherine,

Kindly assist in the approval for this case.

Many thanks!

Best regards,

Jeffery Tan

Claims Department

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 22 Jan 2018

Preliminary Advice

Vehicle No	: SLU1082D	Accident Date	: 12/01/2018
Make	: AUDI Q2	Policy No.	: 1700080971
Assignment Date	: 20/01/2018	Excess	: S\$0.00
Date of Inspection	: 18/01/2018	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,878.00
Revised Amount	:S\$	9,103.00
Check Items (Estimated)	:S\$	336.00
Total	:S\$	9,439.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	60,682.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,318.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0778D

Vehicle Details

Vehicle No.: SLU1082D

Vehicle to be Exported: No

Intended De-registration Date: 20 Jan 2018

Vehicle Make: AUDI

Vehicle Model: Q2 1.0 TFSI S TRONIC

Primary Colour: Red

Manufacturing Year: 2017

Engine No.: CHZ584375

Chassis No.: WAUZZZGA2JA034952

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$26,517.00

Original Registration Date: 22 Nov 2017

First Registration Date: 22 Nov 2017

Transfer Count: 0

Actual ARF Paid: \$19,124.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Nov 2027

PARF Rebate Amount: \$14,343.00

Intended COE Rebate Details

\$145K.

COE Expiry Date:	21 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,112.00
COE Rebate Amount:	\$46,339.00
Total Rebate Amount:	\$60,682.00

The information contained herein is correct as at 20 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 16:57
Date Of Accident	12/01/2018 08:10
Exact Location Of Accident	ADAM ROAD FOOD CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU1082D
Insured/Policyholder	
Name Of Registered Owner	ADNAN B MD ALI
NRIC No	S7170778D
Email Address	ADNAN.ALI@VALSPAR.COM
Mobile Phone No	(LOCAL) +65-98759977
Alternative Phone No	OTHERS-98751971

Vehicle Particulars

Manufacturer	AUDI
Model	ADNAN.ALI@VALSPAR.COM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700080971
Cover Note Number	

Driver

Name of Driver	ADNAN B MD ALI
NRIC No	S7170778D
Date Of Birth	25/02/1971
Occupation	INDOOR
Date Of Driving Pass	29/08/1998
Driving Experience	19 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98759977
Fax Number	
Contact Number	OTHERS-98751971
EMail Address	ADNAN.ALI@VALSPAR.COM

No. Of Passenger (Including Driver)

SKETCH PLAN

A diagram showing a horizontal line representing the ground. A rectangular block labeled 'A' is on the ground. An arrow points to block A with the label 'Stationary'. Above block A, another rectangular block labeled 'B' is shown at an angle, with an arrow pointing down towards it from the text 'hot and fun'.

A-500-0800

g-Debris

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the police report
NO: T/20180112/2052

I/We declare the foregoing particulars are true in every respect.

Polychoder's Signature

Date & Time

7-12-71

Driver's Signature

(if owner is not the policyholder)

Date & Time



Reporting Centre Personnel's Signature _____

Name: Tony Polony

NRIC/FIN No 61244678

Police Report



SINGAPORE
POLICE FORCE



T20100112-2032

Police Station Of Origin:
Tua Payoh N.P.C.
93 Tua Payoh Central #01-22 Tua Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2511888

2013

Report No: 000000000000

CONTINUATION OF REPORT

Sketch Plan

Informant is unable to provide sketch plan

IMPORTANT: Please stick a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474685 quoting the report number as reference.

Signature Of Officer Recording The Report

E7

ASP E8 HERN KONG QING EN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time

12/01/2013 12:33

Officer In Charge Of Case

TE / GIA /

Staff Sgt ANNE SIEW PING

Contact No: 65476430

Classification Of Case:

Authentication Stamp

4/1/2013



SINGAPORE
POLICE FORCE

SN 168

SIGNATURE

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7170778D



Name

ADNAN B MD ALI

عبدان بن مد علي

Race

MALAY

Date of birth

25-02-1971

Sex

M

Country of birth

MALAYSIA

S7170778D

REPUBLIC OF SINGAPORE DRIVING LICENCE



ADNAN B MD ALI

Date: 25 Feb 1971

Date: 16 Sep 2009



0017848468



9064623

NRIC No. S7170778D



Nationality

MALAYSIAN

Date of issue

16-09-2009

Address

APT BLK 153 LORONG 2 TOA PAYOH
#03-604
SINGAPORE 310153

LICENCE TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Motor Cars < 2000kg with < 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg 29 Aug 1998



Licence No: S7170778D

NP 428A

CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : ADNAN B MD ALI
Period of Insurance : 22 Nov 2017 To 21 Nov 2018
Engine No. : CHZ584375
Chassis No. : WAUZZZGA2JA034952

Vehicle No. : SLU1082D
Policy No. : 1700080971
Endorsement No. :
Issued Date : 30 Nov 2017

ABOUT THE COVER

Make/Model : AUDI Q2/ Q2 Sport 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ADNAN B MD ALI

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

1000008099/AIG/Decal

504125206

REMIUM LEASING - SP

31 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

Chiang Qian Yee

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **3** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.
8. **The rental car will be delivered (within Singapore), and MUST BE RETURNED BACK TO Audi Customer Service Centre upon collection of your accident car.**

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0067/2018/JT
Date	:	16-Jan-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Adnan B Md Ali
Address	:	Blk 153 Lorong 2 Toa Payoh #03-604
Telephone	:	HP +65 9875 1971
Type of Claim	:	Own Damage Claims
Policy No.	:	1700080971
Vehicle No	:	SLU 1082 D
Model Code	:	Audi Q2 1.0 TFSI S-tronic
Model / Year	:	Nov-17
Engine No	:	CHZ 584375
Chassis No	:	WAUZZZ6A2JA034952
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Jan-18
Place of Accident	:	Adam road food centre

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 1082 D.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor & headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, rhs front fender & headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,450.00 750,	
3	To respray front bumper & rhs front fender.	\$ 1,500.00 1100,	
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>4,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 1082 D.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Deformed</i>	\$ 1,620.00	✓ 1295.20
2	FRONT AIR GUIDE GRILLE RH <i>cut</i>	\$ 145.00	✓ 115.60
3	FRONT BUMPER LOWER SPOILER <i>Not New</i>	\$ 259.00	X
4	FRONT BUMPER ADAPTOR - RHS <i>Not New</i>	\$ 36.00	? X
5	FRONT WHEEL ARCH TRIM - RHS/LHS <i>Ne</i>	\$ 558.00	✓ 445.60
6	FRONT FENDER - RHS <i>Ryis</i>	\$ 1,011.00	X
7	FRONT FENDER BRACKET - RHS <i>Ne</i>	\$ 41.00	X
9	FRONT FENDER BRACE - RHS <i>Ne</i>	\$ 28.00	X
10	LED HEADLIGHT - RHS <i>cut</i>	\$ 4,378.00	✓ 3602.40
12	SUNDRIES <i>Not New</i>	\$ 300.00	? X
TOTAL SPARE PARTS CHARGES		\$ 8,376.00	
TOTAL LABOUR CHARGES		\$ 4,502.00	
GRAND TOTAL		\$ 12,878.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lg
Surveyed Date : 18/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0067/2018/JT
Date : 16-Jan-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120



Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Adnan B Md Ali
Address : Blk 153 Lorong 2 Toa Payoh
#03-604
Telephone : HP +65 9875 1971
Type of Claim : Own Damage Claims
Policy No. : 1700080971
Vehicle No : **SLU 1082 D**
Model Code : Audi Q2 1.0 TFSI S-tronic
Model / Year : Nov-17
Engine No : CHZ 584375
Chassis No : WAUZZZ6A2JA034952
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jan-18
Place of Accident : Adam road food centre

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 1082 D.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor & headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, rhs front fender & headlight. Re-organise front crash management components. Reinstall all parts removed.		\$ 2,450.00	\$ 750.00
3	To respray front bumper & rhs front fender.		\$ 1,500.00	\$ 1,100.00
4	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,502.00</u>	<u>\$ 2,402.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 1082 D.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER	\$ 1,620.00	\$ 1,295.20
2	FRONT AIR GUIDE GRILLE RH	\$ 145.00	\$ 115.60
3	FRONT BUMPER LOWER SPOILER	\$ 259.00	
4	FRONT BUMPER ADAPTOR - RHS	\$ 36.00	
5	FRONT WHEEL ARCH TRIM - RHS/LHS	\$ 558.00	\$ 445.60
6	FRONT FENDER - RHS	\$ 1,011.00	
7	FRONT FENDER BRACKET - RHS	\$ 41.00	
9	FRONT FENDER BRACE - RHS	\$ 28.00	
10.3	LED HEADLIGHT - RHS	\$ 4,378.00	\$ 3,502.40
11.8	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 8,376.00	\$ 5,358.80
TOTAL LABOUR CHARGES		\$ 4,502.00	\$ 2,402.00
GRAND TOTAL		\$ 12,878.00	\$ 7,760.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLU 1082 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0067/2018/MAS

31 March 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLU 1082 D, Audi Q2 1.0 TFSI S-TRO

With reference to the above-mentioned vehicle, no. **SLU 1082 D**, claimant, **Mr. Adnan B Md Ali**, please find the related document per attached.

1. A copy of the Original invoice no. 85012309 – S\$8,304.06
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLU 1082 D

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408679
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 1 15:46

AIG ASIA PACIFIC INSURANCE PTE LTD	Invoice: 85012309	Account: A0006 (T 0)
MOTOR CLAIM DEPT	Date : 29/03/2018	AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING	Order : SLU1082D	MOTOR CLAIM DEPT
78 SHENTON WAY	Term : 30	AIG BUILDING
#07-16		78 SHENTON WAY
SINGAPORE 079120 079120		#07-16
		SINGAPORE 079120

Regn No.: SLU1082D (V 35949)	Regn Date: 22/11/2017	Mileage: 4171	WIP No.: 52109
Model: Q2 1.0 TFSI S tronic GABANG	Chassis: WAUZZZGA2JA034952	Engine: CHZ 584375	Dept: U
VS8 No.:			
You have been assisted by :- UB-Carrine	()		

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR & HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER & HEADLIGHT. REPAIR RHS FRONT FENDER. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
X	A81A941774A	HEADLIGHT (A) Less 020%	1.00	4378.00	3,502.40
X	A81A807107 GRU	COVER Less 020%	1.00	746.50	597.20
X	A81A807108 GRU	COVER Less 020%	1.00	746.50	597.20
X	A81A807663 GRU	CONN PIECE Less 020%	1.00	126.00	100.80
X	A81A807672 4W3	GRILL (V)(G) Less 020%	1.00	144.50	115.60
X	A81A853717 4W3	COVER Less 020%	1.00	278.50	222.80

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408619
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 15:46

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012309 Date : 29/03/2018 Order : SLU1082D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLU1082D (V 35949) Regn Date: 22/11/2017 Mileage: 4171 WIP No.: 52109

Model: Q2 1.0 TFSI S tronic GABANG Chassis: WAUZZZ6A2JA034952 Engine: CHZ 584375 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine ()

		Details	Qty	Unit Price	Amount
X	A01A053718 4W3	COVER Less 020%	1.00	278.50	222.80

Parts 5,358.80
Labour 0.00
Sublet 2,402.00
Menus 0.00
Lubricant 0.00

Sub-Total 7,760.80

7% GST 543.26

Grand Total 8,304.06



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLU 1082 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0067/2018/GW
2 February 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER


Make & Model : Audi Q2 1.0 TFSI S-Tronic
Vehicle Chassis No. : WAUZZZ6A2JA034952
Vehicle Regn No. : **SLU 1082 D**
Vehicle Mileage : 4171km
Vehicle Owner : Mr. Adnan B Md Ali
Certificate No : 1700080971
Policy Excess : **NIL**
Accident Date : 12/01/2018
Place : Adam Road Food Centre
Repair Cost : \$ 8,304.06
WIP No. : 52109
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

9/2/18

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7170778D



Name

ADNAN B MD ALI

عبدان بن محمد علي

Race

MALAY

Date of birth

25-02-1971

Sex

M

Country of birth

MALAYSIA

S7170778D

REPUBLIC OF SINGAPORE DRIVING LICENCE



ADNAN B MD ALI

Issue Date: 25 Feb 1971

Valid Date: 16 Sep 2009



9064623

NRIC No. S7170778D



Nationality

MALAYSIAN

Date of issue

16-09-2009

Address

APT BLK 153 LORONG 2 TOA PAYOH
#03-604
SINGAPORE 310153

LICENCE TO DRIVE VEHICLES IN THE FOLLOWING CLASS

Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg

29 Aug 1998



Licence No: S7170778D

NP 428A

CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : ADNAN B MD ALI
Period of Insurance : 22 Nov 2017 To 21 Nov 2018
Engine No. : CHZ584375
Chassis No. : WAUZZZGA2JA034952

Vehicle No. : SLU1082D
Policy No. : 1700080971
Endorsement No. :
Issued Date : 30 Nov 2017

ABOUT THE COVER

Make/Model : AUDI Q2/ Q2 Sport 1.0 TFSI S tronic

Engine Capacity/Tonnage : 999.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2017

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :
a) The Policyholder

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver up to the limit of the sum insured.

You have to pay an additional sum of \$3,000 as excess.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, etc.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

DNAN B MD ALI

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg

PORTANT NOTES

e Purchase Company/Employer's Loan: DBS BANK LTD

and hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

15206

UM LEASING - SP

EXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

PORE 159938

Written by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Cheng Qian Yee

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jan 2018		20 Jan 2018 10:55 Edit Adj Rpt	S\$7,760.80 Edit Estimates	S\$7,760.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured: **ADNAN B MD ALI**, ID: S7170778D, Tel: +6598759977, Email: ADNAN.ALI@VALSPAR.COM

Vehicle Reg. No.: **SLU1082D** Date of Loss: 12/01/2018 08:00 - :59
[1 Months and 21 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 7539305458SG** Policy/Cover Note No.: 1700080971 (Comprehensive)

Excess: S\$0.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Dally Amri, Mimi Zarina**]
MimiZarina.DallyAmri@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 30/01/2018]**

Driver/Custodian: ADNAN B MD ALI (46 / Male), NRIC: S7170778D, Tel: +6598759977

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (23/01/2018): Alert - Adj Mandate Approved (S\$9103.00) - SLU1082D - Claim Handler: Dally Amri,...
- AIG_SG (22/01/2018): SLU1082D / OD / 12/01/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLU1082D (7539305458SG)**

OD

Jan 12 2018 8:10AM

[ADNAN B MD ALI]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser <input type="checkbox"/>	
Video						1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	15/01/18 17:18	Video - Accident [Linked Accident Report Documents]	1	Load MP4			
Assessment Reports						1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	22/01/18 15:32	Adjuster Immediate Advice	1	Load HTM			
Photos/Images						3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	22/01/18 15:22	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>		
2	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
3	22/01/18 15:22	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>		
4	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
5	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
6	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
7	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
8	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
9	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
10	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
11	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
12	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
13	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
14	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
15	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
16	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
17	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
18	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
19	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
20	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
21	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
22	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
23	22/01/18 15:22	General View	1	Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	22/01/18 15:17	Singapore Accident Statement	1	Load PDF			
2	22/01/18 15:17	Police Report	1	Load PDF			
3	22/01/18 15:17	Certificate of Insurance	1	Load PDF			
4	22/01/18 15:17	Driver's Driving License	1	Load PDF			
5	22/01/18 15:17	WORKSHOP ESTIMATE	1	Load PDF			
6	04/04/18 09:38	Discharge Voucher	1	Load PDF			
7	04/04/18 09:38	Workshop Invoice	1	Load PDF			

Linked Accident Report Documents

				View	View in Browser
Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	15/01/18 17:18	Video - Accident		Load MP4	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	15/01/18 17:27	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	15/01/18 17:21	Police Report		Load JPG	<input checked="" type="checkbox"/>
2	15/01/18 17:21	Police Report		Load JPG	<input checked="" type="checkbox"/>
3	15/01/18 17:21	Police Report		Load JPG	<input checked="" type="checkbox"/>
4	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	15/01/18 17:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	15/01/18 17:20	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	15/01/18 17:20	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> <div style="text-align: right; margin-top: 5px;"> ^ v </div>			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18001233/AQBE2

Date: 04/04/2018

REFERENCE

Insured/Claimant: ADNAN B MD ALI Policy No: 1700080971
Date of Loss: 12/01/2018 Nature of Claim: OD Claim No: 7539305458SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU1082D**
Make & Model: AUDI Q2, 999cc TFSI S-TRONIC (A) Engine No: CHZ584375
Reg. Date: 22/11/2017 (Man. Year: 2017) Chassis No: WAUZZZGA2JA034952
Colour: Red Odometer: 3586 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$145,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,376.00	5,358.80	3,017.20	36.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,502.00	2,402.00	2,100.00	46.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,878.00	7,760.80	5,117.20	39.74
+ GST 7.00/7.00% (S\$)	901.46	543.26	358.20	39.74
Nett Amount (S\$)	13,779.46	8,304.06	5,475.40	39.74

INSPECTION

Date of Assignment: 20/01/2018
Date Inspected: 18/01/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,620.00 FS	*1,295.20 FS
2	1		*FRONT AIR GUIDE GRILLE RH	Cut	145.00 FS	*115.60 FS
3	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	259.00 FS	*- FS
4	1		*FRONT BUMPER ADAPTOR - RHS	Not Necessary	36.00 FS	*- FS
5	1		*FRONT WHEEL ARCH TRIM - RHS/LHS	Necessary	558.00 FS	*445.60 FS
6	1		*FRONT FENDER BRACKET - RHS	Not Necessary	41.00 FS	*- FS
7	1		*FRONT FENDER BRACE - RHS	Not Necessary	28.00 FS	*- FS
8	1		*LED HEADLIGHT -RHS	Cut	4,378.00 FS	*3,502.40 FS
9	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
10	1		*FRONT FENDER - RHS	Repair	1,011.00 FS	*- FS
Total Parts (S\$)					8,376.00	5,358.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR & HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER & HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	750.00
3	TO RESPRAY FRONT BUMPER & RHS FRONT FENDER	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			4,502.00	2,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >