cs | GAI1800/335 / Kgd3n2 *, OASS, REC. BY Kenruth ASSIGNMENT (Office) 22/1/168 4:45pm Rock! Tan GAI Prote (Person) FR3272X FS2111D G4833167 Kim Keat Motor BIK 10, AMK Ind Park 2A # 05-34 Ave 5 Policy No. CLMOMVM000000120 30/11/2017 (Client's Record CA / REV / REP. / REV 24 HRS wp Date/Toma 5:44pm@22/1118 Victor Date Time FR3272X-X FS 21111 - X

ASS. REC. BY: REF: GAZ/	
Kenneth AS	SSIGNMENT
W. W.	Sp.Reading 2487/9 T/Radio: Insured / Std / NI / NA Eng/No: C/No: C/No: Cond: Good/Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted:	Modi: MID S/Rim / STD A/Rim or Tyre Size: F: /20/90R17 R: /70/90R15 BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front R/Bal.
Date / Time Action / Instruction 18/1 Fine pass to Corhere 11/10 11 Ly 8 Food Confirmed Viz RECEIV	The U/C / Chassis frame / Body Structure affected due to collision. The U/C / Chassis frame / Body Structure affected due to collision. The U/C / Chassis frame / Body Structure affected due to collision.
1) (4/0 1/1/1/7)	ys Of Repair: survey No. of Trip: Survey Fee: Transportation: Site Insp (\$) _ \$ - R\$ _ \$I Interview (\$) Photos Tech Invs (\$) Others Weekend (\$)

Nivitha (LKK Auto)

From:

Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent:

Monday, 22 January 2018 4:45 PM

To:

assignments

Subject:

FW: Accident inv. FR3272X & FS2111D on 30/11/2017.

Attachments:

FR3272X-GIA_Police Report.pdf; FR3272X-Repair Estimate.pdf

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Thursday, 18 January 2018 2:36 PM

To: Kim Keat Motor Co <kkmotor@singnet.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: Accident inv. FR3272X & FS2111D on 30/11/2017.

Without prejudice

Dear Victor

We spoke, noted on your request. I have also spoken to our insured regarding the accident. Please share a copy of the PIR once available.

Dear LKK

Please accept assignment to conduct PRI. Estimates and TP report attached.

Thank you.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Kim Keat Motor Co [mailto:kkmotor@singnet.com.sg]

Sent: Thursday, January 18, 2018 2:25 PM To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Subject: Re: Accident inv. FR3272X & FS2111D on 30/11/2017.

Hi Rachel .

Thanks for your quick respond,

LKK Auto Consultants would be fine for us..

Thank you. Best regards, Victor Seah Kim Keat Motor Co Tel:64833167 Fax:64835764

From: Kim Keat Motor Co [mailto:kkmotor@singnet.com.sg]
Sent: Thursday, January 18, 2018 1:30 PM
To: Tan, Rachel < Rachel. Tan@sg.gaig.com >
Subject: Re: Accident inv. FR3272X & FS2111D on 30/11/2017.
Hi Rachel,
We understand that you are the insurer of vehicle no.: FS2111D which was
invloved in the above captioned accident with motorcycle FR3272X.
We would be obliged if you could kindly sent your surveyor to our company
to survey the damaged to our clients motorcycle.
Attached with copies of relevant document for your immediate action.
Thank you.
Best regards,
Victor Seah
Kim Keat Motor Co
Tel: 64833167
Fax: 64835764
The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.
This email has been checked for viruses by AVG antivirus software. www.avg.com

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAuto)

From:

Tan, Rachel < Rachel.Tan@sg.gaig.com>

Sent:

Thursday, 11 October 2018 5:24 PM

To:

Shiau Chan (LKKAuto); assignments

Cc: Subject: SUR RE: Accident inv. FR3272X & FS2111D (GA) on 30/11/2017.

CLMOMVM000000120

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Thursday, October 11, 2018 2:58 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: [External] RE: Accident inv. FR3272X & FS2111D (GA) on 30/11/2017.

Dear Rachel,

Kindly provide us the claim number of above mentioned.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 22 January 2018 5:46 PM

To: Rachel.Tan@sg.gaig.com; assignments <assignments@lkkauto.com>

Cc: SUR < sur@lkkauto.com>

Subject: RE: Accident inv. FR3272X & FS2111D on 30/11/2017.

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Thursday, 18 January 2018 2:36 PM

To: Kim Keat Motor Co <kkmotor@singnet.com.sg>

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

9618E

Vehicle Details

Vehicle No.:

FR3272X

Vehicle to be Exported:

No

Intended De-registration Date:

19 Jan 2018

Vehicle Make:

HONDA

Vehicle Model:

NV 400 C2V

Primary Colour:

Black

Manufacturing Year:

1998

Engine No.:

NC25E1807986

Chassis No.:

NC341007984

Maximum Power Output:

Open Market Value:

\$9,442.00

Original Registration Date:

31 Jul 1999

First Registration Date:

31 Jul 1999

Transfer Count:

Actual ARF Paid:

\$1,417.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

31 May 2019

. COE Category:

D - Motorcycle

COE Period(Years):

10

PQP Paid:

\$886.00

COE Rebate Amount:

\$120.00

Total Rebate Amount:

\$120.00

The information contained herein is correct as at 18 Jan 2018

ОК

KIM KEAT MOTOR CO Blk 10 Ang Mo Kio Industrial Park 2A Avenue5 #05-34 AMK Autopoint Singapore 568047 Tel:64833167 Fax:64835764 Email:kkmotor@singnet.com.sg

Runny Atta Pains

17 Jan 2018

Great American Insurance Company Survey Dept.

Re: Que	otation for damaged to FR3272X					
Item	Description of Parts	Qty	~	3	Amount	
1.	Mirror RH	1pc	Ru	S	85.00	_
2.	Brake Lever	1pc		DU	38.00	_
3.	Front Signal Lamp Assy RH	1pc	(,	127	85.00	
		50	Total	5	208.00	
		Less 10%		-	20.80	
			Sub-total	S	187.20	
	Nett Item		,			
4.	Grip Handle	1 pair	ay	5	85.00	-
5.	Fog Lamp	1 pair	E	nes	150.00	
6.	Engine Guard	1pc		n	250.00	X
7.	Carriage Box	Tpc	e	n	280.00	_
8.	To Respray Front Fender	18398-7			80.00	601
9_	Labour				200.00	120
		Grand Total		8	1232.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illingal modification(n) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaint

Signatures

Destate



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		1000	199607198R GST Reg. No. 19-96	
			ationale Des Experts En Autom	
GRE	AT AMERICAN IN	SURANCE COMPANY	Ref : CS/GAI1800133	35/Kqd3n2
#16-	MASEK AVENUE 01 CENTENNIAL 3APORE 039190	TOWER	Date: 15-10-2018	
1.		Policy Particula	ars :- THIRD PARTY CLAI	M
10	Insured Veh.	FS 2111D	Veh. Inspected	FR 3272X
	Policy No.		Coverage (\$)	0.00
	Claim No.	CLMOMVM000000120	Excess (\$)	0.00
	Assign From	RACHEL TAN	Assign Date	22/01/2018
2.	eyebbashani.	Vehicle Pa	articulars & Condition	
	Make & Model	HONDA NV400	c.c	399
	Engine No.	HIDDEN	Year of Reg.	1999
	Chassis No.	NC25E1807986	Colour	BLACK
	Odometer	248719	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	120/90 R17	BRIDGESTONE	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	170/80 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre			mm
4.		Descri	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S BODY.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	30/11/2017	Inspection Date	18/01/2018
	Survey held at	KIM KEAT MOTOR CO.		
		BLK 10 ANG MO KIO INDUS #05-34 AMK AUTO POINT SINGAPORE 568047	STRIAL PARK 2A AVE 5	
5a.			Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
5b.		Estim	ate Days of Repair	
			- AND THE PROPERTY OF THE PROP	

1 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FR 3272X

Qty	Description of Parts	Description of Parts Condition		Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
1	MIRROR RH	DENTED	85.00	85.00	
1	BRAKE LEVER	DENTED	38.00	38.00	
1	FRONT SIGNAL LAMP ASSY RH	CRACKED	85.00	85.00	
	LESS 10% DISCOUNT		-20.80	-20.80	
	100A (0.000 A) Addition (1.000 A) A (1.000 A) A		187.20	187.20	
	SPECIAL NETT ITEMS				
1	PAIR GRIP HANDLE (SN)	CUT	85.00	85.00	
1	PAIR FOG LAMP (SN)	CRACKED	150.00	150.00	
1	ENGINE GUARD (SN)	TO REPAIR SEE LABOUR	250.00	-	
1	CARRIAGE BOX (SN)	CUT	280.00	280.00	
	A CONTRACT OF A		765.00	515.00	
	LABOUR				
	TO RESPRAY FRONT FENDER.		80.00	60.00	
	LABOUR.INCLUSIVE OF THE REPAIR OF ENGINE GUARD.		200.00	120.00	
			280.00	180.00	
	GRAND TOTAL		1,232.20	882.20	

RECOMMENDED COST OF LUMP SUM REPAIRS	700.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/GAI18001335/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.