



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S KHIM SEAH ENTERPRISE PTE LTD
206 Woodlands Industrial Park E5
Woodlands Bizhub
SINGAPORE 757284
Insured KHIM SEAH ENTERPRISE PTE LTD
Policy VFX/PP0926241/00221

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 23/1/2018
Our Case Ref: SC17/12/306/4KS-TP
Accident Date: 15/11/2017

Damaged Vehicle No: PA8647L

S/no	Description	QTY	Price	Disc	Amount
------	-------------	-----	-------	------	--------

Replaced Parts

1	RHS REAR VIEW MIRROR	1 PC	\$1,980.00	- 300	\$1,980.00
---	----------------------	------	------------	-------	------------

Labour Charges

1	LABOUR FOR WIRING	1	\$150.00	- 30	\$150.00
2	LABOUR FOR RHS REAR VIEW MIRROR	1	\$640.00	- 320	\$640.00
3	SPRAY PAINTING	1	\$350.00	- 250	\$350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
Hp 90010068
2 days
P/P
11/04/18 @ 1000
Rey 54 paint

Sub Total S 3,120.00

Authorised Signature