



CHARN'S CUSTOMCRAFT

*Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars*

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/AIG(SKR388G)

DOA: 19/01/2018@1055

AIG ASIA PACIFIC INSURANCE PTE LTD

22/01/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKW 1965 H - SUBARU FORESTER 2.0I-L CVT AWD SR

CHASSIS NO: JF1SJ5KC5FG058417 (2015)

1 pc	Rear bumper	\$ 630.50
1 pc	Rear bumper retainer LH	\$ 22.40
		<u>\$ 652.90</u>
	LESS 25%	<u>\$ 163.23</u>
		<u>\$ 489.67</u>
	Alignment	\$ 60.00
	To repair and respray rear rim LH	\$ 100.00
	Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear fender LH and rear bumper.	\$ 300.00
	Putty and respray rear inner panel, rear fender LH and rear bumper.	<u>\$ 550.00</u>
		<u>\$ 1,499.67</u>
	ADD 7% GST	<u>\$ 104.98</u>
		<u><u>\$ 1,604.65</u></u>

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....