

**NO 1 KAKI, BUKIT AVE 6 #02-47
AUTOBAY SINGAPORE 417883
Tel : 6509 5521 / 65095524 Fax : 6509 5523**

YK9002G

DATE : 22.01.2018
VEHICLE NO : SKL7166R
MAKE/MODEL : PEUGEOT 3008
ACC DATE : 21.01.2018

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
LIST PRICE			
1	1 FRT BUMPER	1,244.90	1,244.90 ✓
2	1 FRT BUMPER TOP GARNISH	535.20	535.20 ✓
3	1 FRT BUMPER LIP	957.50	957.50 X
4	2 FRT BUMPER BRACKET RH/LH	146.50	293.00 X
5	2 FRT BUMPER RETAINER RH/LH	146.50	293.00 X
6	1 FRT BUMPER REINFORCEMENT	758.40	758.40 X
7	1 FRT FENDER	802.20	802.20 ✓
8	1 FRT FENDER COWLING	245.20	245.20 ✓
9	1 FRT HEADLAMP	1,050.70	1,050.70 ✓
10	1 FRT FOG LAMP	275.50	275.50 ✓
11	1 FRT FOG LAMP COVER	521.60	521.60 ✓
12	1 FRT SHOCK ABSORBER	535.20	535.20 ?
13	1 FRT SHOCK ABSORBER TOP MOUNTING	110.00	110.00 X
14	1 FRT LOWER ARM	407.60	407.60 ?
15	1 FRT LOWER ARM BOIL JOINT	134.70	134.70 ?
16	1 FRT STABILIZER BAR LINK	107.00	107.00 ?
17	1 FRT DRIVE SHAFT	802.50	802.50 X
18	1 FRT KNUCKLE ARM	750.00	750.00 ?
19	1 FRT KNUCKLE BEARING	485.40	485.40 ?
			10,309.60
		LESS 10%	1,030.96
			9,278.64
SPECIAL NETT ITEMS			
1	1 (SET) FRT BUMPER CLIP	45.00	45.00 ✓
2	1 (SET) FRT FENDER COWLING CLIP	35.00	35.00 ✓
3	1 FRT TYRE	320.00	320.00 X
4	1 FRT SPORT RIM	680.00	680.00 450
			1,080.00
LABOUR CHARGES :			
1	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS		600.00 500
2	TO SPRAY PAINTING ON ACCIDENT PORTION		1,000.00 600
3	TO CHECK WIRING		30.00 ✓
4	TO REMOVE, REPLACE FRONT UNDERCARRIAGE		280.00 ?
5	4 WHEEL ALIGNMENT		100.00 60
6	TO TUFF KOTE		90.00 30
			2,100.00
			12,458.64