

M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ESTIMATE

DATE : 24/1 /2018
ACC DATE : 13/11/2017
REF NO. : VFIX-TP20170393
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO XE2806T VOLVO FM

DESCRIPTION	AMOUNT S\$
1 1 FRONT BUMPER LH	Rp 485.00
2 1 SIDE LAMP LH	47 X 128.00
3 1 STEP BOARD GARNISH LH	Ry 215.00
	828.00
LESS 10%	82.80
	\$ 745.20

LABOUR & MISCELLANEOUS :	AMOUNT S\$
1 To remove damaged parts with all necessary components/attachments apply hot-works where necessary straighten step board bracket replace new parts refit align into position with all necessary components attachments	200 600.00
2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	300 600.00
	\$ 1,200.00

GRAND TOTAL : \$ 1,945.20

SINGAPORE DOLLARS : ONE THOUSAND NINE HUNDRED FORTY FIVE
& TWENTY ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
'wp'

31/1/18 @ 12:15

02 days

Resurvey after repair

Sur @ lkkauto.com