

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SMB1321C

Ref. No

BUS/11/17/5023

Reg. Date

08/01/2018

Vehicle Type

BUS-12M

Make

MAN

Model

MAN

Name of Driver

Samsul Kamal Bin Ibrahim

Type of Accident

SIDE SWIPE

Date / Time of Accident

15/11/2017 09:31:00 AM

Accident Reported Date / Time :

16/11/2017 12:00:00 AM

Surveyor is Required?

Survey by

AXA

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued?

Accident Repair Job Card No :


Special Instruction to ARC, if any :

LEFT FRONT PORTION

SGK2786B (TP) - INSURED WITH AXA

Prepared Date

: 08/01/2018 09:34:11 AM



Sebastian. 26/1/18. - Lup Sin Repair - Question Mark Iten

- Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

sebastionyeang @ Itherute.com

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: Mileage

Work Shop : Repair Completed Date / Time:

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

0

0.00 **Total Labout Charges** 1,060.00 Total Spray Painting Charges 0.00 580.00

2,320.47 **Total Material Charges** 2,320.47 0.00 Other Charges 0.00 TOTAL 3,960.47 0.00 0.00 Lum Sum Total 0.00

No. of Repair Days 3.00 0.00

Prepared / Adjusted By

Arc / Surveyor Sing Off Date : 01/01/1900 12:00:00 AM 01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 08/01/2018 10:31:03 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No Invoice No Quotation Date Invoice Date :

Invoice Amount : Prepared Date:

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
 - · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
 - . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approvel from Insurance Company

Acknowledged by Repairer

Signature:

BUS/11/17/5023 2 Page:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
F01001- CW264		6010153	FRONT HEADLAMP PANEL LH	1	974.70	10.00	877.23	Replace	Replace	No R
8-25101- 6539		6010304	FRONT HEADLAMP LH	1	1,603.60	10.00	1,443.24	Replace	Replace	No CRK.
81-25320 -6111		6010306	FRONT AUX HEADLAMP FLASHER LH		904.40	10.00	813.96	Replace	Replace	No
TOTAL MATERIALS								3,134.43	3,134.43	
TOTAL MATERIALS(Discounted)							2,320.47	2,320.47		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

BUS/11/17/5023

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	1,060.00	0.00 530
Total Labour	1,060.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	580.00	0.00 184
Total Spray Painting & Panel Beating	580.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

BUS/11/17/5023 Page:

3