

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1321C

Ref. No : BUS/11/17/5023

 Reg. Date
 : 08/01/2018

 Vehicle Type
 : BUS -12M

Make : MAN
Model : MAN

Name of Driver : Samsul Kamal Bin Ibrahim

Type of Accident : SIDE SWIPE

Date / Time of Accident : 15/11/2017 09:31:00 AM

Accident Reported Date / Time: 16/11/2017 12:00:00 AM

Surveyor is Required? : Yes Survey by : AXA

Vehicle is Towed Back? : No

Towed Back Date/Time :


Replacement Vehicle issued? : No

Accident Repair Job Card No : Special Instruction to ARC, if any :

LEFT FRONT PORTION

SGK2786B (TP) - INSURED WITH AXA

Prepared Date : 08/01/2018 09:34:11 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: Mileage :

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

0

Total Labout Charges : 1,060.00 0.00

Total Spray Painting Charges : 580.00 0.00

Total Material Charges : 2,320.47 2,320.47

Other Charges : 0.00 0.00

 TOTAL
 : 3,960.47
 0.00

 Lum Sum Total
 : 0.00
 0.00

 No. of Repair Days
 : 3.00
 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 01/01/1900 12:00:00 AM 01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/01/2018 10:31:03 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

BUS/11/17/5023 Page: 2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPAIR LH FRONT PORTION	1,060.00	0.00			
Total Labour	1,060.00	0.00			

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	580.00	0.00
Total Spray Painting & Panel Beating	580.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

BUS/11/17/5023 Page: 3

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
F01001- CW264		6010153	FRONT HEADLAMP PANEL LH	1	974.70	10.00	877.23	Replace	Replace	No
8-25101- 6539		6010304	FRONT HEADLAMP LH	1	1,603.60	10.00	1,443.24	Replace	Replace	No
81-25320 -6111		6010306	FRONT AUX HEADLAMP FLASHER LH	1	904.40	10.00	813.96	Replace	Replace	No
TOTAL MATERIALS							3,134.43	3,134.43		
TOTAL MATERIALS(Discounted)					2,320.47 2,320.47					

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

BUS/11/17/5023 Page: 4