

INS. CASE OWNER:

Salina

CC 4/AIG1800

1571, Kwa39

LKK:

IDAC:

Surveyor:

KSL

DOI:

ASSIGNMENT

113/18

Date / Time:

25/1/18

Registered in Merimen:

25/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

61BD 3604T

Name of Insured:

Comoffice Pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

24/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHONG KONG JIN

Driver Tel No.:

9638 8579

(V/L: YES / NO)

Claim No.:

501420484158

Policy No.:

7100386628

Make / Model:

7. HACE

Place of Accident:

Km CHUAN ROAD

OI GIA REPORT: YES / NO :

YES

/ NO :

YES

/ NO :

YES

/ NO :

YES

/ NO :

YES

/ NO :

YES

/ NO :

YES

Insured Liability :

%

Final ? Yes / No

88m 2882R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng Hoe Motor Pte Ltd



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

25/1/18

Sim 7882R - X; 61BD 3604T - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NIL

Repair Cost:

S\$

2033.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

400.00

(\$

100

x

4

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

8.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

2441.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

2441.00

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2 (Strike if N.A.)

S\$

Name 2:

Payee 3 (Strike if N.A.)

S\$

Name 3:

RECEIVED 4 SEP 2018

6/9/18

ASS. REC. BY:

REF:

A/G /

1571/1623

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.:

Yes or No

Lum Sum:

20 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SBN 280R

Yr Regn:

06.08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M17 Lance GLA

c.c.

1586

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

338442

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMY3NC33A8U 004241

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

1P5/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

mm

mm

L/Bal.

L/Bal.

mm

mm

D.O.A.

24/1/18

D.O.I.

1/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/3

File pass to Customer

Lily @ 1900 Customer June

Twister Car  
(4 x 100)(Red: \$62.50  
5.0)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST 201001158E RCB NO.201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1890203/AMK

Date: 01 Mar 2018

Policy No: 5029051675-09

Veh Reg No: SBM2882R

Make/Model: MITSUBISHI LANCER  
1.6M

Chassis No: JMYSNCS3A86004241

Engine No: 4G18JQ6754

Reg. Date: 16/06/2008

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 24/01/2018

TP Veh Reg No: GBD3604T

*Not Authorised*

*11 Sep & 19 Oct*

*Survey After Paint*

*4 days*

## Estimate Repair Cost to Vehicle No :SBM2882R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
<b>Net Price</b>				
1 FRONT BUMPER	773.00	1 PC	<i>Ry</i> 773.00	<i>✓</i>
2 FRONT BUMPER NUMBER PLATE GARNISH	44.00	1 PC	<i>no</i> 44.00	<i>✓</i>
3 FRONT BUMPER CENTRE INNER HOUSING	75.00	1 PC	<i>cm</i> 75.00	<i>✓</i>
4 FRONT BUMPER SIDE RETAINER	50.00	2 PC	<i>mc</i> 100.00	<i>✓</i>
5 FRONT BUMPER CENTRE LOWER GARNISH	40.00	2 PC	<i>cm</i> 80.00	<i>✓</i>
6 FRONT BUMPER CLIP	5.00	8 PC	<i>mc</i> 40.00	<i>✓</i>
7 FRONT GRILLE HOUSING	146.00	1 PC	<i>cm</i> 146.00	<i>✓</i>
8 FRONT GRILLE CLIP	1.50	4 PC	<i>mc</i> 6.00	<i>✓</i>
			1,264.00	
		Less 10%	126.40	1,137.60
<b>Special Net</b>				
9 FRONT NUMBER PLATE	35.00	1 PC	<i>Ry</i> 35.00	<i>✓</i>
			35.00	35.00
<b>Labour</b>				
10 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	<i>✓</i>
11 REMOVE & REFIX FRT BUMPER & LOWER SKIRT,FRT GRILLE, HEADLAMPS; KNOCKING & REPAIR FRT PANEL & REALIGN BONNET THE SAME	600.00	1 LA	600.00	<i>500</i>
12 PUTTY & RESPRAY FRT BUMPER & LOWER SKIRT,BONNET,FRT PANEL & ALL AFFECTED AREAS	650.00	1 LA	650.00	<i>600</i>
			1,350.00	1,350.00

LKIS Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
**TEL:** 64193000 **FAX:** 64153727  
**ATTN:** Motor Claim Department

**WS Ref:** TP/AIG/AMK  
**Claim Type:** Third Party  
**Accident Date:** 24/01/2018  
**TP Veh Reg No:** GBD3604T

**Estimate No:** ES1890203/AMK  
**Date:** 01 Mar 2018  
**Policy No:** 5029051675-09  
**Veh Reg No:** **SBM2882R**  
**Make/Model:** MITSUBISHI LANCER  
1.6M  
**Chassis No:** JMYSNCS3A86004241  
**Engine No:** 4G18JQ6754  
**Reg. Date:** 16/06/2008

### Estimate Repair Cost to Vehicle No :SBM2882R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 2,522.60
			Add GST @ 7%	176.58
			Total Amount Payable	<u>SS 2,699.18</u>

VEHICLE LYING AT:  
NO.10 ANG MO KIO INDUSTRIAL PARK 2A  
#01-04 AMK AUTOPOINT  
SINGAPORE 568047  
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

*DORLYN LI*

AUTHORISED SIGNATURE

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9223G
Vehicle Details	
Vehicle No.:	SBM2882R
Vehicle to be Exported:	Yes
Intended De-registration Date:	25 Jan 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	4G18JQ6754
Chassis No.:	JMYSNCS3A8U004241
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,444.00
Original Registration Date:	16 Jun 2008
First Registration Date:	16 Jun 2008
Transfer Count:	0
Actual ARF Paid:	\$11,444.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2018
PARF Rebate Amount:	\$5,722.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,701.00
COE Rebate Amount:	\$614.00
<b>Total Rebate Amount:</b>	<b>\$6,336.00</b>

The information contained herein is correct as at 25 Jan 2018

OK

Vehicle Details			
Vehicle No. :	SBM2882R		
Vehicle Type :	L10 - For Instruction Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	LANCER 1.6 M		
Chassis No.:	JMYSNCS3A8U004241		
Propellant :	Petrol		
Engine No. :	4G18JQ6754		
Engine Capacity :	1584 cc		
Maximum Power Output :	79.0 kW ( 105 bhp )		
Maximum Laden Weight :	1600 kg		
Unladen Weight :	1162 kg		
Year Of Manufacture :	2008		
Original Registration Date :	16 Jun 2008		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$15,701.00		
COE Expiry Date :	15 Jun 2018		
Road Tax Expiry Date :	15 Jun 2018		
PARF Eligibility Expiry Date :	15 Jun 2018		
Inspection Due Date :	15 Jun 2018		
Intended Transfer Date :	25 Jan 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use <a href="#">Enquire Road Tax Payable</a> for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

W/X

## PAYMENT ADVICE

Your Ref : AIG Vehicle no.	: GBD3604T
Claimant Vehicle No.	: SBM2882R
Date of Accident	: 24/01/2018
Traffic Accident involving vehicle/s No.	: UPPER PAYA LEBAR RD (NEAR KIM CHUAN RD JUNCTION)

### BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 2,033.00	
2	Loss of INCOME (TUTION CAR)	\$ 400.00	\$100 X 4 days
3	LTA Search	\$ 8.00	
<b>TOTAL</b>		<b>\$ 2,441.00</b>	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK  
Contact No. : 6256 3561



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18001571/wa3

07 January 2018

**Comoffice Pte Ltd**

11 Tai Seng Drive

#06-01

Singapore 535226

Dear Sir/Madam,

**ACCIDENT INVOLVING GBD 3604T AND SBM 2882R ON 24/01/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.


**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)**


I, Tay Lim Heng (the third party claimant) of Blk 642C Punggol Drive  
#13-363 S823642 (address), owner of SBM2882R (vehicle no.)  
hereby authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me  
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle  
no. SBM2882R that was damaged pursuant to the accident which occurred on 24/01/2018  
(date) along Upp Paya Lebar Rd (near Kim Chuan Rd junction) (location) involving vehicle no/s  
GBD3604T ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 24 (day) of Jan (month) 2018 (year)

  
\_\_\_\_\_  
Signed by "the third party claimant"  
(with chop if applicable)

  
\_\_\_\_\_  
Signed by "the workshop"  
(with chop)

## RELEASE VOUCHER

### (AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, CHENG HOE MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS2033.00 (Repair Cost), SS400.00 (Loss of Use), SS8.00 (Disbursement), for vehicle no SBM2882R that was damaged pursuant to the accident which occurred 24/01/2018 (date) along Upper Paya Lebar Rd (near Kim Chuan Rd Junction) (location) involving vehicle no/s GBD3604T. This is pursuant to the inspection conducted on 01/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tay Lim Heng ("the third party claimant") of vehicle no. SBM2882R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage SBM2882R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 4 (day) of Sept (month) 2018 (year)

LSC  


Signed by appointed surveyor

  
[Signature]

Signed by "the workshop" (with chop)

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

## TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department

NO: CL8180912  
Date: 21 Aug 2018  
Policy No: 5029051675-09  
Veh Reg No: SBM2882R  
Make/Model: MITSUBISHI LANCER  
1.6M  
Job No: JC1598106

WS Ref: TP/AIG/AMK  
Claim Type: Third Party  
Accident Date: 24/01/2018  
TP Veh Reg No: GBD3604T

### Description

To Supply all replaced parts, all necessary and agreed labour &  
miscellaneous charges.  
(As recommended by your appointed surveyor)

Quantity	List Price	Amount
1 PC	S\$ 1,900.00	S\$ 1,900.00

Total	S\$ 1,900.00
Add GST @ 7%	133.00
Total Amount payable	S\$ 2,033.00

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

# A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS  
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B018/ 2018
YOUR REF:		
OUR REF : ACS.CH.LTA.2018 (JAN 2018)		DATE : 5/2/18
<p>TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.</p>		
<b>LTANET SEARCHES FOR THE MONTH JAN 2018</b>		
S/NO	TP NO.	CHM DOA
		sub-total b/f
25	15/1/2018	SJN9683C SKP6152R 12/1/2018
26	16/1/2018	SKD5405G SJP3500B 10/1/2018
27	17/1/2018	GBG615R SFX6763U 15/1/2018
28	17/1/2018	SJW303L SLM4724H 17/1/2018
29	17/1/2018	GY8620T SGT8436K 16/1/2018
30	21/1/2018	GBE8451D XD9687D 21/1/2018
31	22/1/2018	SGD4560U SDU6000C 20/1/2018
32	24/1/2018	GBD3604T SBM2882R 24/1/2018
33	25/1/2018	SGX2007J SKV8477J 15/12/2017
34	29/1/2018	SJH6095B SLR6969D 14/1/2018
35	29/1/2018	SKV9347U SJU4495A 25/1/2018
36	29/1/2018	SKQ326R SJV9789P 24/1/2018
37	29/1/2018	SFR3060R SJF2298U 26/1/2018
38	29/1/2018	SJR6677U SKW6736U 23/10/2017
39	29/1/2018	SKH303D SLE614K 28/1/2018
40	30/1/2018	GBE7282G SGZ3288Y 28/1/2018
41	30/1/2018	GW2503Z SKD8932G 27/1/2018
42	30/1/2018	SGA6150Y SKU4939A 26/1/2018
42 searches @8.00 per search		Total: \$ 192.00
		\$ 144.00
		<u>\$ 336.00</u>
[SINGAPORE DOLLARS: THREE HUNDRED THIRTY-SIX ONLY.]		
<p>M/s. A C SYED &amp; PARTNERS ADVOCATES &amp; SOLICITORS SINGAPORE</p> <p>We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. &amp; O.E.</p>		

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2018 <a href="#">Edit Reg</a>		25 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,900.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	<b>Comoffice Pte Ltd</b> , Co. Reg. No.: 200005245N								
Main Claimant:	<b>TAY LIM HENG</b> , ID: S0179223G								
Vehicle Reg. No.:	<b>SBM2882R</b>	Date of Loss:	24/01/2018 14:00 - :59 [115 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 5014204841SG</b>	Policy/Cover Note No.:	2100386628 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBD3604T</b>	Policy No. (Claimant):	5029051675-09						
		Excess:							
Repairer:	<b>Cheng Hoe Motor Pte Ltd (AMK)</b> 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 05/02/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SBM2882R (50142048415G)  
[GBD3604T]  
TP  
TAY LIM HENG  
Jan 24 2018 2:00PM  
[Comoffice Pte Ltd]  
Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown														Edit		
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	26/01/18 09:56	Accident Statement From: SC – Reg. No: G8D3604T, Claimant: COMOFFICE PTE LTD														Load HTM		
2	26/01/18 09:56	Accident Statement From: SC – Reg. No: G8D3604T, Claimant: COMOFFICE PTE LTD														Load HTM		
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
2	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
3	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
4	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
5	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
6	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
7	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
8	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
9	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
10	13/08/18 15:10	General View														Load JPG <input checked="" type="checkbox"/>		
11	13/08/18 15:11	Reinspection Photo														Load JPG <input checked="" type="checkbox"/>		
12	13/08/18 15:11	Reinspection Photo														Load JPG <input checked="" type="checkbox"/>		
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	25/01/18 18:51	EMAIL FROM AIG DD 25.01.2018														Load PDF		
2	25/01/18 18:51	EMAIL PRS														Load PDF		
3	25/01/18 18:51	TP GIA REPORT														Load PDF		
4	25/01/18 18:51	LTA SEARCH														Load PDF		
5	13/03/18 10:43	TP ESTIMATE - MARKED														Load PDF		
6	07/09/18 13:56	WORKSHOP INVOICE														Load PDF		
7	07/09/18 13:56	AUTHORISATION TO ACT FORM														Load PDF		
8	07/09/18 13:56	Release Voucher														Load PDF		
9	07/09/18 13:56	LETTER TO OI														Load PDF		

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBD3604T (Insd veh)	Model:	MITSUBISHI LANCER 1.6 (M)
	SBM2882R (TP veh)		
Date of Accident:	24/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	2,699.18	
Final Repair Cost	: \$	2,033.00	
Loss of Use	: \$	400.00	4.00 days at \$100.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	8.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	2,441.00	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: \_\_\_\_\_  
 \_\_\_\_\_  
 BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)  
*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_  
 \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	: \$	2,441.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

07 Sep  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18001571/KWA3Q2

Date: 07/09/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100386628  
**Claimant Vehicle No :** SBM2882R **Insured Vehicle No :** GBD3604T  
 Date of Loss: 24/01/2018 Nature of Claim: TP Claim No: 5014204841SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBM2882R**  
 Make & Model: MITSUBISHI LANCER, 1.6 (M) Engine No: 4G18JQ6754  
 Reg. Date: 16/06/2008 (Man. Year: 2008) Chassis No: JMYSNCS3A8U004241  
 Colour: Metallic Black Odometer: 338442 km  
 Engine Capacity: 1584 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15  
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm  
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,172.60	1,172.60	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	1,200.00	150.00	11.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,522.60</b>	<b>2,372.60</b>	<b>150.00</b>	<b>5.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
(S\$)	2,522.60	1,900.00	622.60	24.68
<b>+ GST 7.00/7.00% (S\$)</b>	176.58	133.00	43.58	24.68
<b>Nett Amount (S\$)</b>	<b>2,699.18</b>	<b>2,033.00</b>	<b>666.18</b>	<b>24.68</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		8.00		
<b>Nett Liability (S\$)</b>		<b>2,441.00</b>		

### INSPECTION

Date of Assignment: 25/01/2018  
 Date Inspected: 01/03/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)  
 10 ANG MO KIO IND PARK 2A, #01-04

ANG MO KIO AUTOPOINT  
Singapore 568047

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	773.00 FN	*773.00 FN
2	1		*FRONT BUMPER NUMBER PLATE GARNISH	Dented	44.00 FN	*44.00 FN
3	1		*FRONT BUMPER CENTRE INNER HOUSING	Cracked	75.00 FN	*75.00 FN
4	2		*FRONT BUMPER SIDE RETAINER	Necessary	100.00 FN	*100.00 FN
5	2		*FRONT BUMPER CENTRE LOWER GARNISH	Cracked	80.00 FN	*80.00 FN
6	8		*FRONT BUMPER CLIP	Necessary	40.00 FN	*40.00 FN
7	4		*FRONT GRILLE CLIP	Necessary	6.00 FN	*6.00 FN
8	1		*FRONT GRILLE HOUSING	Cracked	146.00 FN	*146.00 FN
9	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>1,299.00</b>	<b>1,299.00</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	<b>126.40</b>	<b>126.40</b>
<b>Total Parts (S\$)</b>	<b>1,172.60</b>	<b>1,172.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND REFIX AIRCON CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
2	REMOVE & REFIX FRT BUMPER & LOWER SKIRT FRT GRILLE ,HEADLAMPS ,KNOCKING & REPAIR FRT PANEL & REALIGN BONNET THE SAME	New	600.00	500.00
3	PUTTY & RESPRAY FRT BUMPER & LOWER SKIRT ,BONNET ,FRT PANEL & ALL AFFECTED AREAS	New	650.00	600.00
Gross Labour Cost (S\$)			<b>1,350.00</b>	<b>1,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >